

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office)

10 FEB 1926

Date of writing Report 9. 2. 1926 When handed in at Local Office 9. 2. 1926 Port of PLYMOUTH.

No. in Survey held at DARTMOUTH Date, First Survey 18. 1. 26 Last Survey 9. 2. 1926  
 Reg. Book. 34986 on the Machinery of the ~~Wood, Iron or Steel~~ T.W. & "THE MEW" (No. of Visits 8)

Tonnage Gross 114 Vessel built at Falmouth By whom Cox & Co. When 1908-5  
 Net 53 Engines made at do. By whom do. When 1908

Nominal Horse Power 60 Boilers, when made (Main) 1908. (Donkey) ✓  
 No. of Main Boilers 1 Owners Great Western Railway Co. Owners' Address Port London Voyage Ferry Service  
 No. of Donkey Boilers 1 Managers ✓  
 Steam Pressure in Main Boilers 130 lb. Surveyed Afloat & in Dry Dock River Dart and Philips' Pool  
 in Donkey Boilers ✓ (State name of Dock.)

Last Report No. 6411 Port Ply.Particulars of Examination and Repairs (if any) B.S. & T.S.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey " " " " ✓

If this was not done, state for what reasons? ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? YesDid the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 135 lbs.Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes , and of the Donkey Boiler? ✓Did the Surveyor examine the drain plugs of the Main Boilers? None , and of the Donkey Boiler? ✓Did the Surveyor examine all the mountings of the Main Boilers? Yes , and of the Donkey Boiler? ✓Has screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? Ordinary bush.Has shaft now been changed? No If so, state reasons ✓Is the shaft now fitted new? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft? Close (new wood).If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done? Complete.

NOW DONE. The main boiler and its mountings examined and put in good order and its safety valves adjusted under steam.

All plain tubes have now been renewed and on completion of repair the boiler tested by hydraulic pressure to 185 lbs. per square inch with satisfactory results.

The tail shafts examined and found sound. The propellers, stern bushes and the sea connections and their fastenings examined and put in good order. The lower halves of stern bushes re-wooded.

The machinery being opened out for B.O.T. Survey opportunity was taken to examine the cylinders, pistons, slide valves and shafting and all was found in good order.

General Observations, Opinion, and Recommendation:—The machinery of this vessel (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9.11, B.E.M.S. 9.11, or L.M.C. 9.11, 140 lb., F.D., &c.) is in good working condition and eligible, in my opinion, to remain as classed and to have fresh recd B.S. 2.26 and notation of tail shaft seen 2.26.

Survey Fee (per Section 28) £ 2-0-0 Fees applied for 9. 2. 1926  
 Special Damage or Repair Fee (if any) £ 2-2-0  
 Travelling Expenses (if chargeable) £ 2-10-0 Received by me, 4/3/26

Committee's Minute

Assigned

TUES. 16 FEB 1926

B.S. 2. 26

CERTIFICATE WRITTEN

11. Mar. © 2020  
 Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register  
 Foundation

009805-009814-0261

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to Marine Superintendent Fishguard



B.L. due 2.26. Lick Boiler  
situated stated.  
machinery partly examined.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that  
this vessel is eligible for  
THE RECORD. B.S. 226

S 2.26

*[Signature]*  
10/2/26.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020

Lloyd's Register  
Foundation