

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report June 25 1947 When handed in at Local Office July 7 1947 Port of NEW YORK

No. in Reg. Book Survey held at Hoboken, N. J. Date, First Survey May 24th Last Survey June 10th 1947 (No. of Visits 5)

71368 on the Wood/Steel S. S. "COTTONWOOD CREEK"

22/07 TONNAGE:-

GROSS 10172

UNDER DK. -

NET 6134

Built at Mobile, Ala. By whom Alabama D.D. & S.B. Co. When 1944 11
Owners British Tankers Co., Ltd. Owners' Address Britannic House, Finsbury Circus, London, E.C.2
(if not already recorded in Appendix to Register Book).
Managers Port belonging to London

Surveyed Afloat or in Dry Dock? Both Name of Dock Todd Shipyards Corp. Hoboken, N. J. Destined Voyage

Cell DBor DBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted
total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements)

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. FIRST Port REPORT

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR General Examination.

Now Done:- Vessel placed on drydock, bottom and rudder cleaned, examined and coated.
General examination made of oil cargo tanks, cofferdams, fore and after pump rooms, forward deep tanks, dry cargo space, fore and after peak tanks, machinery spaces, Bunker tanks, structures under boilers, decks, casings, ventilator hatchways and closing appliances, general equipment, steering gear and windlass.
W & T Repairs Rudder - Four feet faulty welding forward end veed out and rewelded.
Stern Frame:- Stern frame skeg starboard side, found surface crack, hole drilled to bottom of fault, veed out and welded. Stem nosing piece found bent over to port, approximately 6 in. cropped from 9 feet to 20 feet mark. Paravane shoe lower section missing. Port bilge keel forward end and midship set down approximately 6 in. (P.T.O.)

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	
Decks	Good
Caulking of Decks	Welded
Coamings	—
Beams & Fastenings	—
Outside Plating	Good
" " in way of sidelights	—
Frames	—
Reverse Frames	—
Longitudinals	—
Transverses	—
Floors	—
Keelsons	—
Stringers	—
Inner Bottom Plating	—
Have the Tanks been examined internally?	Yes
Have the Tanks been tested?	No
Bulkheads	Good
Ceiling	—
Cement or Asphalt	—
Rudder	Good
Steering gear and its connections	—
Windlass	—
Have pumps been examined and found efficient?	—
Have Sluice Valves been examined and found efficient?	—
Have Watertight Doors been examined and found efficient?	Yes
Have Ventilators and their Coamings been examined and found efficient?	Yes
Air and Sounding Pipes	Good
Doubling Plates under Sounding Pipes	—
Engine Room Skylights	Good
Coal Bunkers, Openings, Covers, &c.	—
Oil Bunkers	Good
Scuppers	—
Cargo Hatchways	—
Hatches & hatch lids	Good
Planking	—
Caulking	—
Treenails	—
Breasthooks & Stemson	—
Transoms, Pointers & Crutches	—
Timbers of Frame at openings	—
" " at other places	—
Stringers, Clamps & Shelves	—
Salting	—
(State if examined.)	
Copper, or Y.M.	—
(State if on Felt.)	
When fitted, Month	— Year
Boats	Good
Masts, Yards, &c.	Good
Condition, how ascertained	from deck
(State if wedges removed.)	
Equipment letter	—
Anchors, No. of	—
Cables (State if now ranged)	—
" length	— mean diamr.
(on board)	
" Rule length	— size
Chain Locker	—
Hawsers & Warps	Stated sufficient
Standing and Running Rigging	Efficient
Sails	—

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel is in safe condition and is in my opinion eligible to be assigned a record of class contemplated with record of drydocking 6-47 and examined 6-47.

Subject to indented plating starboard side in way of ER D.B. tanks being dealt with at owners convenience.

Survey Fee (per Section 29) G.E. & Rprs. \$200.

Special Damage or Repair Fee (if any) \$

Travelling Expenses (if chargeable) \$ 35.00

Second Surveyor's Fee (if any) \$

Fees applied for,

July 30 1947

Received by me,

Aug 6 1947

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

NEW YORK AUG 6 - 1947

Classification contemplated

Examination 6-47 N.Y.

Examined 6-47 N.Y.

Barrington Petroleum in Bulk

004904-004911-0055 1/2

Is Certificate required? If so, to be sent to

Rpt. 9a.

Port of NEW YORK

Continuation of Report No.

47882

dated June 25, 1947

on the SS "COTTON"
WOOD CREEK

"A" Strake Plates No. 5 and 6 from aft in way of ER D.B. tanks indented examined
and found efficient meantime.


Anchor windlass port side crank pin brasses renewed.

Steering gear (Hydwo electric) tried out together with telemotor and found satisfactory.

~~XX~~

Freeboard verified with American Bureau certificate and found correct.

Provisional certificate issued.



© 2021

Lloyd's Register
Foundation

0055 2/2