

# REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office 2- FEB 1956)

Date of writing Report. 26.1. 1956 When handed in at Local Office 26.1. 1956 Port of SPLIT  
 No in Reg. Book. Survey held at Trogir Date. First Survey 25.1. Last Survey 25.1. 1956  
 33968 on the Machinery of the ~~Wood, &c.~~ Steel Screw Motorship "OHRID" (No. of Visits 1)

Tonnage { Gross 191 Vessel built at Split By whom Brodogradilište "Split" Year. Month. 1955 5  
 Net 71 Engines made at Winterthur By whom Sulzer Bros. When 1955  
 MN As Per Rule --- Boilers, when made (Main) --- (Donkey) ---  
 No. of Main Boilers --- Owners JADRANSKA LINIJSKA PLOVIDBA Owners' Address ---  
 HS " " " --- (if not already recorded in Appendix to Register Book.)  
 No. of Donkey Boilers --- Managers --- Port Dubrovnik Voyage ---  
 Steam Pressure— If Surveyed Afloat or in Dry Dock fl.dock, Trogir  
 in Main Boilers --- (State name of Dock.)  
 in Donkey Boilers ---

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

Last Report No. --- Port ---  
 Particulars of Examination and Repairs (if any) DOCKING

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ---

Was a damage report made by anyone else? If so, by whom? ---

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ---

" " Donkey " " " " ---

If not, state for what reasons --- What parts of the Boilers could not be thus thoroughly examined? ---

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ---

State latest date of internal examination of each boiler --- Present condition of funnel(s) ---

Did the Surveyor examine the Safety Valves of the Main Boilers? --- To what pressure were they afterwards adjusted under steam? ---

Did the Surveyor examine the Safety Valves of the Donkey Boilers? --- To what pressure were they afterwards adjusted under steam? ---

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? --- and of the Donkey Boilers? ---

Did the Surveyor examine the drain plugs of the Main Boilers? --- and of the Donkey Boilers? ---

Did the Surveyor examine all the mountings of the Main Boilers? --- and of the Donkey Boilers? ---

Has the screw shaft now been drawn and examined? --- Has it a continuous liner? --- Is an approved oil retaining appliance fitted at the after end? ---

Has shaft now been changed? --- If so, state reasons --- Has the shaft now fitted been previously used? --- Has it a continuous liner? ---

Is an approved oil retaining appliance fitted at the after end? --- State date of examination of screw shaft --- State the wear down in the

stern bush 2 mm Is electric light and/or power fitted? --- If so, did the Surveyor examine the generators, motors, switchgear cables and fuses? ---

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ---

Engine parts, when referred to by numbers, should be counted from foreard. Auxiliary machinery should be referred to by position in Machinery Space.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. COMPLETE

Vessel in floating dock, propeller sea connections and outside fastenings examined and found in order

## General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.)

The machinery of this vessel is, in my opinion, eligible to remain as classed without fresh record.

Survey Fee (per Section 23) £ : : Fees applied for, 19  
 Special Damage or Repair Fee (if any) £ : : Received by me, 19  
 (per Section 23.)  
 Travelling expenses (if chargeable) £ : :

Committee's Minute THURSDAY 23 FEB 1956

Assigned As man

Engineer Surveyor to Lloyd's Register of Shipping.




Lloyd's Register Foundation

009924-009933-0126



Dorking.

It is submitted that this  
vessel is eligible to remain  
as CLASSED.



120 FEB 1956



© 2021

Lloyd's Register  
Foundation