

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office)

FEB 18 1941

DISCLOSED  
BAY No.

19295 Date of writing Report 23rd Nov. 1940 When handed in at Local Office 10 Port of Manila, P. I.  
No. in Survey held at Manila Date, First Survey 22nd Nov. Last Survey 23rd Nov. 1940  
69603 on the Machinery of the ~~Block Island~~ Steel "ANAKAN" (No. of Visits)  
Tonnage { Gross 795 Vessel built at Deest By whom N.V. Schips v/d Werf When 1938 9  
Net 485 Engines made at Mannheim By whom Mtrn Werke Mannheim A.G. When 1938  
Nominal Horse Power 127 Boilers, when made (Main) (Donkey)  
No. of Main Boilers 1 Owners Manila Steamship Co. Inc. Owners' Address Manila, P. I.  
No. of Donkey Boilers 1 Managers Elizalde & Co. Inc. Port Manila Voyage Inter-island  
Team Pressure in Main Boilers ✓ If Surveyed Afloat or in Dry Dock Afloat  
in Donkey Boilers ✓ (State name of Dock.)

Last Report No. 2998 Port ManilaParticulars of Examination and Repairs (if any) CONT. SURVEY

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

as a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " "

this was not done, state for what reasons?

Did what parts of the Boilers could not be thus thoroughly examined?

So what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

What latest date of internal examination of each boiler.

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers?

Is screw shaft now been drawn and examined?

Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Is shaft now been changed? If so, state reasons

Is the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted?

So, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Auxiliary Starting Bottle opened up and inspected internally and externally.

Nos. 1 & 5 Main Engine cylinder covers, pistons, connecting rods, crankpins, Valves & valve gear and

Nos. 1, 2, 5 & 6 Main Bearings & Journals examined and found in good order.

No. 2 Generator Engine & Dynamo examined and found in good order. (4 Cyl. Diesel, situated port side aft of E.R.) Complete, dynamo all in test 1.6 megohms.

## General Observations, Opinion, and Recommendation:—

Clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also the alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, S.S., B.S., S.L.M.C., S.L., or 140 lb., F.D., &c.)

Opinion of the undersigned, the vessel is fit to remain as at present classed, and to have a SPECIAL SURVEY (LMC) be made in the Register Book in the case of this vessel when the survey has been completed.

£80.00 :

Fees applied for

19

Received by me,

19

Engine Surveyor to Lloyd's Register of Shipping.

19 APR 1942



Lloyd's Register  
Foundation

010137-010149-0038



+ June (m) club 9.40  
P. 11.40  
No arrangements stated  
for Completion

... that this  
... is eligible

June (m) 11.40  
Completion



© 2020  
Lloyd's Register  
Foundation