

ent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME s.s.s. "OCEAN WANDERER" REPORT N.Yk. No. 42710**For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey First Entry ~~When due~~This is a sister vessel to the "OCEAN LIBERTY" etc.

The scantlings are suitable for a draught of about  $18\frac{1}{2}$ " in excess of that corresponding to the freeboard which could be assigned as a C.S.S. vessel.

LOCAL "With freeboard"

2 Dks "Electrically welded"

Cell DB 368' 1310t, DTa 20' 734t, FPT 124t, APT 166t

FK, 7BH (Coll to W dk, 6 to 2nd dk), 6 divisional W.T. BHs in 'tween dks.,  
pt. Cem., Lloyd's A & CP

O.L. 441.5'

a:

E.S.D.

The class is assigned and maintained upon the understanding that the equipment will be made to accord with the requirements of the Rules when the present state of emergency has passed.

Insert in S.R.L:- (A bower anchor and 45 fms. of chain  
cable to be supplied).

*Indicate just.*

The Surveyor should be informed it is concluded the scantlings of the  
and deck beams are as indicated on the midship section as built.

S.G.N.Yk. 23-9-42.

010615-010623-0052

© 2021  
Lloyd's Register  
Foundation