

8 DEC 1954

Rpt. 9.

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

No. 10477.

Date of writing Report 24. 11. 1954 When handed in at Local Office 25. 11. 1954 Port of Singapore
No in Reg. Book Survey held at Singapore. Date First Survey and Last Survey 15. 11. 1954
(No. of Visits one)

54590 on the Machinery of the ~~Wood~~ Iron + Steel

M.V. BUNGA.

Tonnage	Gross 213	Vessel built at Singapore	By whom Singapore Harbour Board.	Year 1952 - 9.
Net	74	Engines made at Manchester	By whom Gossley Bros. Ltd.	When 1952 - 7.
MN As Per Rule	60	Boilers, when made (Main)	(Donkey)	
No. of Main Boilers	-	Owners W. Hammer + Co. Ltd.	Owners' Address	
HS	" "	Managers -	(not already recorded in Appendix to Register Book)	
No. of Donkey Boilers	-	If Surveyed Afloat or in Dry Dock afloat - Inner Roads.	Port Singapore Voyage	
Steam Pressure - in Main Boilers	-	(State name of dock.)	Particulars of Classification (which must be indicated precisely as in Register Book & Supplements)	
in Donkey Boilers	-		HULL	MACHINERY

Last Report No. 10263 Port Sing

Particulars of Examination and Repairs (if any) LMC (u).

(Periodical surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State briefly the cause of failure of any part, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any repairs made this year.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey

If not, state for what reasons.

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler.

+10041 Sing 6.54. +LMC 7.52.

S.C.

for service between Singapore +
Pulau Semboe + Pulau Bulson.
(Water tanker)

Aft. Oil Engine.

Did the Surveyor examine the Safety Valves of the Main Boilers?

Present condition of funnel(s).

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

and of the Donkey Boilers?

Has the screw shaft now been drawn and examined? M

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

Has shaft now been changed?

If so, state reasons.

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

State date of examination of Screw Shaft.

State the wear down in the stern bush.

Is electric light and/or power fitted? Yes

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

No

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Not tested.

Engine parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

Complete.

Note B1 issued, copy attached.

Note Done:-

The following machinery parts examined and found or placed in satisfactory condition:-
Main engine nos. 2 + 4 cylinders, covers, valves + gear, pistons, connecting rods, gudgeons, top + bottom end bearing + crankpins. Nos. 3 + 5 main bearings. Auxiliary engine nos 2 + 3 pistons, cylinders, valves + gear, connecting rods, top + bottom end bearing and crankpins. Nos. 2 + 4 main bearing journals. (parts numbered from starboard)
air receivers, electrical installation and oil fuel tanks generally examined, and found satisfactory.

The M.T. cylinder cover renewed (fractured).

General Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.)

seen, is eligible in my opinion to remain as classed with fresh record of LMC (u) 11. 54.

Survey Fee (per Section 22) Mod. Survey \$ 170

Fees applied for,

24-11-1954

18

Received by me,

19

Ralph M. Richards

© 2021
Engineer Surveyor to Lloyd's Register of Shipping

Committee's Minutes

THURSDAY 16 DEC 1954

Assigned

+LMC (u) 11. 54

010624 - 010630 - 0015
Lloyd's Register Foundation
Clear.

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to

LMC(m) due 7.57 now held.
A M.F cyl. cover runned
It is submitted that this
vessel is eligible for THE
RECORD + LMC(m) 11.57

MM *L.P.*
14 DEC 1954

