

is subject to the Electric cables passing through boiler-room and boiler room
vents being examined and dealt with by 5.56 (1 month limit)

30 JUL 1956

5 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME "ERLING RØGENÆS"

REPORT Nwc

No. 113446.

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/52.)

Docking, screwshaft examined.

FIRE DAMAGE & WEAR AND TEAR.

eller, outside fastenings & screwshaft examined, found or placed in good order.

mined Port side of stowhold damaged by fire, found several cables damaged & hanging
trays. New temporary cables suspended in position supplying Galley & W/T.
strapping over front of Port boiler fractured in one place, and forced draught fan found
sted. New Impeller fitted to forced draught fan. New air trunk panel welded in place.
ay & W/T cables clipped in place & remainder of Damaged cables now renewed
relation test carried out according to Rules & found satisfactory.

It is submitted the vessel is eligible to remain as classed, with

record of Survey S. 5.56 now

as recommended, without special condition.



© 2021
Lloyd's Register
Foundation

15.7.56
W. H. J. [Signature]

010640-010651-0012