

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office _____)

Date of writing Report _____ 19____ When handed in at Local Office _____ 19____ Port of New York
 in Survey held at New York Date, First Survey June 9 Last Survey July 16 1947
 Book 21108. on the Machinery of the Wood, Iron or Steel S.S. "CAPTAIN POLEMIS" (No. of Visits 12)

Gross 2829 Vessel built at St. John, N.B. By whom St. John D.D. & S.B. Co. Year 1943 Month 4
 Net 1655 Engines made at Montreal By whom Dom. Bridge Co., Ltd. When -
 Power 269 Boilers, when made (Main) 1943 (Donkey)
 Main Boilers 2 Owners Papachristian Co., Ltd. Owners' Address _____
 Donkey Boilers - Managers _____ (if not already recorded in Appendix to Register Book.)
 Pressure 200 If Surveyed Afloat or in Dry Dock Both Port Montreal Voyage
 y Boilers - (State name of Dock.) Todd Shipyards Corp. Brooklyn, N. Y.

Report No. _____ Port _____
 Particulars of Examination and Repairs (if any) MS - BS &

Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and being detailed in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case. conversion to oil burning

cases where the Surveyor has not made a special damage report he is required to state whether he has his services for this purpose, and why they were declined -

damage report made by anyone else? If so, by whom? -

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

" Donkey " " " " "

is not done, state for what reasons? -

parts of the Boilers could not be thus thoroughly examined? -

special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? -

date of internal examination of each boiler July 1, 1947 Present condition of funnel(s) Good

Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 200

Surveyor examine the Safety Valves of Donkey Boiler? - To what pressure were they afterwards adjusted under steam? -

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes, and of the Donkey Boilers? -

Surveyor examine the drain plugs of the Main Boilers? - and of the Donkey Boilers? -

Surveyor examine all the mountings of the Main Boilers? Yes, and of the Donkey Boilers? -

shaft now been drawn and examined? No Is it fitted with continuous liner? - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -

now been changed? - If so, state reasons -

shaft now fitted been previously used? - Has it a continuous liner? - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -

of examination of Screw Shaft - State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 1/8"

engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted? Yes

the Surveyor examine the generators, motors, switchgear, cables and fuses? Yes

insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes

Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

Done:- Vessel placed in drydock, propeller, after end of stern bush, sea cocks, and valves with

shell connections examined and found or now placed in good condition.

Survey:- Main engine cylinders, pistons, valves and rods, thrust intermediate shafting

bearings, attached air, feed and bilge pumps examined.

Liaries:- Examined auxiliary feed, general service, main circulating and ballast pumps; Nos.

and 2 generators and dynamos, forced draft fan engine, main and auxiliary condensers, all found

now placed in good order. Pumping arrangements examined and tested.

Electrical:- Generators and lighting circuits megger tested, existing grounds removed.

Boiler Survey:- The two (2) main boilers were examined over all parts with doors, mountings and

safety valves and found or now placed in good condition. (P T O)

General Observations, Opinion, and Recommendation:-

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.E.M.S. 9,11, *L.M.C. 9,11, or CS 3,34,

machinery and boilers of this vessel are in good condition and eligible in my opinion to

be classed with fresh record of LMC 7-47 and notation of "Fitted for oil fuel 7-47. F.P.

at 150° F.", subject to after end of TS being examined at next drydocking.

Fee (per Section 29) \$: : Fees applied for

Damage or Repair Fee (if any) \$: : Received by me,

(per Section 29.) Boiler Survey \$45. LMC \$115. Aug 4 1947

Expenses (if chargeable) \$: : NEW YORK AUG 6 - 1947

Committee's Minute signed + LMC 7-47 subject.

CERTIFICATE WRITTEN

CHARACTER * for Special Survey Date of last Survey and of Periodical Surveys.	Years assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any)
* 100 A1		* LMC
6.46		4.43
		TS CLN 6.46
		BS 5.46

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to

010835-010845-01624

© 2021
 Lloyd's Register
 Foundation

Port of NEW YORK

Continuation of Report No.

47888

dated July 28, 1947

on the S.S. "Capital Polemis"

Safety valves adjusted under steam to 200 lbs.

Oil fuel installation examined under working conditions and satisfactory.

Conversion to Oil Fuel:- This vessel now converted from coal to oilburning using Bunker C grade oil.

Boiler fronts equipped with 6 "Todd He Press" model double casing forced draft type oil burning registers suitable for operations with the existing Howden forced draft system.

The Todd fuel oil burning equipment consists of duplex heaters, pumps and strainers complete with fittings.

The installation is to approved plans and Rule Requirements. (Plans attached herewith)

Oil Unit:- Todd Shipyards Corp. Combustion Equipment Division, New York. Tested 6-6-47 AMC LR.

Fuel Service Pumps (2) Dean Bros. $5\frac{1}{2} \times 3\frac{3}{4} \times 5$ "

Transfer Pump - Worthington - $5\frac{1}{2} \times 4\frac{3}{4} \times 5$ " #12-96184.

Heating coils are fitted in all fuel tanks consisting of $1\frac{1}{2}$ " extra heavy steel pipes, exhausts return to a common manifold and drain to inspection tank, all coils tested.

Fuel oil fitting and transfer piping, consisting of 4" risers with 4" branches to port starboard sides on bridge deck connected to discharge manifold in the fireroom.

Oil fuel unit equipped with emergency shut off controlled from deck.

Machinery Repairs:- Metallic packing renewed on piston rods of main engine.

Main engine crank pins and crosshead bearings refitted, crosshead pins dressed.

After intermediate bearing refitted and secured to pedestal.

Four defective tubes renewed in auxiliary condenser.

Attached main feed pump rams machined and bushings renewed.

Valve stem renewed in main circulating pump engine - bushing renewed on impeller shaft.

Steam and liquid end piston rings renewed in auxiliary feed pump. Fan engine overhauled, valve stem renewed.

No. 1 generator engine cylinder rebored, piston built up and rod renewed.

Governor overhauled on No. 2 generator engine.

Kinghorn valves renewed in ballast pump.

Boiler Repairs:- Defective superheater joints renewed on headers.

Soot blower elements overhauled.

Seat and disc renewed on auxiliary feed line, also in auxiliary stop valve.

S.R.L:- "Aft end of tailshaft to be examined at vent docking".

A wire cable found around shaft between propeller and stern bush when drydocked.

Outer end of liner worn approximately $1\frac{1}{4}$ " in way but considered efficient.



© 2021

Lloyd's Register Foundation