

(Received at London Office. MAR 26 1871)

Date of writing Report 15th March 1941. When handed in at Local Office 15th March 1941. Port of Greenwich

No. in Reg. Book. *87501* Survey held at *Queensick* Date. First Survey *"* Last Survey *" 21 March 1941*
on the Machinery of the ~~Wood, Iron or Steel~~ *"CAPE HAWKE"* (No. of Visits *ONE*)

Tonnage { Gross 5100		Vessel built at	Pent. Glasgow	By whom	Lithgows Ltd.	Year.	Month.
{ Net		Engines made at	Glasgow	By whom	D. Ruan & Co. Ltd.	When	1940
Nominal Horse Power {		Boilers, when made (Main)		(Donkey)		When	
No. of Main Boilers		Owners		Owners' Address			
No. of Donkey Boilers		Managers	Lyle Shipping Co. Ltd.	(if not already recorded in Appendix to Register Book.)			
Steam Pressure— in Main Boilers		If Surveyed	Afloat or in Dry Dock	Port	Glasgow	Voyage	
in Donkey Boilers		(State name of Dock.)	Ganwell Quay Dock	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).			

Last Report No......*'Port*

Particulars of Examination and Repairs (if any) Rocking

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

“ Donkey ”

If this was not done, state for what reasons

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler.

Present condition of funnel(s)
 afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? _____, and of the Donkey Boilers? _____

Did the Surveyor examine the drain plugs of the Main Boilers? _____, and of the Donkey Boilers? _____

Did the Surveyor examine all the mountings of the Main Boilers? _____, and of the Donkey Boilers? _____

Has the screw shaft now been drawn and examined? 100 Is it fitted with continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed?..... If so, state reasons.....

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft..... State the distance between lignum vitæ or bearing metal of stern bush and top of after bearing of screw shaft.....

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

New Sauer. Vessel in Drydock, on account of hull damage

Examined propeller and outside fastenings of sea connections and
stern bush.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.&M.S. 9,11, & L.M.C. 9,11, or L.M.C. 140 lb., F.D., &c.)

ALMC 140 lb., F.D., &c.)
CS 3,34.
This is submitted for the information of Committee

Survey Fee (per Section 20).....	£	:	:	Fees applied for
Special Damage or Repair Fee (if any)..... (per Section 20.)	£	:	:	19.....
Travelling expenses (if chargeable).....	£	:	:	Received by me, 19.....

Committee's Minute

Assigned *See L.C. Rpt. No 21344*

M. Caldwell
Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation

010924, 010932, 0110