

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 6 Feb 1941 When handed in at Local Office 7 Feb 1941 Port of Penarth

No. in Survey held at Penarth Date, First Survey 10th Jan 41 Last Survey 30th Jan 1941

Reg. Book. 89074 on the ~~W. J. Iron~~ Steel Sc. "Mari II"

TONNAGE:- Built at Haarlem By whom N. V. Werf Bourad When 1918

GROSS 1395 Owners Ministry of Shipping Owners' Address (if not already recorded in Appendix to Register Book).

UNDER DEK 1226 Managers Shamrock Shipping Co. Ltd Port belonging to Glasgow

NET 811 Surveyed Afloat & in Dry Dock? Both Name of Dock Penarth Pontoon Destined Voyage

WB=Cell DBorDBa feet; uE&B feet; f feet Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

total capacity tons. FPT tons; APT tons; MT feet tons. last Report, No. Port

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined Yes - not required Society's Freeboard (if assigned) as painted on Ship and now verified 2 ft. 9 ins.

Was a damage report made by anyone else? If so, by whom? Yes - Salvage Ass Surgen.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage and General Examination.

Damage stated caused by (1) collision with the m.v. "Lobieski" in the Irish Sea on the 2nd August 1940. (2) Ranging alongside the ss. "Kingston Hill" in Loch Long during a gale on 5th + 6th December 1940.

For further particulars please see log books

How done - Damage (1) Examined stem, stem plating and f. castle deck plate together with p.s. sheer strake plating, upper deck plating and bulwarks plating abreast No. 1 hatch and placed same in efficient condition; temporary repairs carried out at this time.

Damage (2) Examined steering-gear-deck-house and adjacent bulwark plating and placed in good condition; permanent repairs (P.T.O.)

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed	✓	✓	✓	✓	✓	✓	✓	3 bulwark stanchions, 3 deckhouse plates and 1 bulwark plate renewed. 1 stiffener part renewed. Stem bar fracture elec. welded. A number of shell rivets caulked.
Removed and Fair'd or Repaired	✓	✓	✓	✓	✓	✓	✓	
Fair'd or Repaired in place	✓	✓	✓	✓	✓	✓	✓	

PRESENT CONDITION OF THE	FR. AP. 4 BLARM.	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
Shells	Satisfactory	Satisfactory	(State if on Fett.)
Caulking of Decks	"	"	When put on, Month Year.
Stanchions	"	"	Boats (part exams) Good
Rivets & Fastenings	"	"	Masts, Yards, &c.
Outside Plating	"	"	Condition, how ascertained from deck
" in way of sidelights	"	"	(State if wedges removed) ✓
Reasthooks	"	"	Sails
Ransoms	"	"	Equipment letter
Frames	"	"	Anchors, No. of
Reverse Frames	"	"	Chain Locker
Longitudinals	"	"	Cables (State if now ranged)
Transverses	"	"	" lengths 105 ft. mean diam. 1 1/2 - 1 3/4 (on board)
Floors	"	"	" Rule length 240 size
Keelsons	"	"	Hawser & Warps Sufficient
Stringers	"	"	Standing and Running Rigging Good
Inner Bottom Plating	"	"	
State if Tanks have been examined inside	Yes	State if examined	
State if Tanks now tested (N.2 p.s.)	Yes		
Bulkheads	Satisfactory		
Ceiling	"		
Cement or Asphalt (State which.)	Good		
Rudder	"		
Steering gear and its connections	"		
Windlass (part examined)	"		
Have pumps now been examined and found efficient?	✓		
Have Sluice Valves now been examined and found efficient?	✓		
Have Watertight Doors now been examined and found efficient?	✓		
Have Ventilators and their Coamings been examined and found efficient?	Yes		

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24.

This vessel as now seen is in an efficient condition and eligible in my opinion, to have the record of "Class B contemplated" Examined (in red) 1,41 subject to the Boiler Room tank-end plate (p.s.) and floors (p.s.) together with f. castle shell plating and p.s. forward deck stringer plate & sheer strake plate (abreast No. 1 hatch)

Survey Fee (per Section 20) £ 6 : 0 : 0 Fees applied for, being dealt with at the first convenient opportunity.

Special Damage and Repair Fee (if any) £ 4 : 4 : 0 Received by me, B. Moffatt.

Travelling Expenses (if chargeable) £ : : : Surveyor to Lloyd's Register of Shipping.

Second Surveyor's Fee (if any) £ : : : 7 MAR 1941

Committee's Minute Character Assigned 100 ft. Claven, Contemplated

W. J. Iron Co. Ltd. (1,41 eff) 100 ft. Claven, Contemplated

Phosphor 156 ft. Examined 1,41

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

" " " forward bulkhead plate (1) renewed

© 2021
Lloyd's Register
Foundation