

Rpt. 8

REC'D NEW YORK NOV 23 1960

Port Cleveland, Ohio

NP 3352  
- 2 JAN 1961

Date of writing Report Nov. 22, 1960

When handed in at Local Office

Received London

Survey held at Cleveland, Ohio

No. of Visits 2

First Date Nov 13, 1960

Last Date Nov. 14, 1960

DISCLOSED SECTION

# REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

20749

on the Iron or Steel

"ORIENT TRADER"

793

Built at Baltimore

By whom Bethlehem Fairfield

When Year 1945 Month

Owners Orient Mid East Line

Owner's address (If not already in R.B.)

Managers

Port of Registry

Pireaus

Surveyed Afloat or in Drydock Afloat

Name of Dock

Date of last examn. in Drydock 4.60

B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 142590 Port LON  
To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS		Machinery	
Date of Special and of Drydocking Surveys, etc.			
BS		MBS	
SS	1.56	ES	8.55
Docking	4.60	MBS	2.60
		CL	1.60
		sps	8.55

Give dates and references to any letters relating to this Report.

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined Not required

Freeboard as marked on ship and now verified ft.

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR DAMAGE: Stated sustained due to vessel's cargo being afire at Erie, Pa., on November 12th, 1960 in way of No. 3 lower hold.

NOW DONE: No. 3 lower hold, including tank top, examined for possible damage due to fire and water extinguishing.

No apparent damage observed.

No repairs required due to fire or water.

DISCLOSED SECTION  
No. 793

CONTINUATION OVER/OR SHEET

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Is a Survey also been held on machinery of the Ship? No  
If so, is the Report sent now, or when will it be sent? -

Is Classification Certificate required? If so, to be sent to No  
Has Interim Certificate been issued? Yes

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey, for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1.55"; or to remain as Classed and to have record of drydocking 1.55, and the notation of S.S. . . . 1.55".

In my opinion, this vessel is eligible, in my opinion, to remain as now classed in the Register Book, without fresh record of survey.

J. S. Wallace  
Surveyor to Lloyd's Register of Shipping

Date of Committee

Minute

Deferred for SS. (by 1.61) M.



6110-019110-59110  
011665-011670-0149

TABLE 1

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR SURVEY

Items	Now Examined		Tanks	Now Examined Internally	Now Tested
	YES	NO or NONE			
Shell plating, sternframe and rudder cleaned, examined and recoated in drydock			F.P. Tank		
Rudder lifted			A.P. "		
Weather Decks, Superstructures and Casings			D.B. Tanks (indicate Oil Fuel) and Cofferdams		
Hatchways, Covers, closing and securing appliances					
Ventilator coamings, skylights, companionways and closing appliances			Fresh Water Tanks		
Hold			Deep Tanks		
"Tween Decks			Oil Fuel Bunkers and Settling Tanks		
Fore Peak Spaces			Side Tanks		
After " "			Wing Tanks		
Engine Space			Other Tanks		
Boiler " "			Cargo Tanks (Tankers)		
Under Engines and Boilers					
Tunnel and Well			Cofferdams		
Coal Bunkers			Pump Rooms		
Chain Locker					
Other Spaces					
			Have Tanks now Examined been Cleaned as Necessary?		
			Have Strums in Cargo Tanks (of Tankers) been removed?		
			Have Tanks been Retested as necessary after completion of any Repairs?		

Have the spaces now surveyed been cleared and cleaned as necessary? \_\_\_\_\_

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules? \_\_\_\_\_

Have the bilges been cleaned out and examined? \_\_\_\_\_ Has cement in bottom been examined? \_\_\_\_\_

Has steelwork had rust removed and afterwards been recoated as necessary? \_\_\_\_\_

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork? \_\_\_\_\_

Has a Load Line Survey been held? \_\_\_\_\_ If so, state which \_\_\_\_\_

Have the shell and deck plating been drilled as per Rule? \_\_\_\_\_ If so, Report 8(Dr) to be attached \_\_\_\_\_

Have any alterations to the approved scantlings and arrangements now been effected? \_\_\_\_\_ If so, report details in body of Report.

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

TABLE 2

The present condition of the following parts in so far as examined is to be reported:—

Shell plating	Ceiling and Cargo Battens	Sluice Valves examined and found	
" " in way of side scuttles	Cement or Asphalt	Air and Sounding Pipes	
Rudder and Sternframe	Cargo and other Hatchways	Doubling Plates under Sounding Pipes	
Decks	Hatches and closing appliances	Masts and Rigging examined and found	
Superstructures and their closing appliances	Ventilators, their coamings and closing appliances	Condition, how ascertained (State if wedges removed)	
Coamings and Casings	Companionways and Skylights	Chain Locker	
Beams and Fastenings	Shell Openings	EQUIPMENT	
Frames	Ash Shoots	Equipment Letter	
Reverse Frames	Overboard Discharges and Scuppers	Anchors, No. of	Condition
Longitudinals	Freeing ports	Cables (State if now ranged and examined)	
Transverses	Steering Gear (Main and Auxiliary)	" length (on board)	mean diam.
Floors	examined and found	" Rule Length	Size
Keelsons	Windlass examined and found	Hawsers and Warps	
Stringers	Pumps " " "	State if any Anchors or Chain Cable have	
Inner Bottom Plating	W.T. Doors " " "	now been supplied or retested, if so,	
Bulkheads and Tunnel		complete Report 8(Eq) and attach.	

Have conditions (A) or endorsements (B) of Class (if any) been dealt with? \_\_\_\_\_ See Below \_\_\_\_\_

REMARKS, REPAIRS, Etc. (Contd.) \_\_\_\_\_

Survey Fee \$100.00  
 Sunday 22.00  
 Special Damage or Repair Fee (if any) \_\_\_\_\_  
 Travelling Expenses (if chargeable) 6.00

Second Surveyor's Fee (if any) \_\_\_\_\_  
 Date when A/c. Rendered 11/22/60

