

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office

28 JUL 1955

Date of writing Report 20th July, 55. When handed in at Local Office 20th July, 55. Port of Hong Kong.

No. in Survey held at Hong Kong. Date. First Survey 30th June, Last Survey 5th July, 19 55.

on the Machinery of the ~~XXXXXX~~ Steel S.S. "AN PING"

Vessel built at P. Rupert, B.C. By whom Prince Rupert D.D. & Shipyards, Ltd. When 1946. 4.
Engines made at Montreal. By whom Canadian Allis-Chalmers Ltd. When 1946.
Boilers, when made (Main) 1946. (Donkey) -
Owners Bank of Taiwan. Owners' Address -
Managers Taiwan Nav. Co. Ltd. (If not already recorded in Appendix to Register Book.)
If Surveyed Afloat or in Dry Dock Both. Port Keelung. Voyage
Cosmopolitan Dock.

Particulars of Examination and Repairs (if any) Docking, B.S. & Gen. Exam.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

as a damage report made by anyone else? If so, by whom?

did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes.

not, state for what reasons? What parts of the Boilers could not be thus thoroughly examined?

That special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

ate latest date of internal examination of each boiler 2nd July, 1955.

Present condition of funnel(s) Good.

did the Surveyor examine the Safety Valves of the Main Boilers? Yes. To what pressure were they afterwards adjusted under steam? 200 lbs.

did the Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes. and of the Donkey Boilers?

did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

did the Surveyor examine all the mountings of the Main Boilers? Yes. and of the Donkey Boilers?

as the screw shaft now been drawn and examined? No. Has it a continuous liner? Is an approved oil retaining appliance fitted at the after end?

as shaft now been changed? If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner?

an approved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft State the wear down in the

stern bush 50/1000" Is electric light and/or power fitted? If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

as the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes.

the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

ow Done :-

For Docking :- Vessel placed in drydock, propeller, after end of stern bush, sea cocks & valves (inlet & overboard) & outside fastenings examined & found or placed in efficient condition.

Boiler Survey:- Examined both boilers in their entirety together with mountings, manholes, doors & fastenings, afterwards examined under steam & the safety valves adjusted to above pressure, & all found or placed in good condition.

O.F. burning & steam smothering arrangements examined & tested & found in order.

General Examination :- Generally examined - ballast pump, S.W. circulating pump, bilge pump & found in good condition.

Electrical Machinery megger reading sighted and found in order.

Main Engine & auxiliaries examined under running condition & found in satisfactory condition.

Interim Certificate issued - copy attached.

General Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11 or LMC 9,11 or LMC 140 lb., FD, &c.)

This vessel's machinery & boilers as seen are in good and efficient condition & eligible

in my opinion, to remain as classed with fresh record of BS 7,55.

Survey Fee (per Section 22) B.S. 320.00

Special Damage or Repair Fee (if any) 1 : :

avelling expenses (if chargeable) 7.00

ommittee's Minute

signed

Fees applied for

5/7/ 19 55

Received by me,

19

TUESDAY 16 AUG 1955

Deferred for LMC MS but BS 7,55

Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

01896-011901-0055

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to