

REPORT of SURVEY for REPAIRS, &c.

Date of Writing Report 19.11.54 When handed in at Local Office 19.11.54 Port of SYDNEY N.S.W.

No. in Reg. Book Survey held at SYDNEY N.S.W. Date, First Survey 14.10.54 Last Survey 16.11.54 19

67116 on the Wood, Iron or Steel S/S LADY ISOBEL

TONNAGE:—

GROSS 1545

UNDER DK. 1221

NET 875

Built at Kinderkijk

By whom Gebr. Jonker.

When 1921

MONTH 3

Owners Australian Steamships Pty. Ltd., Owners' Address

Managers Howard Smith Ltd.,

(if not already recorded in Appendix to Register Book)

Port belonging to MELBOURNE

Surveyed Afloat or in Dry Dock? Both Name of Dock Mort's Dry Dock Destined Voyage

CellDBorDBa feet; uE&B feet; f feet }
total capacity tons. FPT tons; APT tons; MT tons. }

Only alterations in the existing records of tanks should be inserted.

N.B.—All Alterations in the existing records should be underlined.

Last Report, No. 27465 Port Syd

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case).

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as } 2 ft. 3 ins.
painted on Ship and now verified }

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR DRY DOCKING. Shell plating, rudder and sternframe examined cleaned and recoated.

The decks, casings, superstructure bulkheads, hatchways, ventilators and other deck openings examined with their closing and securing appliances.

The windlass, main and auxiliary steering gears generally examined. Steering chains and fairlead pins specially examined for wear.

Annual Freeboard survey held.

REPAIRS TO AFT PEAK TANKTOP. Refer to Syd. Rpt. No. 27465 dated 20.8.54. & S.R. List No. 134

Portion of the cement composition now removed from the aft peak tank top and the plating doubled for 4'-0" x 2'-0" in way of the two companionway landings, the tank tested and found tight.

P.T.O.

SUMMARY OF DAMAGE REPAIRS:—

	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Beams	Inner Bottom Plates	Dk. Plates	Other Items:—
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

PRESENT CONDITION OF THE

Decks	Good	Bulkheads	Good	Engine Room Skylights	good	Copper, or Y.M.	—
Caulking of Decks	Good	Ceiling	—	Coal Bunkers, Openings, Covers, &c.	Good	(State if on Felt)	—
Coamings	Good	Cement or Asphalt	Good	Oil Bunkers	—	When fitted: Month	— Year
Beams & Fastenings	Good	Rudder	—	Souppers	Good	Boats	good
Outside Plating	Good	Steering gear and its connections	Good	Cargo Hatchways	Good	Masts, Yards, &c.	good
" " In way of sidelights	Good	Windlass	Good	Hatches	Good	Condition, how ascertained	from deck
Frames	—	Have pumps been examined and found efficient?	—	Planking	—	(State if wedges removed)	—
Reverse Frames	—	Have Sluice Valves been examined and found efficient?	—	Caulking	—	Equipment letter	P
Longitudinals	—	Have Watertight Doors been examined and found efficient?	—	Treenails	—	Anchors, No. of	3B 1S 1K
Transverses	—	Have Ventilators and their Coamings been examined and found efficient?	yes	Breasthooks & Stems	—	Cables (State if now ranged)	no
Floors	—	Air and Sounding Pipes	good	Transoms, Pointers & Crutches	—	" length (on board)	—
Keelsons	—	Doubling Plates under Sounding Pipes	—	Timbers of Frame at openings	—	" Rule length	—
Stringers	—			" " at other places	—	Chain Locker	—
Inner Bottom Plating	—			Stringers, Clamps & Shelves	—	Hawser & Warps	sufficient
Have the Tanks been examined internally?	—			Salting	—	Standing and Running Rigging	good
Have the Tanks been tested?	—			(State if examined)	—	Sails	—

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,33," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1,38."

This vessel, so far as seen, is in good condition and, in our opinion, is eligible to remain as classed and to have record of Dry Docking Syd. 11,54 made in the Register Book.

ENDORSEMENTS. "Bulwark plating etc. (s.s.), abreast No. 2 hatchway set in. Indents in shell plating (p.s.) "

Survey Fee (per Section 29)	£	9	:	0	:	0	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	12	:	0	:	0	19.11.54.
Travelling Expenses (if chargeable)	£	:	12	:	0		Received by me,
Second Surveyor's Fee (if any)	£	:	:	:	:		19

Committee's Minute

THURSDAY 16 DEC 1954

Character Assigned

11.54 Syd. without spec. can
(with endorsement)
BS 11.54

Surveyor to Lloyd's Register of Shipping

Lloyd's Register
Foundation

012019-012026-0141

REPAIRS IN BRIDGETWEEN. DECK. Forward lower bunker hatch coaming wasted and renewed. front

REPAIRS IN BRIDGETOWN. Forward lower bunker hatch and Bridge/bulkhead, and stringer plate port side aft locally wasted and sheathed as necessary.

Steering Engine. 5 lengths of steering chain part renewed as necessary and afterwards tested.

tested.

ENDORSEMENTS. "Bulwark plating etc. (s.s.) abreast No. 2 hatchway set in Indents in shell plating (p & s.)" examined and remaining efficient.

the Board is called by Convling Press. annual care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS

[illegible]

* When a bower anchor is supplied, it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES

[illegible]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN

This
"Wh
properly ex
y circum
its Surve
ault or
Society.

t. B.)