

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

30 MAR 1950

Date of writing Report 20-3. 1950. When handed in at Local Office 20-3. 1950. Port of Greenock.

No. in Survey held at Greenock. Date. First Survey 29-12-49. Last Survey 8-3-1950. (No. of Visits 27)

Reg. Book. 04450 on the Machinery of the Wood, Iron or Steel S.S. "DOVER HILL" (ex "Empire Maroshi"-46).

Tonnage Gross 7290. Vessel built at Sunderland. By whom Short Bros. Ltd. Year 1945. Month 4

Net 2035.5. Engines made at Newcastle. By whom N.E. Marine Eng Co (1938) Ltd. When 1945. Month 4

Nominal Horse Power 510 M.M. Boilers, when made (Main) 1945 (Donkey) ✓

No. of Main Boilers 3 (Sht). Owners Down Hill S. Co. Ltd. Owners' Address Sunderland. Port Sunderland. Voyage Liverpool. (in ballast)

No. of Donkey Boilers None. Managers Cunard Ship Management Co. Ltd. (if not already recorded in Appendix to Register Book.)

Steam Pressure in Main Boilers 220 lbs. If Surveyed Afloat or in Dry Dock Both.

in Donkey Boilers ✓. (State name of Docks) Victoria Harbour, Garelochhead.

Last Report No. Port Falkirk of Clyde. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Particulars of Examination and Repairs (if any) LMC - C.L. - OIL FUEL CONVERSION.(Periodical Surveys, when held, must be reported in detail and ~~separately~~ in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.....

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined. ✓.

Was a damage report made by anyone else? If so, by whom? ✓.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes ✓. LONGITUDINAL FRAMING AT DECKS

Donkey " " " " ✓.

If not, state for what reasons. ✓. What parts of the Boilers could not be thus thoroughly examined? COMPLETE

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? COMPLETE

State latest date of internal examination of each boiler P. 22-2-50. C. 21-2-50. S. 21-2-50. Present condition of funnel. GOOD.

Did the Surveyor examine the Safety Valves of the Main Boilers? Yes To what pressure were they afterwards adjusted under steam? SAT 220 lbs. Sat 230 lbs.

Did the Surveyor examine the Safety Valves of the Donkey Boilers? ✓. To what pressure were they afterwards adjusted under steam? ✓.

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓. and of the Donkey Boilers? ✓.

Did the Surveyor examine the drain plugs of the Main Boilers? ✓. and of the Donkey Boilers? ✓.

Did the Surveyor examine all the mountings of the Main Boilers? ✓. and of the Donkey Boilers? ✓.

Has the screw shaft now been drawn and examined? Yes Has it a continuous liner? Yes Is an approved oil retaining appliance fitted at the after end? No

Has shaft now been changed? No If so, state reasons ✓. Has the shaft now fitted been previously used? ✓. Has it a continuous liner? ✓.

Is an approved oil retaining appliance fitted at the after end? ✓. State date of examination of Screw Shaft 9-2-50. State the wear down in the stern bush 1/8". Is electric light and/or power fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? Yes

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes

Engine parts, when referred to by numbers, should be counted from forward.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. To complete LMC - Both dynamos to be placed in efficient running condition.

Now home for LMC & C.L.

Vessel placed in drydock. Propeller, aft and stem bush & all outside underwater fastenings examined & found in good order. Screw shaft cleaned & examined to gether with continuous liner, stem bush, gland etc & found in good order. All underwater fittings opened, examined & closed after minor repair. Main Engines.

Opened & examined all cylinders, worn piston rings, rods, valves & casings crankshaft journals, main & bottom end bearing, crosshead journals, beveling, guides & faces eccentric pulley, sheaves & valve motion, thrust collar & pack, intermediate shafting & roller bearings & attached pumps. Holding down bolts & chocks attached to an auxiliary. Main condenser cleaned, examined & tested.

New piston rings fitted to H.P engine & spans replaced. H.P & I.P valve spindles

General Observations, Opinion, and Recommendation:— The machinery of this vessel is in P.T.O. good condition & eligible in my opinion to remain as classed with ^{C. 22-2-50} LMC 3.50. C.L. 2.50 & with added insulation "Fitted for oil fuel 3.50. F.P. above 150°F" Subject to both dynamo engines & armature being placed in an efficient condition before the vessel proceeds on an outward voyage.Survey Fee (per Section 29) LMC. £ 32 : 0 : 0 Fees applied for 24 MARCH 1950.

C.L. 3 0 0. Received by me,

Special Damage Repair Fee (if any) £ 10 : 10 : 0

(per Section 29.) Oil Fuel CONVERSION

Totalling expenses (if charged) FREE SURVEY 52 : 10 : 0

Sunday & Late FEES. 5 : 0 : 0

Committee's Minute GLASGOW 29 MAR 1950

Assigned S 2/50 Deferred for comp. LMC.

A. Y. Sinclair
Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

012211-012220-0097½

Work done for L.M.C. (continued)

found worn in way of packing & now machined, lined up a new packing fitted. New 'dome' bush fitted to M.P. & L.P. valve rods. L.P. guide shoe found unsatisfactory & now remade. Engine alignment checked & all necessary adjustments made. All bearings, rings, packings etc adjusted & engine closed in good order. Minor machining & repairs as necessary to attached pumps.

Intermediate shafting & roller bearing. - Examination showed N° 4 roller bearing race had shifted on shaft thus allowing roller to fracture housing. It was also noted that N° 3 bearing was of the orthodox "plummer" type - it having, it was stated been fitted some time previously. Signs of movement were apparent on coupling faces. Shafting has now been completely re-aligned as for a new ship. The representative to the makers of these roller races (Huron Cooper Roller Bearing Co. Ltd.) attended & bearings have now been completely overhauled & fitted to his instructions - the following alteration being incorporated. (1). Centrif welded gun plat fitted to stiffen existing shaft. (2) Extra Ch. block fitted directly under centre of housing as support weight of shaft & obviates deflection of housing. A new roller bearing fitted to M° 3 & plummer bearing remaining onboard as precautionary measure only.

Burner P.C.S. Burner opened, cleaned & examined internally & externally in their entirety including superheat elements & headers, chocks, ties, manholes & fastenings & all mountings. General condition found satisfactory. 2 stay & 1 plain tie found unsatisfactory in Starboard Burner & now renewed. Superheat elements removed ashore & were tested. Minor repair to mounting only. Alteration to Burner front to facilitate oil burning carried out at this time.

Burner later examined under steam found satisfactory & safety valves adjusted to pressures stated.

Auxiliary Machinery - All auxiliary machinery opened up, examined & closed in good order with exception of dynamos (mentioned under S.R.L.).

Windlass - Both capstan drums found seized & now free & workable. General adjustments to bearings etc as necessary.

Steering Engine & Telepointer - minor repair & checking only.

Ballast Pump - Closed in good order after adjustment.

P.G. Pump - condition good. Bilge suction line blanked & length of pipe removed on account of oil fuel conversion.

Circulating Engine & Impeller - piston & valve rods lightly machined & bushed to suit. Impeller clearance checked & casing cleaned & valid.

Auxiliary Condenser - Cleaned, examined & tested.

Feed Pump (2) Generally overhauled & in good order.

Feed Heater - Cleaned & in good order.

Evaporator - Cleaned & examined. Safety valve adjusted to W.P. 231.

Fan Engine & Impeller - Closed in good condition after minor adjustments.

Fresh Water Domestic Pump - minor repair only.

Dynamos Engine(2) - Cylinder blocks removed ashore. Valve casings machined & cylinder piston removed. New piston & valve rods fitted, new valves fitted & all bearings adjusted.

Towing subsequent trials it was found inboard dynamo failed to run at required revolutions & investigation showed piston was .040 small & cylinder bore. It is recommended that either a new bronze piston be fitted or the existing piston be machined for run prior to vessel proceeding or her outward voyage. This recommendation

to be a condition of class.

Mechanical Circuits & Equipment - All circuits megger tested. Several found low & now attended to. Re-tested upon completion & found satisfactory. Both dynamos armatures removed ashore, commutators machined & induced. During trials it was noted that inboard armature was not running true & commutator sparking heavily. Brush tension has been increased & sparking reduced thus allowing vessel to proceed to Liverpool where it is in the Cunard intention to again machine commutator & overhead brush gear. It is recommended this armature be placed in an efficient condition prior to the vessel proceeding on her outward voyage. - this recommendation being a subject to continuation of class.

Bilge & Pumping Systems - examined, overhauled & closed in good order.

Now Done For CONVERSION TO OIL FUEL BURNING.

The vessel has at this been converted to Oil Burning all alterations being satisfactorily carried out as per attached plans (approved 6-1-50), & requirements of Section XX of the Societies Rules (1948-49). Being complied with as far as they are applicable.

Fuel unit was made by Messrs Toledi Oil Burner Ltd. London. Particulars. Unit N° 129. Pump N°. 234169 (PORT). 237249 (STAR).

HEATERS (PORT) 11968. (STAR) 11968. LLOYDS TEST 500/650" 26-10-49. Transfer Pump - Makers - Huron C. & J. WEIR LTD.

Size 7" x 6 1/2" x 15" N° 238050. MANUFACTURED 1949.

All oil fuel discharge & pressure piping has been fitted to specified test pressure on bare heating coils in deep, double bottom & settling tanks. All suction lines fitted to 50 lbs/in². Suction lines passing through deep tank also satisfactorily tested.

It has been verified no damper exists in the funnel.

A section of bilge suction line has been removed from the G.S. pump line & ends blanked thus insuring no fuel contamination of boiler feed water is possible from bilge range.

Required retended spinners operated from upper deck have been fitted to all tank suction, steam smoothing & unit isolating valves. These controls found efficient under test. Adequate portable fire extinguishers of the foam type & sand bags fitted in addition to 2 fire main hose connections in Boiler Room. Drift trap fitted to all furnace mouth.

Main Engine. Oil fuel installation, auxiliary machinery, steering gear, windlass & pumping arrangements were examined at sea under normal conditions & found satisfactory with the exception of Dynamo Engine & Armature whose future efficient running has been entered as S.R.L.

A. H. Sinclair
Grenock. 9-3-50.

© 2021 Lloyd's Register Foundation

~~735 mrs~~



© 2021
Lloyd's Register
Foundation