

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

No. 36056

Date of writing Report 3rd March 1953

(Received at London Office)

When handed in at Local Office

19

Port of

Rotterdam

No in Reg. Book. Survey held at

Vlaardingen

Date

First Survey 19th Jan. 53Last Survey 14th Febr. 1953

(No. of Visits 10)

90872 on the Machinery of the Wood, Iron or Steel

m.p. GERRY-S

Tonnage { Gross 499
Net
Nominal
Horse Power }

Vessel built at

Terneuzen

By whom

N. V. Terneuzense Scheepb. Mij.

Year. Month.

Engines made at

Amsterdam

By whom

Werkspoor N.V.

When

Boilers, when made (Main)

(Donkey)

Owners

N. V. Rotterdamse Kolon Centrale

Owners' Address

(if not already recorded in Appendix to Register Book)

Port

Rotterdam

Voyage

Nieuwe

No. of Main Boilers

No. of Donkey Boilers

Steam Pressure—

in Main Boilers

in Donkey Boilers

Last Report No.

Port

Particulars of Examination and Repairs (if any)

Dam.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a through examination at this time?

If not, state for what reasons.

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler.

Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

and of the Donkey Boilers?

Has the screw shaft now been drawn and examined?

Yes

Has it a continuous liner?

No

Is an approved oil retaining appliance fitted at the after end?

Has shaft now been changed?

No

If so, state reasons.

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

State date of examination of Screw Shaft.

20-1-53

State the wear down in the stern bush.

Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

It is stated by Owners representative that difficulties have been experienced with screw shaft during last voyage, same running hot in sternbush. Vessel placed on slipway. Propeller, sternbush and outside fastenings examined. Screw shaft drawn, same exnd and found slightly scored at the forward end of the sternbush and also signs of fretting of the sternbush in way, neckbush scored.

Repairs due to damage: Screw shaft at sternbush bearing slightly ground fair, also sternbush at forward end. Screw shaft refitted and neckbush renewed. Screw shaft plumber block lined up, also intermediate - thrust shaft and main engine. Chocks renewed as found necessary, alignment examined and found satisfactory.

On completion of repairs the machinery examined at a full power sea trial and all found in good working conditions.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11, LMC 9,11 or LMC 140 lb., FD, &c.)

OS 3,31

For information of the Committee. (T.S. seen 1-53)

Survey Fee (per Section 23)

Fees applied for

10-3 19.53

Special Damage or Repair Fee (if any)

Received by me,

(per Section 23.)

19

Travelling expenses (if chargeable)

Committee's Minute

Assigned

See minute on F.E. machy rpt. Ant. 28246.

Guillaume Jacobo
Engineer Surveyor to Lloyd's Register of Shipping.

012620-012623-0040

Lloyd's Register
Foundation