

Report of Survey for Repairs, &c., of Engines and Boilers.

MON. 12 SEP 1892.

No. *10633* Date of Writing Report *7th Septe* 1892 Port of *Greenock*
No. in Reg. Book *26* Survey held at *Greenock* Date, first Survey *and* Last Survey *6th Septe* 1892
on the Machinery of the *S.S. "Naparima"* Master *Cruchy* No. of Visits *ma*
YEAR. MONTH.
Tonnage { Gross *1649* Vessel built at *Newcastle* By whom *Edwards Shipbuilding Co. Ltd.* When *1890* 2
Net *1043* Engines made at *Newcastle* When *1890* Boilers, when made (Main) *1890* (Donkey) *1890*
Registered Horse Power *160* Owners *James Prentice & Co. Port Glasgow* Voyage *Port India via Glasgow*
No. of Main Boilers *Two* If Surveyed Afloat or in Dry Dock *Scotts Dry Dock* Class of Vessel & Machinery *100A1. 1.92*
Steam Pressure in Main Boilers *160 lbs* (State name of Dock.)
in Donkey Boiler *80* (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) *LMC. 2.90*
Last Survey No. Port

Particulars of Examination and Repairs (if any) of *part Machinery*
(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from
Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *me*
Do. " Donkey " " "
If this was not done, state for what reasons? *Boilers not due for Survey.*
And what parts of the Boilers could not be thus thoroughly examined?
Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?
Did the Surveyor examine the Safety Valves of the Main Boiler?
At what pressure were they afterwards adjusted under steam?
Did the Surveyor examine the Safety Valves of Donkey Boiler?
To what pressure were they afterwards adjusted?

Vessel in Dry Dock for Cleaning & recasting bottom.

Examined propeller outer end of screw shaft & stem bush and fastenings of sea connections and found them in good order.

General Observations, Opinion, and Recommendation:—
(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1,91, B.&M.S. 1,91, or L.M.C. 1,91, as the case may be.)

The above mentioned parts of Machinery are now in good order and safe working condition and the vessel is in my opinion eligible to remain as named in Register Book

Office or Registration Fee (per Sec. 27)	£	:	Fees applied for
Survey Fee (per Section 28)	£	:	18
Special Damage Fee (per Section 28)	£	:	Received by me,
Travelling Expenses (if chargeable)	£	:	18

*State if Certificate is required

Committee's Minute *TUES. 13 SEP 1892*
Assigned *As now*