

11626

(Received at London Office

12 JUL 92

(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.

Repairs on account of Damage should be separated from

Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler ?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Special survey held at this time at the request of Owners - all the working parts of machinery opened out and there were examined the cylinders, pistons, slide valves - pumps, crankshaft & shafting, pipes & connections - Particulars of new main & donkey boilers are given on annexed form.

Damage survey now held at Owners request for the purpose of ascertaining the amount of damage stated to have been sustained through the vessel striking the bar at Figueira on the 30th January & 11th February while entering & leaving that Port on a voyage from Newport.

Investigation found the condenser bottom joint to soleplate started and leaking and covered with cement - the air & circulating pump joints and the joint between the cylinders also started & leaking - found the crank shaft flawed in fillets of both high & low pressure crank pins - the piston rods of both engines fractured - the condenser bottom covered with mud & sand and the tubes at joint to plates leaking - also found the water service pipes muddy & dirty - the bilge pipes in engine room & storeroom damaged & out of order - the engine soleplate holding down bolts slack.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification and notation of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1,91, B.&M.S. 1,91, or ~~X~~L.M.C. 1,91, as the case may be.)

The engines & boilers are now in good & safe working condition and eligible to be classed **+ L.M.C. 6-92** in the Register Book also the notification **+ N.B. 92** on account of the new main boiler now fitted particulars of which are given on annexed form.

Office or Registration Fee (per Sec. 27)..... £ :

Survey Fee (per Section 28) £ :

Special Damage Fee (per Section 28)..... £ 3:

Travelling Expenses (if chargeable) £ :

*State if Certificate is required

Committee's Minute

Assigned

+ Lm C. C. 92 + R. B. 92

Fees applied for

4/4 18

11

Received by me,

11/4 1892

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Report of Survey for Repairs, &c., of Engines and Boilers.

No.	Survey	Port	Class of Vessel & Machinery	Port	Owner's Name	Registered	No. of Main Boilers	Steam Pressure in Main Boilers	No. of Donkey Boilers	Gross Tonnage	Net Tonnage	Survey held at	Date	Part of
11026	Survey No.	Port	Class of Vessel & Machinery	Port	Owner's Name	Registered	No. of Main Boilers	Steam Pressure in Main Boilers	No. of Donkey Boilers	Gross Tonnage	Net Tonnage	Survey held at	Date	Part of
11026	Survey No.	Port	Class of Vessel & Machinery	Port	Owner's Name	Registered	No. of Main Boilers	Steam Pressure in Main Boilers	No. of Donkey Boilers	Gross Tonnage	Net Tonnage	Survey held at	Date	Part of

Particulars of Examination and Reports (if any) *Acute Leucæmia & Pneumonia.*

State also the date and initials of each person receiving this card.

1. The first and most important thing to do is to make each man better separately and make a thorough examination at this time.

11 This was not done, state for what reasons?

And what parts of the Bollocks could not be thus theologically examined?

Some eyes to assist himself of the thorough efficiency of these parts of each roller ?

And what special means, in the absence of instant communication, were adopted by him

11 what pressure were they afterwards adjusted under steam

11-11-61

John Brown

1891

Paul: ...

[Faint handwritten text, likely bleed-through from the reverse side.]

...the ... of the ...

the two sides of the river

1890

...the ... of the ...

Nothing more worth writing - I am Dear Sir

Handwritten text, likely bleed-through from the reverse side of the page, is visible at the bottom of the page.

on bottles of ink & other things -

continued. The children had been crying with pain and

Point to plate latrine - we found the water source

1914 - The large house on the corner of the street

Notes - The engine is not running. The engine is not running. The engine is not running.

.....

that, for example, $B^2, 1.01, B^2, 1.01, 1.01$ or $2.01, 1.01$ or $2.01, 1.01$ as the case may be.)

...the ...

1860

1891

not applied to

11/11/1911

2

State if Certificate is required

NAME: _____

12

Lloyd's Reg

Foundation

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some faint smudges and discoloration, particularly along the bottom edge. There is no text or other markings on the page.

S. S. "Elfrida"

Recommended that the condenser bottom joint to soleplate also the air & circulating pump joints be remade - this necessitating the removal of the condenser pumps - also recommended that the cylinders be removed & rejointed - that the crankshaft be replaced by a new one - that the piston rods be renewed - that the condenser tubes be all removed, the condenser cleaned, tubes replaced & tested, condenser doors rejointed and any tubes found damaged to be replaced with new ones - that the water service pipes be all taken adrift, cleaned & replaced - that the bilge pipes in engine room & stokehold where damaged & where cut to facilitate the work in hand, be renewed.

Also recommended that the vessel be placed in Dry Dock for the examination of the propeller, shaft & connections and sea cocks, and that the tunnel shafting be righted and that the whole of the working parts of engine be opened out for examination.

Found the propeller slack on shaft, found the joint of main blow-off cock defective and the bolts of the donkey blow off cock damaged & slack and the tunnel shafting & soleplate out of line.

Recommended that the propeller be removed & refitted - that the shaft be drawn in for examination - that the tunnel blocks be adjusted to the corrected line of shafting - that the holding down bolts be removed & the soleplate adjusted to line of tunnel shaft - and that all platforms & fixtures removed to further the work in hand be again replaced & secured.

All of the above recommendation have been satisfactorily carried out.

J. R.