

Report of Survey for Repairs, &c., of Engines and Boilers.

Feb 23 FEB 1894

Date of writing Report 22nd Feb 1894 When handed in at Local Office 18 Port of Glasgow
 No. in Reg. Book. 167 Survey held at Glasgow Date, First Survey 1st Feb 94 Last Survey 19th Feb 1894
on the Machinery of the Wood, Iron or Steel S. S. Pegu Master Taylor
 Tonnage { Gross 3661 Vessel built at Dumbarton By whom W. Denny & Sons When 1889 MONTH 4
 Net 2391 Engines made at Dumbarton When 89 Boilers, when made (Main) 89 (Donkey) 89
 Registered Horse Power 354 Owners Brit & Amer. S. N. Co. Ltd Port Glasgow Voyage Rangoon
 No. of Main Boilers 2 Steam Pressure—180 lbs If Surveyed Afloat or in Dry Dock
 in Main Boilers 180 lbs (State name of Dock.)
 in Donkey Boiler 180 lbs

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned how expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>1-100 A 1</u> <u>2.93</u>		<u>1-L M. & C.</u> <u>4.89</u>

Last Survey No. Comp. Port S.S. No 1.
 Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

yes

Do. " Donkey " " "

yes

If this was not done, state for what reasons?

—

And what parts of the Boilers could not be thus thoroughly examined?

—

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

—

Did the Surveyor examine the Safety Valves of the Main Boiler?

yes

At what pressure were they afterwards adjusted under steam?

180 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler?

yes

To what pressure were they afterwards adjusted?

180 lbs

If the Survey is not complete state what arrangements have been made for its completion?

—

This vessel has been placed in dry-dock when the tail shaft was drawn in for refitting of propeller. Shaft sound & good as far as seen. All sea cocks & valves examined.

The engines have all been opened up all parts examined such as cylinders, pistons valves, rods, shafting, pumps and condenser and put good order.

The boilers have been examined and found in good order.

This survey has been held at this time to bring the Board of Trade survey to correspond with the Annual Boiler Survey.

General Observations, Opinion, and Recommendation:—

This vessel's machinery

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey; thus, for example, B.S. 9, 92, B.&M.S. 9, 92 or L.M.C. 9, 92, as the case may be.)

is now in our opinion in a good and efficient working condition and eligible to be noted: 1-L M. & C. 2.92 in the Society's Register Book.

Office of Registration Fee (per Sec. 27) £ :
 Survey Fee (per Section 28) £ :
 Special Damage Fee (per Section 28) £ :
 Travelling Expenses (if chargeable) £ :

Fees applied for

18

Received by me,

18

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

Committee's Minute TUES. 27 FEB 1894

Assigned 1-L M. & C. 2.94

GLS169-0158

John Macdonald
 Esq. Surgeon to Lloyd's Register of British and Foreign Shipping
 10th May 1871

Register Book.
to be noted:
Efficient working condition
is now in our opinion in a good and

This Report is copied by Co

in good order. —
The bottom has been examined and found
order. —
Shipping, pumps and the stowage and put good
examined that on shipment, find no water, no
The engines have all been examined up all parts
each water room. —
propeller. Shaft cannot go up as far as before. All are
back when the last shaft was down on the rafting of
this boat has been placed in dry.

180 No 24

1 A 1000
p. 2

1006
-1987
1528
S

1006
1006

[Faint handwritten notes and bleed-through from the reverse side of the page are visible.]