

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report April 10th 1898 When handed in at Local Office April 18th 1898 Port of Marathon Mexico

No. in Reg. Book 183 Survey held at Guaymas Mex. Date, First Survey Altata Last Survey December 1897
on the Wood, Iron or Steel Sc. Log (No. of Volls) Master Joaquin Arano

TONNAGE:- Built at London By whom W. Walker & Co When 1887-10
GROSS 116 Owners Western Railway Co of Mexico Port belonging to Marathon
UNDER DEK 112 Owners' Address Marathon Mexico
NET 4 (If not already recorded in Appendix to Register Book.)
Surveyed Afloat or in Dry Dock? — Name of Dock Shipway Destined Voyage Marathon
WB=CellDBorDBa feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
NB.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 2 Port of Guaymas Mex

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

CHARACTER	Years Assigned	Machinery and Boiler Survey
* for Special Survey, Date of last Survey and of Periodical Surveys.	now assigned	(including date of N.B., if any).
<u>*100A1</u>	<u>10,90</u>	<u>LMC 10,90</u>
		<u>NB88</u>
<u>SS No. 3-10.90</u>		
Society's Freeboard (if assigned) as painted on Ship and now verified		

REPAIRS, OR EXAMINATION AS PER RULE, FOR (See over)

Repairs to be made
 Keel plates to be renewed from center of vessel to the stern post, also the rivets which are completely eaten through.
 At the present date the vessel has not been repaired. (See over on 7.5.98 attached)


SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Faired or Repaired ...								

PRESENT CONDITION OF THE	Timbers of Frame at the openings	Rudder	Hatches
Decks <u>newly coaked</u>	Ditto ditto at other places	<u>good order</u>	<u>renewed</u>
Waterways <u>good</u>	Keslsons <u>good order</u>	Windlass & Capstan <u>good</u>	Boats <u>2 boats in good order</u>
Coamings <u>in good order</u>	Stringers, Clamps & Shells <u>good</u>	Have Pumps now been examined and found efficient? <u>all the pump in order</u>	Masts, Yards, &c. <u>in good order</u>
Up'r Dk. Beams & Fastenings <u>good</u>	Salting <u>examined no salting</u> (State if examined.)	Have Sluice Valves now been examined and found efficient? <u>found in order</u>	Condition, how ascertained <u>wedges rem.</u> (State if wedges removed)
Low'r Dk. Beams & Fastenings <u>good</u>	Ceiling <u>in good order</u>	Have Watertight Doors now been examined and found efficient? <u>efficient</u>	Sails <u>all mending good</u>
Plating <u>upper sides good</u>	Cement or Asphalt <u>Cement good</u> (State which.)	Ubing. Plates under Sounding Pipes	Equipment letter
Planking <u>bad on bottom</u>	Tanks <u>no tanks</u> (State if now tested.)	Engine Room Skylights <u>good order</u>	Anchors, No. of <u>2 Hower / 1 Main 2 Keel</u>
Rivets <u>bad on bottom</u>	Caulking of Bot'm, D'k, & Wat'rwys	Coal Bunker. Open'gs, Lids, &c. <u>good</u>	Cables (state if now ranged) <u>ranged</u>
Breasthooks & Stenson <u>good</u>	Copper, or Y.M. <u>—</u> (State if on Feil.)	Souppers <u>in good order</u>	" length <u>120 faths</u> size <u>7/8</u> (on board) <u>170 faths</u> size <u>1 1/8</u>
Transoms, Pointers, & Crutches	When put on, Month Year	Cargo & Main H'tch'wys <u>good</u>	" Rule length <u>60 faths</u> size <u>1 1/2</u> (per Table 23)

General Observations, Opinion as to Class, Recommendation, &c. :-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 197," or "to remain as classed and to have record of survey, 197, and the notations of *sc* No. 1-97 and *ptND97*, &c."

Office Fee (if chargeable) per <i>Scale II., Sec. 27</i>	£	Fees applied for,	£
Survey Fee (per <i>Section 23</i>)	£	Received by me,	£
Special Damage or Repair Fee (if any) (per <i>Sec. 23</i>)	£		£
Travelling Expenses (if chargeable)	£		£
Second Surveyor's Fee (if any)	£		£

J. J. Mynder
Surveyor to Lloyd's Register of British & Foreign Shipping.



Has a Survey also been held on the Machinery of the ship? If so, is the Report sent now, or when will it be sent?

2887-1900-28/97-Transfer In. (TA) Surveys are requested and to write on or refer the space for Committee's Minute.

Is Certificate registered? If so to be sent to

LON 715-0315

In answer to questions of Lloyd's Secretary.

- 1st I personally examined the rudder, rudder head, stem frame, and stem, also all the steering gear, and found it in good order.
- 2nd The holds, coal bunkers, and fore and after peaks cleared, three shakes of ceiling or lumber boards, of each side were lifted, fore and aft, and did personally examine them, and found the cementing of the bottom in good order, including those of the machinery space.
- 3rd The chain cables were ranged, and I ascertained their length one chain 120 fathoms $\frac{5}{8}$ new chain, one 80 fathoms $\frac{5}{8}$ in new.
- 4th I personally examined the anchors, two bows of 4 feet each. One steam anchor and chain, and two kedges, one spare bow and one spare chain.
- 5th I examined the masts, also had the wedges taken out, the rigging stripped, and found it bad. Had new rigging replaced, and the general Deck equipment is good.
- 7th In regard to the fractured keel plate and rivets, nothing has been done to the vessel, and I do not know when it will be done.

So this ^{was} my reason for not writing the report on said vessel before the repairs were made

Marathon Mexico April 18th 1898
 J. J. Alexandre

13th January 1899

Expenses till Tuesday
 Cable Lloyd's agent

JAN 17 1899

Expenses till Friday

JAN 20 1899

Expenses clear with red line

Write Owners
 2020/1/26

Jan 26 Jan. 1899
 Decision of Messrs
 Coma companies



N.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much draped as to spread the ink, or cause it to show through to the other side.

AS THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.