

(Received at London Office) **TUES, 27 SEP 1898**

Last Survey No. \_\_\_\_\_ Port \_\_\_\_\_

Particulars of Examination and Repairs (if any) *Damage. + 100 A 6.98 + L. M. C 10.98*

EXAMINER.  
✕ for Special Survey.  
Date of last Survey and of  
Periodical Surveys.

Years  
Assigned  
to  
expired

Machinery and Boiler  
Surveys  
(including date of N.B., if any).

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do.	"	Donkey	"	"	"
-----	---	--------	---	---	---

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler ?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Has the propeller shaft been drawn and examined at this time? Yes If spare propeller shaft fitted, state whether new?

State the distance between lignum vitæ of stern bush and top of after bearing of screw shaft? *New wood*

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Now done on account of Damage. Please see Port Natal Report No 183:— Propeller found broken. Stern bush

found slightly shaken in place.  
Damage Repairs now done: Tail Shaft-tried in Lathe  
and found free from any appearance of defect.  
Horn-bush trimmed outside re-lined with Lignum vitae  
and efficiently re-fastened in place. Tail Shaft re-placed  
and a new Gun Metal Propeller fitted.

*General Observations, Opinion, and Recommendation:—*

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,97, B.&M.S. 9,97 or S.L.M.C. 9,97, 10 lb., F.D., &c.)

The Machinery of this Vessel is in good order and in my opinion eligible to remain as closed, without fresh records.

Office or Registration Fee (per Sec. 27).....	£	:	:	Fees applied for
Survey Fee per Section 28).....	£	:	:	18
Special Damage Fee (per Section 28).....	£	:	:	
Travelling Expenses (if chargeable).....	£	:	:	
				Received by me,

\*State if Certificate is required

## Committee's Minute

*Assigned*

As now  
but without spl. could be

*J. Ritchie.*  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

LON716-0371



Lower shaft examined, stern bush  
unwooded refitted. propeller  
unwood on acc of damage.

It is submitted that  
this vessel is eligible to  
remain as CLASSED. without  
special restriction

*Handwritten:*  
27/9/98

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation