

364-

No. 364 Survey held at Sundaland Date December 1835
 on the Ship "Eliza Isabella" Master Alex' Watters
 Tonnage 140 Built at Sundaland When built 1835
 By whom built Henry Dixon Owners W Mitchell & Co.
 Port belonging to Shoreham Destined Voyage to Shoreham
 If Surveyed Afloat or in Dry Dock during the Building

Length aloft.....	Feet. Inches.	Extreme Breadth	Feet. Inches.	Depth of Hold	Feet. Inches.
Scantlings of Timber.					
Timber and Space.....	each $\frac{1}{2}$ $\frac{1}{2}$	Inches. Middle Ends	Keel to Bilge	$\frac{1}{2}$	Foot Waling.....
Floors.....	sided $\frac{1}{2}$ Moulded $\frac{1}{2}$ $\frac{1}{2}$		Bilge Planks	$\frac{1}{2}$	Bilge Planks
1 st Foothooks.....	" $\frac{1}{2}$ $\frac{1}{2}$		Bilge to Wales	$\frac{1}{2}$	Ceiling in Flat
2 nd Ditto.....	" $\frac{1}{2}$ $\frac{1}{2}$		Wales	$\frac{1}{2}$	Ditto Bilge to Clamp
3 rd Ditto.....	" $\frac{1}{2}$ $\frac{1}{2}$		Topsides	$\frac{1}{2}$	Hold Beam Clamps
Top Timbers	" $\frac{1}{2}$ $\frac{1}{2}$		Sheer Strakes	$\frac{1}{2}$	Deck Beam Ditto.....
Deck Beams	" $\frac{1}{2}$ $\frac{1}{2}$		Plank Sheers.....	$\frac{1}{2}$	Ceiling 'twixt Decks
Hold Beams	" $\frac{1}{2}$ $\frac{1}{2}$		Water-ways	$\frac{1}{2}$	Hold Beam Shelves
Keel ^{length of Am. M. Y. Wm.}	" $\frac{1}{2}$ $\frac{1}{2}$		Upper Deck ^{Yarn}	$\frac{1}{2}$	Deck Beam ditto
Kelsons	" $\frac{1}{2}$ $\frac{1}{2}$				

Thickness of Plank.

Outside.	Inside.	inches.
Keel to Bilge	Foot Waling.....	$\frac{1}{2}$
Bilge Planks	Bilge Planks	$\frac{1}{2}$
Bilge to Wales	Ceiling in Flat	$\frac{1}{2}$
Wales	Ditto Bilge to Clamp	$\frac{1}{2}$
Topsides	Hold Beam Clamps	$\frac{1}{2}$
Sheer Strakes	Deck Beam Ditto.....	$\frac{1}{2}$
Plank Sheers.....	Ceiling 'twixt Decks	$\frac{1}{2}$
Water-ways	Hold Beam Shelves	$\frac{1}{2}$
Upper Deck ^{Yarn}	Deck Beam ditto	$\frac{1}{2}$

Copper.

	inches
Heel-Knee, and Dead Wood abaft	$\frac{1}{2}$
Scarps of Keel.....	$\frac{1}{2}$
Floor Timber Bolts.....	$\frac{1}{2}$
Kelson ditto.....	$\frac{1}{2}$
Transoms and throats of Hooks	$\frac{1}{2}$
Arms of Hooks	$\frac{1}{2}$

Size of Bolts in Fastenings.

Copper.

	inches
Bolts thro' the Bilge and Foot Waling	$\frac{1}{2}$
Butt End Bolts	$\frac{1}{2}$
Lower Pintle of the Rudder	$\frac{1}{2}$

Iron.

	inches
Hold Beam	$\frac{1}{2}$
Deck Beam	$\frac{1}{2}$

Timbering.—The Space between the Floor Timbers and Lower Foothooks in this Vessel is $\frac{1}{2}$ Inches. The Space between the Top-timbers is $\frac{1}{2}$ Inches.

The Stem, Stern Post, Transoms, Aprons, Knight Heads, Hawse Timbers, are composed of English Oak and are usually free from all defects.

Her Floors and first Foothooks are composed of English Oak Timber.

Her other Foothooks and Top Timbers of English Oak

Her Shifts of the first and second Foothooks are not less than $\frac{1}{2}$ to $\frac{1}{2}$ N.B. When reported by you less than the prescribed Rule, then state how many. Several feet on both sides, very short scarp -

The rest of the Shifts of the Frame are indifferent-

The Frame is badly squared from the first Foothook Heads upwards, and not free from sap, and from thence downwards, the frame is badly squared & slightly in several places:

The alternate Frames are not bolted together. 10 Frames on each side bolted up to 2nd Head

The Butts of the Timbers are usually close together; their thickness not less than $\frac{1}{2}$ to $\frac{1}{2}$ of the entire moulding at that place.

The Frame is badly chocked with no Butt at each end of the chock.

The Main Kelson is composed of Amer. Oak and the False Kelson of Amer. Oak

The Scarps of the Kelsons are not less than 8 feet 6 inches.

The Deck and Hold Beams are composed of English Oak

Planking Outside.—This Vessel's Plank from the Keel to the first Foothook Heads is composed of Amer. Elm

From the first Foothook Heads to the Light Water Mark of Amer. Elm

From the Light Water Mark to the Wales of Baltic English Oak

The Wales and Black-strakes are of Afr. & English Oak & Baltic Oak

The Topsides of English Oak

The Sheer-strakes of English Oak

The Gunwales of Baltic Oak Water-ways of African Oak

The Shifts of the Planking are not less than 5 feet — Inches. N.B. If reported less than the prescribed Rule, state whether general or partial, and if partial, in what part of the Ship. Wrought at the bow ship, the scarp an from 3 to 4.6

The Planking is wrought 2 and 3 between generally 2

Planking Inside.—The Clamps are composed of Foreign Oak the Stringers of Foreign Oak

The Bilge Planks of Foreign Oak and the remainder of the Ceiling of English Oak

Fastenings.—To Hold Beams Double Wood Lugs & Knur; and Shelf underneath -

Deck Beams Double Wood Lugs & Knur and Shelf underneath -

Number of Breasthooks Four Pointers None Crutches none Wood Jawson Knur

Butts End Bolts are of 1 in the Bottom, and one Bolt in each Butt End through and clenched.

Bilge and Footwaling is bolted through and clenched.

General Quality of Workmanship Very indifferent throughout

We certify that the preceding is a correct description of the above-named Vessel.

Builder's Name

Surveyor's Name

John Brantley

Her Masts, Yards, &c. are in good condition, and sufficient in size and length.

*Mast of yellow Pine remainder
of Red Pine*

She has SAILS.

CABLES, &c.

ANCHORS.

Nº.	Fathoms.	Inches.	Nº.	cut	cut	cut
2	Fore Sails,	160	Chain Certificate seen.....	1	3	Bower, 8 $\frac{1}{2}$ - 8 - 7 $\frac{1}{2}$
1	Fore Top Sails,		Hempen Stream Cable.....	1	1	Stream, 3 $\frac{1}{4}$
2	Fore Topmast Stay Sails,	60	Hawser	1	1	Kedge, 1 $\frac{1}{4}$
1	Main Sails,	80	Towlines	6 $\frac{3}{4}$		All of proper weight.
2	Main Top Sails, and to be found in the tail	75	Warp	4 $\frac{1}{2}$		
			All of <u>good</u> quality.			

Her Standing and Running Rigging is well fitted sufficient in size and good in quality.

She has One Long Boat and Skiff good and suitable for the vessel.

The present state of the Windlass is good Capstan _____ and Rudder with 4 Beams good

One Chain Cable old but Retested, Hawser old but very good.

John P. Denton

General Remarks—Statement and Date of Repairs.

Frame is generally wide & irregularly spaced; part of the Frame placed on the moulding side & several timbers on L side with little care or skill; several shores, not well seated; The fittings to stem & stern post are wainshippy; particularly the former very thin and insufficient; Hull knee is short in both arms; several of the beams are wainshippy on the topside small ends; New Monk, English Oak and a generally wainshippy. The quality of planking is generally good; but in some parts indifferent wrought; Turnals of big Oak totally good; All iron fastened.

This Vessel commenced building in Dec: 1835 launched in Dec: 1835 under contract and was duly surveyed in different stages on $\frac{20}{9} : \frac{20}{10} : \frac{11}{11}$.

Her general appearance is very indifferent, and cannot be given a certificate for a higher class than the Undersigned.

If Sheathed, Doubled, or Felted,

and Date when last done

And one of opinion this Vessel should be Classed A.A.I.

John Bawton

John P. Denton

The Amount of the Fee £ 2 : 2 : 0 is received by me,

SDR23/380

Committee Minute 24 December 1835

Character assigned A for 1 year

N.W.L.

J.P.D.



© 2018

Lloyd's Register
Foundation