

No. 503 Survey held at Sunderland Date June 1836
 on the River Tyne Master C. Munand
 Tonnage 224 Built at Sunderland When built 1836/1822/822
 By whom built Jas. Johnson Owners W. Boyes 108 Register
 Port belonging to Sunderland Destined Voyage unchanged
 If Surveyed Afloat or in Dry Dock Opened Ways

Length aloft.....	Feet. Inches.	Extreme Breadth	Feet. Inches.	Depth of Hold	Feet. Inches.
Scantlings of Timber.					
Timber and Space	each $\frac{1}{12}$	Inches. Middle	Inches. Ends	Thickness of Plank.	
Floors.....	sided $\frac{1}{12}$	Moulded $\frac{1}{12}$	9	Outside. Keel to Bilge	3
1 st Foothooks.....	$\frac{1}{12}$	8		Bilge Planks	4
2 nd Ditto.....	$\frac{9}{10}$	$\frac{7}{12}$	"	Bilge to Wales	$\frac{3}{4}$
3 rd Ditto.....	"	"	"	Wales	$\frac{1}{4}$
Top Timbers	"	"	"	Topsides	$\frac{1}{2}$
Deck Beams	9	9	5	Sheer Strakes	3
Hold Beams	11	11	8 $\frac{1}{2}$	Plank Sheers	3
Keel $\frac{1}{2}$ Length of Am. by Mr. ...	11	9	28	Water-ways	4
Kelsons	12	28		Upper Deck Battic	3

Copper.	Size of Bolts in Fastenings.	Copper.	Iron.
Heel-Knee, and Dead Wood abaft		Bolts thro' the Bilge and Foot Waling	3/4
Scarps of Keel.....	N.	Butt End Bolts	-
Floor Timber Bolts.....		Lower Pintle of the Rudder	2 $\frac{1}{2}$
Kelson ditto.....			
Transoms and throats of Hooks			same in Iron above the Copper
Arms of Hooks			

Timbering.—The Space between the Floor Timbers and Lower Foothooks in this Vessel is $\frac{1}{2}$ Inches. The Space between the Top-timbers is $\frac{1}{2}$ Inches. The Stem, Stern Post, Transoms, Aprons, Knight Heads, Hawse Timbers, are composed of *English Oak* and are *perfectly* free from all defects.
 Her Floors and first Foothooks are composed of *English Oak* Timber.
 Her other Foothooks and Top Timbers of *repeated English Oak*.
 Her Shifts of the first and second Foothooks are not less than $3\frac{1}{2}$ to $4\frac{1}{2}$ inches. N.B. When reported by you less than the prescribed Rule, then state how many.

The rest of the Shifts of the Frame are _____

The Frame is *fairly* squared from the first Foothook Heads upwards, and *not* free from sap, and from thence downwards, the frame is *generally well grained*.

The alternate Frames are _____ bolted together.

The Butts of the Timbers are *well close* together; their thickness not less than $1\frac{1}{2}$ inches of the entire moulding at that place.

The Frame is _____ chocked with *a* Butt at each end of the chock.

The Main Kelson is composed of *American Oak* and the False Kelson of *American Oak*.

The Scarps of the Kelsons are not less than *6* feet *—* inches.

The Deck and Hold Beams are composed of *American and English Oak*.

Planking Outside.—This Vessel's Plank from the Keel to the first Foothook Heads is composed of *American Beech*.

From the first Foothook Heads to the Light Water Mark of *American Beech*

From the Light Water Mark to the Wales of *English Oak*

The Wales and Black-strakes are of *English Oak*

The Topsides of *English Oak*

The Sheer-strakes of *English Oak*

The Gunwales of *English Oak*

The Water-ways of *English Oak*

The Shifts of the Planking are not less than $3\frac{1}{2}$ to $4\frac{1}{2}$ Feet *—* inches. N.B. If reported less than the prescribed Rule, state whether

general or partial, and if partial, in what part of the Ship.

The Planking is wrought *generally* $2\frac{1}{2}$ between.

Planking Inside.—The Clamps are composed of *Oak* the Stringers of *Oak*

The Bilge Planks of *Oak* and the remainder of the Ceiling of *Oak* *(with a few Planks of Pine)* *flat*

Fastenings.—To Hold Beams *South Wood Ledge Knot and Spike* *both above below*

Deck Beams *South Wood Ledge Knot*

Number of Breasthooks *Five* Pointers *—* Crutches *Felt* *reasone*

Butts End Bolts are of *Copper* in the Bottom, and *no* Bolt in each Butt End through and clenched.

Bilge and Footwaling *is not* bolted through and clenched.

General Quality of Workmanship *Fair*

We certify that the preceding is a correct description of the above-named Vessel.

Builder's Name _____

Surveyor's Name *John Burton*

Brought & manned by R. Br.
Her Masts, Yards, &c. are in Good condition, and sufficient in size and length. Command of R. Br.

She has SAILS.

N^o.
2 Fore Sails,
2 Fore Top Sails,
2 Fore Topmast Stay Sails,
1 Main Sails,
2 Main Top Sails,
and is well framed.

CABLES, &c.

Fathoms.	Inches.
180	Chain 18 fms 3
60	Hempen Stream Cable 3 1/4
75	Hawser 3 1/4
3	Towlines 7 1/2
	Warp 5 1/4 : 4 3/4 : 4
	All of good quality.

ANCHORS.

No.	Cwt	Cwt	Cwt
3	10 1/2	10	10
1	3 1/2	—	—
1	1 1/2	—	—

Bower, Stream, Kedge, All of proper weight.

Her Standing and Running Rigging is in good order sufficient in size and tolerably good in quality.

She has a Clinch built Long Boat and is in good condition.

The present state of the Windlass is good. Capstan poor and Rudder with 4 bars all good

John P. Denton

General Remarks—Statement and Date of Repairs.

Frame of Ship when ripped is all of dry Tak of good scantling, well guarded and all sound. Chocking very good. Beams all sound, but a part of the dry beams run wavy & sloppy. Iron Hocks all dry Tak, part of them run short down and wavy but all sound. The far length of Shelf on top of hole Beams on S Side is defective; part of 2 L 8" are not stepped down from their points. The Waterways, Spinketing, plank shears, Star Sheets, topsides, upper deck, Water Mounts, also the plank & timbers outside, down to the keel appear all good. The shifting of the outside plank very indifferent: and Bulk nearly all stepped.

Repair done at the present time under account

New Middle keel of Am? Elm: 3 of 1 foot hocks, 2 hole hocks:

New Paul Pitt, Back New Spinketing, Ridge, bottom planks
hauled from water to keel.

If Sheathed, Doubled, or Felted,

and Date when last done

And we are of opinion this Vessel should be Classed

R. 1 John Brantley

The Amount of the Fee £ 1 : 1 : 0 is received by me, See Rec'd return

Sept. 1836

John P. Denton

Committee Minute 1 October 1836

Character assigned R. 1. J. D.

MPL