

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 11th March 1920 When handed in at Local Office 12 MAR 1920 Port of SUNDERLAND

No. in Reg. Book. not yet in Survey held at SUNDERLAND Date, First Survey 6 Jan Last Survey 10th March 1920

on the Wood, Iron or Steel Single screw steamer "AFON TOMY" Master J. Vaughan

TONNAGE:- Built at Southampton By whom Dibles Ltd YEAR. MONTH. 1920 3

GROSS 684 1/4 Owners W. Coombs Port belonging to Llanelli

UNDER DK. ✓ Owners' Address New Dock, Llanelli

NET 336 28 (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? both Name of Dock Bridge Destined Voyage France

WB=CellDBorDBa ✓ feet; uE&B ✓ feet; f ✓ feet; total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as 3 ft. 10 1/2 ins. painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? yes Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of 1st Entry Survey and Damage

Damage stated to have been caused by the vessel striking the North Pier while being towed into the river Wear on the 3rd January 1920.

The vessel was placed in dry dock, shell bottom, sides and rudder examined.

Shell, Starboard Side, (Numbers from forward.)

E Strake No. 3, off faired and re-placed

No. 4, faired in place.

F No. 4.

Riveting and caulking in vicinity of repairs made good.

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptd15, &c."

Survey Fee (per Section 28) £ 5 : 5 : 0

Special Damage or Repair Fee (if any) (per Sec. 29) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Committee's Minute

Character Assigned

Fees applied for, 12 MAR 1920

Received by me, 18.3.1920

19.

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

W1-0035

Is Certificate required? If so, to be sent to

Frames Star? Side. (numbered from collision bulk head to aft)
9th & 14th failed in place.

$10^{\frac{1}{2}}$, $11^{\frac{1}{2}}$, $12^{\frac{1}{2}}$ & $13^{\frac{1}{2}}$ re-sowed from margin to deck.

Rivets fitted in repairs and overhauled in the vicinity.

Ceiling over bilges removed in way of repairs, and re-laid. Cumcat cut out in pockets in way of repairs and re-laid.

Surfaces of material in way of repairs coated with bituminous composition.

Completion of 1st Entry Survey

Decks have tested and found to be satisfactory.

Dorraton Pump, Steering Gear, and Windlass found to be in working order.
after Peak bulkhead in way of Stern tube, found to be satisfactory.
Gunboard verified.

Deep keels and pillars fitted in Engine & Boiler Space.

Engine & Boiler Casing (top) riveted and caulked after shipping of machinery.
A few minor jobs satisfactorily completed.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST, PER CERTIFICATE.			WEIGHT REQUIRED by TABLE 30 or 31.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons.	Cwts.	qrs.	lbs.	Cwts.	qrs.			
	1st Bower ...															
	2nd "															
	3rd "															
	Collective Weight.															
	Stream															
	Kedge.....															

* When a bower anchor is supplied it must be clearly stated whether it is a ...

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.