

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

NEWCASTLE-ON-TYNE

Date of writing Report	16/4/39.	When handed in at Local Office	18/4/39	Port of
No. in Book.	Survey held at Newcastle on Tyne		Date, First Survey	13/3/39
729	on the Machinery of the Wood, Iron or Steel S/s "CORABELLA"		Last Survey	6/4/1939
Gross	5682	Vessel built at Sunderland	By whom	J.L. Thompson & Sons
Net	3373	Engines made at do	By whom	Geo. Clark & Sons
Motor Power	395	Boilers, when made (Main) 1937	(Donkey) ✓	When 1937
Main Boilers	3(44)	Owners	Owners' Address	Port LONDON Voyage
Donkey Boilers	220	Managers	(If not already recorded in Appendix to Register Book.)	
Pressure		# Surveyed Afloat in Dry Dock S.H.W.R. Dry Dk.		
Air Boilers		(State name of Dock.)		
Donkey Boilers				

Report No. Port

Particulars of Examination and Repairs (if any) Dry Cond & Dope

Local Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and being detailed in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he used his services for this purpose, and why they were declined

Dope Rpt. issued

damage report made by anyone else? If so, by whom?

Copies attached

also Interim Certificate at

at request of owner's Representative.

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Years since last surveyed & extinct.	Machinery and Boiler Surveys (including date of N.B., if any).
+100A1		+LMC 8-37
4-38. Sld		
		T500 4.38

Donkey ,

was not done, state for what reasons?

All parts of the Boilers could not be thus thoroughly examined?

At special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Last date of internal examination of each boiler

Present condition of funnel food

Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Surveyor examines all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Surveyor examines the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

Surveyor examines all the mountings of the Main Boilers?

, and of the Donkey Boiler?

Screw shaft now been drawn and examined?

Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? No

It now been changed? Yes If so, state reasons

Concave cracked at fore end of keyseat, and at aft end of liner

Screw shaft now fitted been previously used?

No Has it a continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? No

Date of examination of Screw Shaft 5/4/39

State the distance between lignum vitae on bearing metal of stern bush and top of after bearing of screw shaft

engine parts, when referred to by numbers, should be counted from forward.

close fit.

Is electric light and/or power fitted? Yes bush bored out

Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

Work done: Vessel placed in dry dock. Propeller (all solid bronze), stern brush, stern tube (drawn in in order to effect renewal of stem frame lower part), screw shaft (drawn in), sea connections with their shell fastenings examined and found or placed in good condition. Machinery condition: HP Poppet Valves, M.P.L.P. Slide valves, cages & chambers, Condenser pump of Centrifugal Water Pump, Main Stop Valves of the 3 main boilers, and Superheater Element Tubes examined and found or placed in good order.

Damage stated caused by propeller striking Quay Wall at Montreal on 17th May 1938 when leaving Montreal for Sydney, Cape Breton. See also Dope Rpt. dated 18/4/39 Newcastle. Repairs due to above:- Propeller sent ashore to shop and 3 bent tips fairled and built up by 'burning' and dressed up, the fourth blade tip (chipped) dressed up.

Screw shaft marked Lloyd's 817 W.H.F. 4/6/37, found fractured at both sides of keyseat at forward end of core, also at aft end of liner - rejected and the unused Spare Screw Shaft Lloyd's 817 W.H.F. 19/5/37 fitted as working shaft. A new Spare Screw Shaft Lloyd's 186 W.H.F. 4/4/37 Supplied.

Observations, Opinion, and Recommendation:-

To clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. D.II, B.A.M.S. 9.II, & L.M.C. 9.II, or S.E.M.C. 140 lb., F.D., &c.)


CN 2,34.

The machinery of this vessel is in good safe working condition, eligible in my opinion to remain as classed and to have record T.S.N.C.L. 4.39.

Fee (per Section 29) Condu Survey £ 2: 2: - Fees applied for 120 APR 1939
 Damage & Repair Fee (if any) Propeller Draft £ 5: 5: - Received by me,
 (per Section 29) Superheater £ 3: 3: - 19/4/39
 (per Section 29) Spec Rpt £ 1: : - 19/4/39
 (per Section 29) Total £ 10: 10: - 19/4/39

Committee's Minute FRI. 2 JUN 1939

As now



© 2020

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

W1168 - 0202 1/2

Machinery of the S/S "CORABELLA"

Alterations:

Propeller:- Recess at forward end of boss increased in diameter and a rubber joint ring fitted at extreme aft end of T.S. lever, in addition to the original gland ring and rubber ring which is fitted near the aft end of CL.

Diameter of Propeller reduced to 17-10" dia.

It was stated that 3" was cut off each blade tip.

Main Stop Valves of all 3 Boilers overhauled and each middle or "mixing steam" valve now fitted with a special sleeve and valve in order to reduce the area of passage when opened fully, each Saturated Steam Valve to Superheaters fitted with a new G.M. seat & valve lid, and each Superheated Steam Valve fitted with a new Monel metal seat & valve lid.

Repairs due to wear & tear

Superheater elements of all 3 Boilers - the tube ends in C.C. of which were found generally overheated & distorted - all tube ends renewed. See also Special Report dated 18/4/39. Copy attached

HD Poppet Valves & seats overhauled and 1 seat & valve renewed

MP Valve & cage (badly worn on front side) - renewed

MP Valve Spindle - scored & bent - renewed.

G.M. Grids of Main & Ballast injections on ship's side found loose and lugs for bolts wasted or missing - new lugs fitted to Sea Charts by Elec. welding and the grids secured by studs & nuts, Main Condenser opened up and tubes cleared by rod.

Main Engine & Thrust Seat HD Bolts overhauled & hardened up

Engine of Centrif Circ. Water Pumps - the Cylinder Intake valves

was broken (stated caused through a bottom end bolt breaking).

on 30th November 1938 when on voyage from Sydney, Cape Breton to Vancouver A.C.D.
Engine taken to shop. Engine overhauled and Cylinder Intake valves renewed and one bottom end bolt renewed. (one new bolt was stated to have been previously fitted when temporary repairs ^{alleged} were made after the casualty).

Examination on account of heavy weather:-

(1) on 25th & 26th October 1938 on voyage from Rotterdam to Sydney, Cape Breton Island.

(2) on Various dates between the 1st & 22nd Feb 1939 on voyage from Union Bay, British Columbia, to London For further particulars, see log books.

Steering Engine (aft in Poop House), opened up & examined, overhauled & adjusted and satisfactorily tested on completion.

See also Ship Report No. 8.

R.W.