

Rnt

Received from Chief Surveyors

ME

Steel S.S. "ANDREW JACKSON" Report

Phl

No. 3551

For the CHIEF SHIP SURVEYOR

Notes which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

When due

The Downton Pump has been dispensed with for the present.

100 A.1. (steel). "Shelter Dk. with freeboard."

1 DK (steel) & Shelter DK (steel), and Web frames

Longitudinal Framing.

Cell DB 362' 1434t. OTa 21' 153t. FPT 235t. APT 163t.

FK. ~~6~~ BH to Shelter Dk, ~~1~~ BH to Upper Dk. Genz.

Alt 18/6/20  
as above John Adams  
A4 C.P. P4i, B134', F44' on Shelter Dk.

Alt  
7-1-20

It is concluded, the floors in Double Bottom, thickness of centre girder angles, thickness of side girder angles, thickness of Bridge Deck plating, thickness of plating at ends of strakes H to N, spacing of nuts on each side of transverse webs for longitudinals No 8+9, & the spacing of nuts in shelter turn deck web lugs to shell are all as approved & as in sister vessels. That the bulkheads in sister vessels, namely 4 bulkheads to shelter deck & 3 bulkheads to upper deck, bulkhead stiffeners are as approved, that the sheerstrake has been doubled or red in thickness at the Bridge Ends, also that the nuts in edges of Porth & Forecastle platting are spaced 4 diameters apart as required but the Surveyors should be asked to state if this is so.

The Surveyors should also state whether in their opinion the workmanship is admy.

as above  
19/7/20

W1474-0058

©2021

Lloyd's Register  
Foundation