

Report of Survey for Repairs, &c., of Engines and Boilers.

SAT. MAY. 9 - 1914

(Received at London Office)

MAY 8 1914

Port of NEWCASTLE-ON-TYNE.

Date of writing Report 7th May 1914 When handed in at Local Office

Date, First Survey and

Last Survey 6th May 1914 (No. of Visits 1)

No. in Reg. Book. Survey held at Shields

By whom Richardson Durr & Co. When 1914

Master (Donkey) ✓

on the Machinery of the Wood, Iron or Steel

Gross 4350
Net 2700

Vessel built at Stockton

By whom Blair & Co. When 1914

Registered Horse Power

Engines made at

(Donkey) ✓

No. of Main Boilers

Boilers, when made (Main)

Port London Voyage Hot fixed

No. of Donkey Boilers

Owners Bursk & Co. 1914

Steam Pressure in Main Boilers

If Surveyed Afloat or in Dry Dock Dry Dock

in Donkey Boilers

Last Report No.

Port

Particulars of Examination and Repairs (if any) Docking

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Survey

Year Assigned for next survey. Machinery and Boiler Surveys (including date of N.B., if any).

100 A1 Class Contemplated

Not yet read.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

, and of the Donkey Boiler?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers?

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? ✓ or two liners? ✓ or is it without liners? ✓

Has shaft now been changed? No If so, state reasons ✓ or two liners? ✓ or is it without liners? ✓

Is the shaft now fitted new? ✓ Has it a continuous liner? ✓ or two liners? ✓ or is it without liners? ✓

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? Fitting.

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete.

Examined the propeller, aft end of bush & the fastenings of the sea cocks. & found all in order.

General Observations, Opinion, and Recommendation: The above is respectfully submitted for the information of the Committee.

Survey Fee (per Section 88) £ 10
Special Damage or Repair Fee (if any) £
Travelling Expenses (if chargeable) £

Fees applied for
Received by me, 10

George Murdoch
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute FRI. MAY. 15. 1914
Assigned Lee minute on 106 75 8420



© 2021 Lloyd's Register Foundation 01535-0026