

Screw $\frac{1}{2}$ " No 87

Ans 235-40.

It is submitted that before dealing with this case. the surveyor should be requested to state the area of each safety valve which he has omitted to state on his report.

Dr. Ans. 26/3/01



© 2021

26.2.01

W 157-0072

Dia. of Tunnel shaft

as per rule $5 \frac{7}{16}$
as fitted $5 \frac{5}{16}$

Dia. of Crank shaft journals

as per rule $5 \frac{7}{16}$
as fitted $5 \frac{9}{16}$ Dia. of Crank pin $5 \frac{7}{16}$ Size of Crank webs $4 \frac{1}{8} \times$