

Rpt. 8.

WRECK
SECTIONWRECK
(Received at London Office)

30 MAR 1953

No. 11421

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 17.3.53 When handed in at Local Office 17.3.53 Port of Marseille
No. in Reg. Book 54109 Survey held at Berre and Marseille Date, First Survey 14th January Last Survey 20th February 1953on the Wood, Iron & Steel British Motor Tanker BRITISH CHEMIST (No. of Tons pro)
Built at Newcastle By whom Salmon & Co Ltd When 1945 YEAR MONTH June
GROSS 6497 Owners British Tanker Co Ltd Owners' Address London
UNDER DK. 6428 Managers ✓ Port belonging to London
NET 429 Destined Voyage ForeignSurveyed Afloat or in Dry Dock? Afloat Name of Dock ✓
Cell D Bor DBa ✓ feet; uE & B ✓ feet; f ✓ feet
total capacity ✓ tons. FPT ✓ tons; APT ✓ tons; MT ✓ feet ✓ tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 110051. Port Swc.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined yes, to the MasterSociety's Freeboard (if assigned) as CONTINUOUS SURVEY.
painted on Ship and now verified ✓Noted not requiredWas a damage report made by anyone else? if so, by whom? NoREPAIRS, OR EXAMINATION AS PER RULE, FOR SHELL SIDE PLATING DAMAGE stated sustained on the 10th February during voyage to Berre through striking the CARONTE Railway Bridge on account of currents.Now done:was examined afloat at Berre during unloading operations and subsequently light at Marseille.FOUND:On Starboard bow (plates numbered from forward) the following plates damaged:

- (a) Forecastle side plating: P3 badly buckled P4 slightly buckled O3 badly buckled and no frames badly buckled
(b) Shell side plating in way of 2nd Deck: M3 M4 badly buckled and L3 L4 slightly buckled also P3 slightly buckled
(c) Shell side plating in way of hold: J3 slightly buckled J4 badly buckled and 4 frames in way

REPAIRS:P3, O3, M3-M4 (part of each, as one plate) and J4 renewed; N3, L3, J3 painted in place; internals fully renewed

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...	5 (2 part)	8 (part)	✓	✓	3 (part)	✓	1	approx 1000 feet breast
Removed and Fair'd or Repaired	✓	✓	1 deep	✓	✓	✓	✓	bolts renewed and
Fair'd or Repaired in place	3	12	✓	✓	✓	✓	1	5 strappings renewed & fair'd

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Coamings	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Beams & Fastenings	Rudder	Scuppers	Boats
Outside Plating	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
" " in way of sidelights	Windlass	Hatches	Condition, how ascertained
Frames	Have pumps been examined and found efficient? <u>Survey confined to the above mentioned items</u>	Blanketing	(State if wedges removed.)
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. of
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stems	Cables (State if now ranged)
Floors	Have the Tanks been examined internally?	Transoms, Pointers & Crutches	" length mean diamr.
Keelsons	Have the Tanks been tested?	Timbers of Frame at openings	(on board.)
Stringers		" " at other places	" Rule length size
Inner Bottom Plating		Stringers, Clamps & Shelves	Chain Locker
Have the Tanks been examined internally?		Salting	Hawser & Wops
Have the Tanks been tested?		State if examined	Standing and Running Rigging
			Sails

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-39."

This vessel, so far as has been seen, is in good condition and eligible, in my opinion, to be continued as classed in the Register Book without fresh record of Survey, subject to the bottom shell plating (a.s.f.) being specially examined at her next drydocking also subject to all conditions at present attached to her class being dealt with as previously recommended.

Survey Fee (per Section 23) £45.50.0
Special Damage or Repair Fee (if any) (per Sec. 23) £8.00.0
Travelling Expenses (if chargeable) £50.30.0
Second Surveyor's Fee (if any) £

Committee's Minute THU 9 APR 1953Character Assigned As now, slightly

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation

W11630-0148