

No. 110,584

OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office 14 AUG 1942)

Report 14 AUG 1942 When handed in at Local Office 14 AUG 1942 Port of -London-
 ey held at -London- Date. First Survey 8 Dec 1941 Last Survey 27th July 1942
 he Machinery of the Wood, Iron or Steel S/S LLANDILLO.

1966 Vessel built at Sunderland By whom Bartram & Sons When 1928 4
 2985 Engines made at Stockton By whom Black & Co. (1926) Ltd When 1928.
 1960 Boilers, when made (Main) 1928 (Donkey) 1928
 3513 Owners G. William Thomas SS Co Ltd Owners' Address
 Managers H. Radcliffe & Co. Port London Voyage
 1801 If Surveyed Afloat or in Dry Dock Book
 1201 (State name of Dock) Millwall D. D. and King Gas DK.

No. Port
 s of Examination and Repairs (if any) Damage & L.M.C.
 when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the
 of any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on
 the cause of which must be stated) should be separated from Repairs due to other causes; and
 the body of the report, should be briefly summarised at the end of the report. State also the
 of any letters respecting this case.
 where the Surveyor has not made a special damage report he is required to state whether he
 vices for this purpose, and why they were declined. Yes No required.
 port made by anyone else? If so, by whom? for Underwriters Surveyor
 rsonally go inside each Main Boiler separately and make a thorough examination at this time? Yes
 Donkey " " " "

state for what reasons
 the Boilers could not be thus thoroughly examined?
 means, in the absence of internal examination, were adopted by the
 himself of the thorough efficiency of those parts of each Boiler?
 internal examination of each boiler All main boilers 23rd March 1941 11.5 am '42. Present condition of funnel(s) good
 examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 1801
 examine the Safety Valves of Donkey Boiler? Jno To what pressure were they afterwards adjusted under steam? 1201
 examine all the manholes, doors and their fastenings of the Main Boilers? Yes , and of the Donkey Boilers? Yes
 examine the drain plugs of the Main Boilers? Yes , and of the Donkey Boilers? Yes
 examine all the mountings of the Main Boilers? Yes , and of the Donkey Boilers? Yes

now been drawn and examined? Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? NO
 changed? NO If so, state reasons
 fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? Good fit
 nation of Screw Shaft 8K Apr 1942 State the distance between lignum vita or bearing metal of stern bush and top of after bearing of screw shaft
 when referred to by numbers, should be counted from forward. Is electric light and/or power fitted YES.

you examine the generators, motors, switchgear, cables and fuses? YES.

resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? YES.

complete, state what arrangements have been made for its completion and what remains to be done
 states to have been caused by Enemy action on 23rd Dec 1940. Vessel sunk.
 was towed to Millwall Dry Dock.

Vessel placed in drydock, Examined propeller screw shaft (drawn in) and
 sea cocks valves and fastenings and all placed in order.
 Examined main engine cylinders, valve casings pistons, rods
 two valve spindles, valve gear, guide rods, top end pins and braces
 and bearings main bearings crank shaft journals, crank pins
 shaft, thrust blocks, Collars, intermediate shafting, engine soleplate and
 down bolts, and all placed in order. (Continued).

Observations, Opinion, and Recommendation:— The machinery of this vessel
 what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also
 eration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9/11, B&M.S. 9/11, *L.M.C. 9/11, or
 140 lb., F.D., &c.)

as now seen is in safe working condition and is eligible in my opinion to
 as now classed with fresh record of +L.M.C. 7-42, and TS. CL 4-42.

+L.M.C. £ 13.0.0 Fees applied for 14 AUG 1942
 Fee (if any) £ 42.0.0
 Section 29. ELECT. £ 2.2.7 Received by me, P. Weston
 (if chargeable) £ 2.2.7
 TUE. 8 SEP 1942 CERTIFICATE OF
 R. Weston, Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation
 W191-0016 1/2

Insert character of ship and machinery precisely as in the Register Book

Is a Certificate required if so, to be sent to

Examined Main Air, Circulating, Feed and bilge pumps.

Independent feed pumps. General service pump, circulating pump and engine, ballast pumps, one steering engine. Windlass, Fire hoses, electric machinery, also main and auxiliary condensers and all placed in order.

All boilers examined internally and externally with mountings and fastenings and all placed in order, and safety valves adjusted under steam.

Repairs Main Engines.

Lagging removed from cylinders and casings, pistons, rods, valves and spindles removed, cylinders cleaned internally, Scaler and paint externally and relagged. Any wind will now catch with wind will.

All piston rods found pitted, rods skinned, neck and gland bushes renewed.

All valve spindles found pitted, spindles skinned in way of packing and valve guides, neck and gland bushes renewed will feel gritty.

All valve gear dismantled pins honed as required and braces readjusted.

All gear guide plates removed water space cleaned, teeth rejoined.

Horn IP and shot remelted.

All top end pins honed and bushes bedded.

Crank shaft lists, main bearings cleaned, oil ways recut. Shaft bedded. Test to 600 ft/min in order.

Bottom end pins honed and bearing bedded.

All holding down bolts hammered and renewed as required.

Two thrust shoes found fractured, now renewed.

Water cooling spaces of other shoes cleaned.

Intermediate shafting. 110' length journals honed and bearing bedded.

Journals of other lengths found pitted, run skinned in lathe and bearings remelted, after flange of after length of intermediate shafting and screw shaft flange found pitted, both repair in lathe.

Stern tube hydraulically tested to 300 psi and rewooded.

Crank shaft, intermediate shafting and screw shaft examined for alignment.

One blade of 4 blades bronze propeller found fractured at tip, extending 8" end of fracture plugged.

Main and auxiliary condensers cleaned and hydraulically tested.

Air, circulating, feed and bilge pumps, and connections opened up cleaned and valves renewed as required.

Independent circulating pump damaged beyond repair complete new unit fitted.

Auxiliary condenser circulation pump damaged beyond repair new pump fitted.

Water end of independent feed pump fractured now renewed.

Ballast pump, General service pump and dry dock feed pump, steering engine, elevator, and dynamo aligned or pre-conditioned throughout.

Boilers Main.

All lagging removed. hydraulically tested 180 lbs/in²

one stay tube found defective in Ceres boiler 5" bore now renewed, and all lagging renewed.

lagging removed hydraulically tested to 120 lbs/in². combustion chamber guides and top stays found washed now renewed.

Shell plating slightly set up in way of all stays in my opinion this will.

Machinery examined throughout

Some repairs effected on
Account of enemy action
following firing.

17/4/42

17/4/42

"S.S. Llandaff" 2/2

- undated 10/4/42

Report spirit cans with pyrolyzed oil and paint removed
and general fittings repaired since most report and subsequent
insects attack with material seized prior to report treated, seized
wherever found, and scattered positions and insect free positions
sprayed, and sprayer tank cleaned and cleaned positions seized
and "mosquito" netting where found, and where in insect free areas
S/S Llandaff ~~inspected intact~~ ~~undated~~

not effect the efficiency of the boiler, boiler re-lagged, furnace gridded
Main and auxiliary steam piping, main and auxiliary feed piping and
10Kg boiler steam pipes, and 10Kg boiler feed pipes all cleaned, hydraulically,
tested to 360, 450, 240, and 300 lbs 2" respectively, none failed after 300
Few heating dismantled, cleaned, hydraulically tested to 360 lbs.
Brackets connecting heaters to bulkhead fair fractures, repaired by welding
fitting two steel angle brackets under lower bracket, using rivets and
main ingesta valve check joints tight, and renovation work done
On completion of repairs to the pumping arrangement remaining, and
and joints in order.

The main engines and all auxiliaries including steering gear and
air compressors were examined under working conditions, found
found satisfactory.

Electrical Installation. Dynamo inspected during running and under
full load conditions, and found satisfactory. Installation examined, and after
after re-wiring, was found satisfactory running and with main set
rotated at 1000 rev/min with a current reading 10A.
Current measured was correct showing that 10A. will pass through motor
operated and that in normal use, with some current into the motor
motor and generator connection to fixed side of supply side, although
that is correct and with some fault spots
connection leads indicate that permanent set will
the purpose of auxiliary generators and motors indicated, both main
motors, if no current from supply goes back to it will not
operate unless it has a "B" connection.

Both generators and motors examined and found
normal in usage conditions and mainly used as prime movers, but
also used as load and as prime movers.

Both main and auxiliary sets of generators and also
auxiliary sets of generators and auxiliary sets of generators
also used as load and as prime movers.

Both main and auxiliary sets of generators and also
auxiliary sets of generators and auxiliary sets of generators
also used as load and as prime movers.

Both main and auxiliary sets of generators and also
auxiliary sets of generators and auxiliary sets of generators
also used as load and as prime movers.

Both main and auxiliary sets of generators and also
auxiliary sets of generators and auxiliary sets of generators
also used as load and as prime movers.

Both main and auxiliary sets of generators and also
auxiliary sets of generators and auxiliary sets of generators
also used as load and as prime movers.

OT 91



Lloyd's Register
Foundation

2019