

REPORT of SURVEY for REPAIRS, &c.

Feb. 14th. 28.

Feb. 14th. 28.

Port of Hong Kong

Date of writing Report When handed in at Local Office

No. in Survey held at Hong Kong

Date, First Survey Aug. 11th. 27. Last Survey Feb. 11th. 1928.

Reg. Book. 36944 on the Wood, Iron or Steel Sc. 2 Twin Mts. "TJILBOET"

(No. of Visits 64)

Master

TONNAGE:-

Built at Rotterdam

By whom Maats. Fyenoord

When 1918

YEAR. 2

GROSS 5760

Owners Java-China-Japan Lijn

Port belonging to Batavia

MONTH.

UNDER D.K. 4877

Owners' Address

Surveyed Afloat or in Dry Dock? Dry Name of Dock Taikoo

When 1918

YEAR. 2

NET 3625

(if not already recorded in Appendix to Register Book).

Port belonging to Batavia

MONTH.

WB=Cell DBor DBa feet; uE&B feet; f feet; f feet; f feet; f tons.

total capacity tons. FPT tons; APT tons; MT tons.

Port belonging to Batavia

YEAR. 2

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, &c., and of the inner bottom plating, especially in the boiler space.

Last Report, No. 6233 Port Hong Kong

Port belonging to Batavia

YEAR. 2

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Port belonging to Batavia

YEAR. 2

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Damage Report made

Was a damage report made by anyone else? If so, by whom? No

REPAIRS, OR EXAMINATION AS PER RULE, FOR Reconstruction and Special Survey No. 3. (See also Report No. 6160 and continuation damage report attached.)

A new fore end has been constructed and both fore & aft ends joined together satisfactorily, as per plans enclosed.

Part of the material used in the reconstruction was salvaged from the old fore end and repaired as necessary, and all new material has been tested by the Surveyors to this Society (Steel makers

David Colville & Sons Ltd. Steel Co. of Scotland. Lanarkshire Steel Co.).

In the reconstruction of the vessel the scantlings shown on the original plans were followed, copies of which were obtained from the Owners, all shell & deck butts being the same as before.

All weather decks, double bottom & peak tanks and bulkheads have been tested as required by the

Rules & the workmanship is good.

Forging report for part stem enclosed.

(Continued on sheet No. 2)

| MARY OF DAMAGE REPAIRS:- | Plates. | Frames. | R. Frames. | Floors. | Beams. | Str. Plates. | Dk. Plates. | Other Items:- |
|---------------------------------|---------|---------|------------|---------|--------|--------------|-------------|---------------|
| Renewed | 172 | 126 | - | 126 | 35 | 48 | 42 | As per report |
| Removed and Fairied or Repaired | - | - | - | - | 185 | - | 104 | |
| Fairied or Repaired in place | - | - | - | - | - | - | - | |

SENT CONDITION OF THE

| Good | State if Tanks have been examined inside | Yes | Dblg. Plates under Sounding Pipes | Good | Copper, or Y.M. of Wood Vessels |
|------|--|------|-----------------------------------|-------|---------------------------------|
| " | State if Tanks now tested | Yes | Engine Room Skylights | " | (State if on Welt.) |
| " | Bulkheads | Good | Coal Bunkers, Open'gs, Lids, &c. | " | When put on, Month |
| " | Ceiling | " | Scuppers | " | Year |
| " | Cement or Asphalt (State which.) | " | Cargo Hatchways | " | Boats |
| " | Rudder | " | Hatches | " | Masts, Yards, &c. |
| " | Steering gear and its connections | " | Planking of Wood Vessels | - | Condition, how ascertained |
| " | Windlass | " | Caulking | ditto | Deck & aloft |
| " | Have Pumps now been examined and found efficient? | Yes | Trewnails | ditto | (State if wedges removed) |
| " | Have Sluice Valves now been examined and found efficient? | Yes | Breasthooks & Stemson | ditto | Yes |
| " | Have Watertight Doors now been examined and found efficient? | Yes | Transoms, Pointers, & Crutches | ditto | |
| " | Have Ventilators and their Coamings been examined and found efficient? | Yes | Timbers of Frame at openings | ditto | |
| " | | | Ditto ditto at other places | ditto | |
| " | | | Stringers, Clamps & Shelves | ditto | |
| " | | | Salting | ditto | |
| | | | | | |

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and pt ND 15, &c."

This vessel, having been satisfactorily reconstructed and all the requirements for Special Survey No. 3 having been complied with, is now in a good and efficient condition and eligible in my opinion to remain as classed with fresh record of survey 2,28. and the notation of ss H.Kg. No. 3-28. in the Register Book.

Instruction of new fore end \$3,500.00.
Fee (per Section 20) \$3,500.00.

Joining up fore & aft ends \$ 550.00.

Special Damage or Repair Fee (if any) (per Sec. 20) \$ 450.00.

Travelling Expenses (if chargeable) \$ 250.00.

18/12/27. Sunday fee \$ 20.00.

Second Surveyor's Fee (if any) \$

Fees applied for,
12/2/1928

Received by me,

27/2/1928

866

L. J. Morrison
Surveyor to Lloyd's Register of Shipping.

10m
are required no

To Certificate required P 11/20, to be sent to

W223-0140 (116)



© 2019

Lloyd's Register
Foundation

HULL OF S.S. "TJILEBOET"

Prior to undocking the sheer heights were taken from the base line to upper deck and are as follows:-

| Stem | 1/8 from Stem | Amidships. | 1/8 from Sternpost | Sternpost |
|--------|---------------|------------|--------------------|-----------|
| 38'-2" | 34'-6½" | 30'-2½" | 31'-4" | 33'-3½" |

Lowest point of sheer 39'-3", abaft amidships height 30'-0", Round of beam = 13½".

It was stated that the vessel would be remeasured for tonnage on arrival in Java and it has been requested that any alterations in the tonnages be forwarded.

As the vessel was undergoing such extensive repairs it was considered advisable to carry out Special Survey No. 3 at this time.

SPECIAL SURVEY No. 3.

Vessel placed in dry dock, bottom, rudder, keel, stem & stern frame cleaned, examined placed in good condition and recautched, Rudder lifted & gudgeons rebushed.

Holds, peaks, tween decks, bunkers and machinery spaces cleared.

All ceiling removed from tank tops in holds & bunkers, limber boards & sparring removed throughout and steel work exposed (including plating in way of sidelights and in way of ash shoot openings).

All oxidation removed throughout the vessel and steel work examined and placed in good condition.

There being no indication of wastage it was not considered necessary to drill the shell plating.

All double bottom, peak, deep tanks & oil fuel bunkers examined internally and tested under water pressure to rule requirements, floors sealed where necessary & all broken loose cement renewed.

Decks examined and drilled and gauged as necessary.

Chain cables ranged, chain locker examined and cables replaced.

Anchors, masts, spars, rigging, hatches (in position at the hatchway) steering gear and its connections, rods, chains, etc. rudder quadrant & tiller, windlass, pumps, sluice valves, water tight doors, air & sounding pipes and general equipment examined and placed in good condition.

Freeboard verified and cut in.

Doubling plates found or fitted under all sounding pipes.

Ventilators and their casings examined and placed in good condition.

Particulars of the new and old material used in the reconstruction of the vessel, from Bulkhead at Frame No. 95 to stem, are as follows:-

NOTE:- For repairs to aft end up to and including bulkhead at frame 95 see previous report.

NEW MATERIAL

STEM :- Lower part of stem renewed. (38 feet in length).

Keel/13 to stem renewed. (6 plates)

A/14 to stem renewed. Port & Starboard(16 plates)

B/10 to stem renewed Port & Starboard(14 plates)

C/9 to stem renewed Port & Starboard(14 plates)

D/12 to stem renewed Port & Starboard(12 plates)

Hong Kong

Continuation of Report No. 6246 dated Feb. 14th, 1928, on the

HULL OF S.S. "TJILDEBOET"

- E/13 to stem renewed Port & Starboard (16 plates)
 F/14 to stem renewed Port & Starboard (10 plates)
 G/13 to stem renewed Port & Starboard (14 plates)
 H/14 to stem renewed Port & Starboard (14 plates)
 J/15 to stem renewed Port & Starboard (12 plates)
 K/15 to stem renewed Port & Starboard (14 plates)
 Forecastle side plates renewed Port & Starboard. (8 plates)
 Forecastle sheer strake renewed Port & Starboard. (8 plates)
 3 bridge side plates renewed Port & Starboard. (6 plates)
 3 bridge sheer strake plates renewed Port & Starboard (6 plates)
 Forward wall bulwarks renewed Port & Starboard. (2 plates)
 Shell doublings at break of bridge & forecastle renewed.

FRAMES & FLOORS ETC.

- 126 frames & floors from frame No. 96 to stem renewed Port & Starboard.
 102 tank side brackets & their attaching angles from frame 96 to collision bulkhead renewed Port & Starboard.
 All intercostals & their angles in Nos. 1 & 2 D.B. Tanks renewed.
 Centre keelson & its attaching angles renewed from bulkhead 95 to stem.
 All tank top plating, margin plates & gussets of Nos. 1 & 2 D.B. tanks renewed from bulkhead 95 to collision bulkhead.
 One panting stringer each side renewed & all panting beams renewed.
 All lower hold pillars & ladders in Nos. 1 & 2 holds renewed.
 Fore peak tank top plating & wash plates, stiffeners, brackets, stringers and breasthooks renewed.

BULKHEADS. Bulkhead at frame No. 117 entirely renewed up to main deck, wing plates renewed between main and upper decks.

Bulkhead at frame No. 144 entirely renewed up to lower deck.

Bulkhead at frame No. 147 entirely renewed up to F.P. water tight flat, wing plates renewed above.

DECKS FORECASTLE 6 stringer plates renewed, 2 old deck plates crepped & part renewed, 52 beam knees renewed, port splicing plate renewed & all wood deck renewed.

BRIDGE DECK 6 stringer plates & 8 deck plates renewed, 46 beam knees renewed, & all wood deck renewed.

UPPER DECK 12 stringer plates & 9 deck plates renewed, 4 deck beams & 122 beam knees renewed, wood deck renewed in forward wall.

MAIN DECK 14 stringer & 23 deck plates renewed, 10 full length beams & 10 half beams renewed, 122 beam knees renewed.

OWER DECK (No. 1 HOLD). 10 stringer plates, 11 deck beams & 78 beam knees renewed.

EQUIPMENT 90 fathoms 2, 5/16" chain cable (anchor) renewed.

90 fathoms 1, 3/4" chain cable (mooring) renewed.

120 fathoms 5, 1/4" steel wire renewed.

90 fathoms 5" steel wire renewed.

2 lifeboat & 1 Captain's gig renewed.

Stores & tools renewed as per previous list.

(Continued on sheet No. 4)

© 2019



Hull's Register
Foundation

W223-0140 (376)

19 MAR 1928

9a.

of Hong Kong

Continuation of Report No. 6246 dated Feb. 14th. 1928. on the

HULL OF S.S. "TJILDEBOET"

GENERAL

Tank and bilge suction pipes forward of bulkhead No. 95 renewed.

Lower part of air, filling & sounding pipes forward of bulkhead No. 95 renewed.

All ceiling, limber boards & sparring in Nos. 1 & 2 holds, tween decks & chain locker renewed.

Rigging and stays to foremasts and samson posts renewed.

Windlass and winches repaired.

Seaman's quarters in forecastle rebuilt.

50% wood hatch covers renewed.

Hatch tarpaulins and canvas awnings renewed.

Electric wiring and lights renewed (old fittings used).

OLD MATERIAL SALVED & USED

Upper part of stem with mooring hawse pipe.

26 forecastle deck beams.

14 forecastle deck plates.

57 upper deck beams.

41 upper deck plates.

41 full & 10 half main deck beams.

23 main deck plates.

28 lower deck beams & 5 tie plates (No. 1 hold).

23 bridge deck beams.

21 bridge deck plates.

No. 1 hold upper & lower deck hatch coamings & shifting beams.

No. 2 hold upper & lower deck hatch coamings & shifting beams.

Fore and aft girders under forecastle, bridge, upper, main & lower decks & all tween deck pillars to same.

Bridge front plates, doors and stiffeners (except wing plates)

Tween deck bulkhead plates & stiffeners (except wing plates) on bulkhead at frame Nos. 117 & 147 from main to upper deck.

Part hold ladders & ladders to bridge & forecastle decks.

Cargo port doors & strongback backs.

Two coal shoots.

Deck houses and booby hatch on bridge deck.

Four W.C. troughs & part piping for same.

Part forecastle house casing & skylights on forecastle.

Steel silk room casing & doors in bridge space.

Part air & sounding pipes to tanks & bilges.

25 scuttle ports.

12 storm valves.

12 ventilator coamings, 15 ventilator cowls & 13 ventilator pipes.

Windlass, 2 hawse pipes with 2 shall & 1 deck flange & cable stoppers, 3 chain pipes.

All anchors & 180 fathoms chain cable.


Night winches & 24 foundation angles for same.

Forward masts, 2 samson posts, 8 derricks, & 2 derrick sockets.

(Continued on sheet No. 5)

W223-0140 (416)

© 2019



Lloyd's Register
Foundation

9a.

of Hong Kong

(5)

Continuation of Report No. 6246 dated Feb. 14th. 1928. on the

19 MAR 1928

HULL OF S.S. "TJILEBOET"

Six bollards, 13 fairleads, 2 wire reels, 4 davit sockets.

All deck steam & exhaust pipes & part pipe caging & chairs for same.

50% of wood hatches, 21 hatch battens & 11 hatch locking bars.

All hand rails and stanchions on forecastle & bridge decks.

All awning stanchions & part awning spars & ridge poles.

Starboard companion ladder.

20 bulb's eye electric fittings.

50 small iron deck fittings, such as eye plates, cleats etc.

REPAIRS:-Wear & Tear.

Rudder gudgeons rebushed and sundry minor repairs effected.

G. Morrison /



Hong Kong

19 MAR 1928

(2)

Continuation of Report No. 6246 dated Feb. 14th. 1928. on the

MACHINERY OF S.S. "TJILDEBOET"

While the after end of the vessel was anchored in Hong Kong Harbour waiting the construction of the new fore end, the centre boiler was used to supply steam to the dynamo and pumps and these machines were exhausting into the main condenser. Shortly after the vessel was placed at anchor, considerable leakage developed in the condenser tubes, although this condenser had been previously tested with cold water pressure and showed no leakage.

On withdrawing some of the leaky tubes the material of same was found perished and it was recommended that the remainder of the tubes be withdrawn for examination and on examination these tubes were also found to be in a more or less deteriorated condition and it was recommended that the condenser be retubed, which has now been done.

G. L. Morrison

P.S. Billebaet
6246

Report of the Surveyors
on the Survey of the
Coast of South America
from the Mouth of the
Magellan River to the
Cape Horn, and from thence
along the South American
Coast to the Pacific Ocean.
Part II.

Volume I.

Edited by J. C. R. Billebaet.

Published by the Government
of the Argentine Republic.

Printed at the Government
Press, Buenos Ayres, 1881.

Price, 100 Pesos.

Argentine Republic.

