

## REPORT OF SURVEY FOR REPAIRS, &amp;c.

Date of writing Report 10<sup>th</sup> April 1941 When handed in at Local Office 19 Port of Alexandria  
No. in Survey held at Alexandria Date, First Survey 24<sup>th</sup> March 41 Last Survey 25<sup>th</sup> March 1941  
Reg. Book. 73362 on the Wood, Iron or Steel Draco (No. of Visits 2)  
TONNAGE: Built at Aberdeen By whom Hall Russell & Co. Ltd. When 1922 YEAR. MONTH.  
GROSS 2018 Owners Ellerman's Wilson Line. Ltd. Owners' Address (if not already recorded in Appendix to Register Book).  
UNDER DK. 1565 Managers ✓ Port belonging to Hull  
NET 1177

Surveyed Afloat or in Dry Dock? Afloat Name of Dock ✓ Destined Voyage ✓  
Cell D B or D B a feet; u E & B feet; f feet  
total capacity tons. FPT tons; APT tons; MT feet tons.  
Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 2068 Port Ork

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (including date of N.B., if any).
+ 100 A.I. 12.38	+ L.M.C. 5.38.
S.S. Hull N°3 2.34	B.S. 5.40
S.S. Hull N°1 38.	T.S. 3.37 C.L.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined ✓

Society's Freeboard (if assigned) as painted on Ship and now verified ✓ ft. ins.

Was a damage report made by anyone else? If so, by whom? No.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage to shell plating, Star<sup>rd</sup> side, in way N°2 Hold  
alleged to have been sustained through cargo lighter (steel) colliding with the vessel  
whilst lying at anchor at Isbrourk on the 17<sup>th</sup> March 1941.

Wasted plating in Port tween deck bunker also now examined & repaired.

Collision damage found as follows:—

Star<sup>rd</sup> side shell plating

N°5 plate from for<sup>st</sup> 2<sup>nd</sup> stake below main sheer stake

badly indented in way of top landing approx 7" x 4"

As the vessel was urgently required for service it was recommended that slack rivets be  
caulked & hose tested & this has now been done

Deck plating in Port tween deck bunker space in way machinery casing, and electro welded

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

## PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights.	Copper, or Y.M. (State if on felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month. Year.
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Air Tight Doors been examined and found efficient?	Treenails	" length mean diam. (on board)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c.:— Consequent upon the

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

above Survey, this vessel is eligible in my opinion, to remain as classed  
without fresh record of survey subject to permanent repairs being carried out at  
the Owners convenience

Survey Fee (per Section 20) .....	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any)..... (per Sec. 20)	£	4	4 : 0	30 <sup>th</sup> March 1941
Travelling Expenses (if chargeable) .....	£		5 : 0	Received by me,
Second Surveyor's Fee (if any) .....	£			30 <sup>th</sup> March 1941

Committee's Minute

Character Assigned

FRI. 22 AUG 1941

As now  
Signed

Surveyor to Lloyd's Register of Shipping.



© 2021

Lloyd's Register  
Foundation

W26-0204



The above temporary repair now carried out to my satisfaction & permanent repair may be carried out at Owners convenience.

Damage to shell plating, 12" side, in way No. 3 tank  
to have been sustained through cargo tiebars (steel) colliding with the vessel  
lying at anchor at Hoboken on the 17<sup>th</sup> March 1941.  
It is noted that plating in fore turret that timber also was splintered & repaired.  
A further damage found as follows:  
12" side shell plating  
12" side from fore 3" - 12" side below main deck above  
to fair in place & ca  
about 12" in way.  
The vessel was originally repaired for service it was recommended that about 12" in  
to fair in place & ca  
about 12" in way.  
The vessel was originally repaired for service it was recommended that about 12" in  
to fair in place & ca  
about 12" in way.

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.			WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.			
	1st Bower ...													If Patent state name of Patentee.		
	2nd "															
	3rd "															
	Collective Weight.															
	Stream .....															
	Kedge.....															

## CHAIN CABLES.

[illegible]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.