

## REPORT OF SURVEY FOR REPAIRS, &amp;c., OF ENGINES AND BOILERS

(Received at London Office)

Date of writing Report... 19... When handed in at Local Office... 8... 11... 45 Port of NEWCASTLE-ON-TYNE  
 No. in Survey held at South Shields Date First Survey 1945 Last Survey 25-6-1945  
 Reg. Book. 20485 on the Machinery of the Wood, Iron or Steel S/S Botlea (No. of Visits...)

Tonnage { Gross 5119 Vessel built at Irvine By whom Ayrshire Dock Co Ltd When 1917 5  
 Net 3245 Engines made at Glasgow By whom Dunsmuir & Jackson Ltd When 1917  
 Nominal 510 Boilers, when made (Main) 1917 (Donkey) ✓  
 Horse Power 3 Owners Ministry of War Transport Owners' Address ✓  
 No. of Main Boilers 3 Managers Weidner, Hopkins & Co (if not already recorded in Appendix to Register Book.)  
 No. of Donkey Boilers ✓ Port London Voyage ✓  
 Steam Pressure 180 If Surveyed Afloat or in Dry Dock Afloat  
 in Main Boilers ✓ (State name of Dock.)  
 in Donkey Boilers ✓

Particulars of Classification which must be inserted precisely as in Register Book &amp; Supplements.

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years assigned now expired	Machinery and Boiler Surveys (including date of N.B., if any)
+100 A1 12,44		+LMC 12,41
S.S.C.T.N. 113-12,41		B.S. 4,44
		C.L. N4,43

Last Report No. 1043 Port Adm.Particulars of Examination and Repairs (if any) B.S. (part)

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? C & S. only.

Donkey " not, state for what reasons PB not prepared for survey What parts of the Boilers could not be thus thoroughly examined? ✓

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓  
 State latest date of internal examination of each boiler 25-6-45

Did the Surveyor examine the Safety Valves of the Main Boilers? No To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of the Donkey Boilers? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? yes and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓ and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? No and of the Donkey Boilers? ✓

Is the screw shaft now been drawn and examined? ✓ Has it a continuous liner? ✓ Is an approved oil retaining appliance fitted at the after end? ✓

Is the shaft now been changed? ✓ If so, state reasons ✓ Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓

Is an approved oil retaining appliance fitted at the after end? ✓ State date of examination of Screw Shaft ✓ State the wear down in the

tern bush ✓ Is electric light and/or power fitted? ✓ If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

Engine parts, when referred to by numbers, should be counted from forward.  
 If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

How done :- B.S. :- Starboard and centre boiler examined internally and externally, with manholes, doors and fastenings. Furnaces found distorted, and having a number of repaired fractures. Plain smoke tubes found to be thin. Recommended renewal of furnaces and plain tubes. Repairs deferred by M.O.W.T. owing to labour difficulties prevailing at the time.

General Observations, Opinion, and Recommendation:— This vessel has now been converted  
 (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11 \*LMC 9,11 or \*LMC 140 lb., FD, &c.)  
 to a hulk, to be loaded with gas shells, towed out to sea and sunk.

Fee (per Section 29) B.S. (part) £ 7 : 0 : 0 Fees applied for 9 NOV 1945

Damage or Repair Fee (if any) ✓ (per Section 29.)

Licence Base ✓ ng expenses (if chargeable) £ ✓

FRI. 30 NOV 1945

Committee's Minute

ed

Deferred

Received by me,

19

G. Booker

Engineer Surveyor to Lloyd's Register of Shipping.



© 2021

Lloyd's Register Foundation

W293-0104