

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office, NOV 11 1940)

Date of writing Report 8 - 11 - 1940 When handed in at Local Office 8 - 11 - 1940 Port of Leith.

No. in Survey held at Leith

Date, First Survey and Last Survey Nov 1st 1940

on the Machinery of the Wood, Iron or Steel Sc BAY FISHER.

Gross 545
Net 262

By whom J. Lewis & Sons Ltd.

When 1919 - 11

When 1919.

Vessel built at Aberdeen
Engines made at Aberdeen

By whom J. Lewis & Sons Ltd.

(Donkey) ✓

Boilers, when made (Main) 1919

Owners' Address (if not already recorded in Appendix to Register Book.)

Port Barron.

Voyage

Managers James Fisher & Sons Ltd.

Surveyed Afloat or in Dry Dock Edinburgh Dock.

(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey Date of last Survey and of Periodical Surveys.	Years assigned expired.	Machinery and Boiler Survey (including date of N.B., if any).
+100A1 8-40.		+LMC 12-37
SS Bw No 3-1-34.		BS 9-39.
SS Bw No 1-38.		TSCL 8-40.
Cargo battens not fitted.		

First Report No. 20160 Port Lth

Particulars of Examination and Repairs (if any) Part-B.S.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

as a damage report made by anyone else? If so, by whom? ✓

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

" " Donkey " " " "

this was not done, state for what reasons? ✓

what parts of the Boilers could not be thus thoroughly examined? ✓

to what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

the latest date of internal examination of each boiler 1/11/40

Present condition of funnel(s) Good

the Surveyor examine the Safety Valves of the Main Boiler? Yes

To what pressure were they afterwards adjusted under steam? Not adjusted

the Surveyor examine the Safety Valves of Donkey Boiler? ✓

To what pressure were they afterwards adjusted under steam? ✓

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes

, and of the Donkey Boilers? ✓

the Surveyor examine the drain plugs of the Main Boilers? ✓

, and of the Donkey Boilers? ✓

the Surveyor examine all the mountings of the Main Boilers? Yes

, and of the Donkey Boilers? ✓

screw shaft now been drawn and examined? No

Is it fitted with continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

s shaft now been changed? ✓ If so, state reasons ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

s the shaft now fitted been previously used? ✓

Has it a continuous liner? ✓

the date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft Afloat.

Is electric light and/or power fitted? ✓

Engine parts, when referred to by numbers, should be counted from forward.

so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

the Survey is not complete, state what arrangements have been made for its completion and what remains to be done To Complete the Survey the

Safety Valves remain to be adjusted. It is stated that this will be done at an early date.

Now done Main Boiler and its mountings examined internally and externally and found in order.

General Observations, Opinion, and Recommendation:— The Machinery of this Vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.&M.S. 9,11, & L.M.C. 9,11, or

*LMC 140 lb., F.D., &c.)

so far as now seen is in safe working condition and is eligible in my opinion to remain as classed with fresh record of survey BS 11-40 on completion.

Survey Fee (per Section 29) BS. £ 2 : 0 : 0

Fees applied for 8-11-1940

Special Damage or Repair Fee (if any) (per Section 29.) £

Received by me, 19

Travelling expenses (if chargeable) £

FRI. 15 NOV 1940

Committee's Minute

Assigned & Referred for Comp.

H.B. Murray

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

W338-2090