

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

OCT 17 1940

Date of writing Report 19 When handed in at Local Office 12. 10. 19 40 Port of Glasgow

No. in Survey held at Glasgow Date, First Survey and Last Survey 9. 10. 19 40
Reg. Book. 72389, on the Machinery of the Wood, Iron or Steel s.c. CLAN FRASER. (No. of Visits 1)

Tonnage { Gross 7529 Vessel built at Greenock By whom Greenock Dry Dock Ltd. When 1939 - 2
Net 3524 Engines made at Greenock By whom J. G. Kincaid & Co. Ltd. When 1939

Nominal Horse Power 1370 Boilers, when made (Main) 1939 (Donkey)

No. of Main Boilers 538.5 Owners The Clan Line Steamers Ltd Owners' Address (if not already recorded in Appendix to Register Book.)
No. of Donkey Boilers 220 Managers Gagger Irvine & Co. Ltd Port Glasgow Voyage
Steam Pressure in Main Boilers 220 If Surveyed Afloat or in Dry Dock Greenock Dry Dock
in Donkey Boilers

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey Date of last Survey and of Periodical Surveys.	Year surveyed now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+100A1 1-40 with fuelboard.		+LMC 2-39 CL.
Fitted for Oil Fuel 2,39 F.P. above 150°F		

Last Report No. Port
Particulars of Examination and Repairs (if any) Dry

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

" " Donkey " " " "

If this was not done, state for what reasons? Survey not due

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Did the Surveyor examine the Safety Valves of the Main Boiler?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used? Has it a continuous liner?

State date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward.

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

Now done:- Vessel placed in dry dock. Propeller end of stern tube and underwater fittings examined and found in order.

General Observations, Opinion, and Recommendation:- The machinery of this vessel so
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.&M.S. 9,11, L.M.C. 9,11, or L.M.C. 140 lb., F.D., &c.)
for as now seen is in efficient condition and eligible in my opinion to remain as classed without fresh record.

Survey Fee (per Section 29) £ ✓ : : Fees applied for 19
Special Damage or Repair Fee (if any) £ ✓ : : Received by me, 19
(per Section 29.)
Travelling expenses (if chargeable) £ ✓ : :

Committee's Minute GLASGOW 15 OCT 1940

Assigned As now

Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register

W374 200/45

Notes.
P.H.
21/10/60.



© 2020

Lloyd's Register
Foundation