





D.D. "GALAXIOS"Grounding Damage (continued)

Rudder lifted, all pintles and 4 bushes renewed

Steering chains repaired and tested

Eddy breaker on stemframe E.W. as required

Anchors & cables ranged & examined. Some slack  
studs put cable renewed.

Windlass examined.

Short crack at top of steel house pipe repaired  
by E.W.

Steel liege bul cracked at fore end.

W & T. Repair :- Doubling plate fitted to stem plate in 'C'  
strake steel side

S.R. Int :- Nothing done at this time to stem and stem  
plate which remains efficient

Condition Survey :- Examined weather decks and casings,  
hatches (part entered) vents, steering gear etc.  
examined.

IS 2 hold generally examined.

*J. J. Jones*

RETAIN