

F.E.

by Chief Ship Surveyor _____ Received from Chief Ship Surveyor _____

L'S NAME STEEL S.S. "HORNCHURCH" Rpt. Sunderland No. 27567

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 61 Depth "d" 17.75

Forming: Table No. 3 Description Bulb angle as approved.

Longitudinal No. 17080

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{135}{101}$

Bridge Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed \times 100 A1 (steel) as recommended.

1 Dk. (steel) Well Dk.

Cell DB 196' 472t. DTA 42' 153t. FPT 95t. APT 120t.

FK. 6BH pt.cem. Lloyds A.&CP P 23', Q 94', B 52', F 27'

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.

[Signature] 26.7.19

It is concluded that the Deep Tank left has been constructed in accordance with the plan approved, but the Surveyors should be requested to state if this is so.

W403-0160

HEADS, Poop Deck, Angle, Bulb Angle, Plate,	6	3	35	6	3	35	BRIDGE DECK STRINGER PLATE, OF 4 IN. G. THICKNESS						48
Top Bulb, or Channel							" Angle on ditto	5x5	46	5x5	46		
" Angles on upper edge							" Tie Plates						