

Date of writing Report.....<sup>24</sup><sub>3-1902</sub> When handed in at Local Office.....<sup>25</sup><sub>3-1902</sub> Port of.....  
No. in Survey held at South Shields. Date, First Survey 11<sup>th</sup> Feb. Last Survey 13<sup>th</sup> Feb 1902  
Reg. Book. (No. of Visits) 2.

No. in Reg. Book. 24894 Survey held at South Shields. Date, First Survey 11<sup>th</sup> Feb. Last Survey 13<sup>th</sup> Feb 1942  
(No. of Visits 2.)  
on the Wood, Iron or Steel "HARPAGON." (7 Feb. " 1 )

TONNAGE		Built at	By whom	YEAR	MONTH
No.	5719	Port Glasgow	Lithgow & Co.	1935	6
GROSS	5026	Owners	National S.S. Co. Ltd.	When	
Vessel	3378	Managers	J. & G. Harrison Ltd.	Owners' Address	
NET				(if not already recorded in Appendix to Register Book).	
Built		Port belonging to	London		
Surveyed Afloat or in Dry Dock?	On rock	Name of Dock	Middle D. Co. Ltd.	Destined Voyage	

ell DB or DBa	feet; uE&B	feet; f	feet	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)
total capacity	tons. FPT	tons; APT	tons; MT	

Only alterations in the existing records of tanks should be inserted.

CHARACTER	
-----------	--

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 110,216 Port Lon

Periodical Surveys, when held must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

not required

Was a damage report made by anyone else? If so, by whom? *Underwriter Surveyor*

PAIRS, OR EXAMINATION AS PER RULE, FOR DOCKING FOR GROUNDING. (See London Apb - Feb. 1942)  
Vessel stated to have grounded with the tides on the 3<sup>rd</sup> 4<sup>th</sup> + 5<sup>th</sup> Feb. 1942, whilst  
discharging alongside wharf in the River Thames.

How done: Vessel placed in drydock, bottom + rudder cleaned examined + recoated. Signs of contact were observed, but no damage to the shell plating due to the above grounding was found.

The following repairs + renewals to mooring ropes + wires are stated by the owner's sub. to have been carried out.

manilla ropes renewed - 1 @ 10" 3 @ 7" (all 90 fathoms)

spliced - 2 @ 7.

Win. ropes renewed - 2 @ 3" 1 @ 2 1/2" (all 90 lbs.) 1 @ 3" wire rope spliced. P.T.O.

MARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed . . . . .	/	/	/	/	/	/	/	See report for repairs & renewals to mooring ropes & wires.
Removed and Fair'd or Repaired . . . . .	/	/	/	/	/	/	/	
Fair'd or Remained in place . . . . .	/	/	/	/	/	/	/	

SENT CONDITION OF THE		SENT CONDITION OF THE	
Parts examined. good	Bulkheads	Parts examined. good	Engine Room Skylights
do.	Ceiling	do efficient	Coal Bunkers, Openings, Covers, &c.
ing of Decks	Cement or Asphalt		Oil Bunkers
do.	Rudder	good	Scuppers
ings	Steering gear and its connections	do.	Cargo Hatchways
do.	Windlass	do.	Hatches
a & Fastenings	Have pumps been examined and found efficient?		Planking
do.	Have Sluice Valves been examined and found efficient?		Caulking
Plating	Have Watertight Doors been examined and found efficient?	Yes	Treenails
efficient	Have Ventilators and their Coamings been examined and found efficient?	Yes	Breasthooks & Stemson
in way of sidelights	Air and Sounding Pipes		Transoms, Pointers & Crutches
Parts examined. effect.	Doubling Plates under Sounding Pipes		Timbers of Frame at openings
Frames			" " at other places
Longitudinals			Stringers, Clamps & Shelves
do.			Salting
verses			(State if examined)
ns			
ers			
Bottom Plating			
the Tanks been examined internally?			
the Tanks been tested?			

*General Observations, Opinion as to Class, Recommendation, &c.:*—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as classed in the Register Book *without fresh record of Survey*," "*to remain as classed and to have record of survey, 138*," or "*to remain as classed and to have record of survey, 138, and the notations of ss No. 1-38.*"

is vessel is eligible, in my opinion, to remain as classed, with docking date 2.42, subject  
indented plate 203 in 4<sup>th</sup> strake below shelter sheer (P.S.A.) being dealt with at Owner's convenience,  
permanent repairs at 1<sup>st</sup> cov. opp. (collision) to plating etc. (P.S.) in way of 2001 + 4 Holds + 1<sup>st</sup>  
indented tunnel plating etc.. Indented 207 plate from aft 1<sup>st</sup> + 2<sup>nd</sup> strakes below shelter sheer (P.S.)  
being dealt with at Owner's convenience.

Estimated fee £2.2.0.

Ling Expenses (if chargeable) ..... £  
**LICENCE CASE**  
 and Surveyor's Fee (if any), ..... £

Committee's Minute

Character Assigned

ERL 27 MAR 1942

100% Subject  
With freeboard  
Fitted for oil fuel

Fees applied for, 19.....  
Received by me, 19.....

(Great damage to ceiling, cargo battens + lower deck hatches to be dealt with at first opportunity).

Surveyor to Lloyd's Register of Shipping

Lloyd's Register  
Foundation

W43-0114



"HARPAGON."

No repairs have been carried out at this time to the ceiling, cargo batten, & lower deck hatches scared damaged by grab.

The owner's Supt. stated that these would be placed in order at a foreign port at first opportunity.

## Wear &amp; Tear Repairs.

about 22 keel rivets forward etc. welded + keel seams caulked where necessary.

about 24 odd shells nicely in side shell elec. welded.

\* 35 rivets renewed in P.T. bilge keels.

1 Rudder pin<sup>ts</sup> hardened up.

a few minor repairs effected.

The weather decks, casings, hatchways, ventilators, steering gear, windlass, masts, rigging, general equipment, engine room, tunnel & recesses, & Nos 4 & 5 Holds examined generally.

Per special Realous List - No repairs effected at this time to indented plate U.S. in 4<sup>th</sup> (not 3<sup>rd</sup>) strake below shelter sheet (P.S.A.); plating etc. (collision) (P.S.) in way of No. 1 & 4 holds; indented tunnel plating etc. Indented U.S. 7 plate from aft in the 1<sup>st</sup> & 2<sup>nd</sup> strakes below shelter sheet (P.S.). These items now examined, & found to remain efficient.

The welded rivets in No. 1 & 2. Keel plates now dealt with as reported above.  
It is submitted this record be now deleted from the S. R. List.

also the record "oxy docking"

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, Ex. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower ...														If Patent state name of Patentee.		
	2nd „																
	3rd „																
	Collective Weight. .																
	Stream .....																
	Kedge.....																

\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

## CHAIN CABLES.

[illegible]

s.s. Harpagon.

Eggs Report.

Lacking

Vessel placed in drydock, propeller and outside fastenings examined and found efficient. Wear Down,  $\frac{3}{16}$  <sup>ins.</sup> S. 11.0

E. Wilson