

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

FEB 11 1939

Date of writing Report 9 Feb 1939 When handed in at Local Office 10/2/39 Port of NEWCASTLE ON TYNE
 No. in Reg. Book 61182 Survey held at Blyth Date, First Survey 8 Feb Last Survey 9 Feb 1939 (No. of Visits 2)
 on the Machinery of the Wood, Iron or Steel Le 3rd PARCHILL (ex Glenaroh 38)
 Tonnage } Gross 500 Vessel built at Ardrossan By whom Ardrossan DD & SB Cold. When 1915 Month 5
 Net 190 Engines made at Glasgow By whom Mc Kie Baxter When 1915
 Nominal Horse Power 72R. Boilers, when made (Main) 1915 (Donkey)
 No. of Main Boilers 1 Owners M Taylor. Owners' Address _____
 No. of Donkey Boilers _____ Managers _____ Port Blyth Voyage _____
 Steam Pressure in Main Boilers 135 If Surveyed Afloat or in Dry Dock yes Blyth Dk & SB Cold Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 in Donkey Boilers _____

Last Report No. _____ Port _____ Compluss r
 Particulars of Examination and Repairs (if any) Docking.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? no

" " Donkey " " Boiler already exd (See Leith Rept. 1939)

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler Present condition of funnel good

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam? 135 lbs.

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? yes, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boilers?

Has screw shaft now been drawn and examined? no Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? yes 09.

Has shaft now been changed? If so, state reasons _____

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft not available

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete.


Now done. - Propeller outside fastenings of sea connections examined and found in good order.
 See SR Lists and Leith Rept. No. 1939. The two lower manholes of this boiler have now been satisfactorily built up and the doors refitted.
 Safety valves adjusted under steam to 135 lbs.

General Observations, Opinion, and Recommendation:— The machinery of this vessel is, in my opinion eligible to remain as classed and to have record of BS-12-38 as already recommended.

Survey Fee (per Section 29)..... £	Fees applied for
Special Damage or Repair Fee (if any)..... £	
Travelling expenses (if chargeable)..... £	
Received by me, £ 19	

John Findlay.
 Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute _____
 Assigned BS 12.38



Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to

No. due 11. 38. Completed

It is submitted that
this vessel is eligible for
THE RECORD.

No. 12. 38

June
28. 2. 39

The vessel was built at
 Glasgow in 1838 and is
 now employed in the
 service of the Admiralty
 as a transport vessel.
 She is now under the
 command of Captain
 [Name] and is
 employed in the
 service of the
 Admiralty.

Date	Particulars	Amount
1838
1839
1840
1841
1842
1843
1844
1845
1846
1847
1848
1849
1850
1851
1852
1853
1854
1855
1856
1857
1858
1859
1860
1861
1862
1863
1864
1865
1866
1867
1868
1869
1870
1871
1872
1873
1874
1875
1876
1877
1878
1879
1880
1881
1882
1883
1884
1885
1886
1887
1888
1889
1890
1891
1892
1893
1894
1895
1896
1897
1898
1899
1900

The vessel was built at Glasgow in 1838 and is now employed in the service of the Admiralty as a transport vessel.