

Report of Survey for Repairs, &c., of Engines and Boilers.

-1 MAR 1929

(Received at London Office)

Date of writing Report 19 When handed in at Local Office 23rd February 1929 Port of NEWCASTLE-ON-TYNENo. in Survey held at SOUTH SHIELDS Date, First Survey 20 Feb. Last Survey 22nd February 1929

eg. Book. 5549 on the Machinery of the Wood, Iron or Steel Sc. "KIRNWOOD" (No. of Visits 3)

Gross 3741 Vessel built at S. Shields By whom J. Readhead & Sons Ltd. When 1928-1

Net 2272 Engines made at S. Shields By whom J. Readhead & Sons Ltd When 1928

Nominal Horse Power 334 Boilers, when made (Main) 1928 (Donkey) 1928.

No. of Main Boilers 258 Owners Joseph Constantine Steamship Line Ltd Owners' Address

No. of Donkey Boilers 1 Managers (if not already recorded in Appendix to Register Book).

Steam Pressure in Main Boilers 200 lbs. Port MIDDLS BRO. Voyage

in Donkey Boilers 120 lbs. If Surveyed Afloat or in Dry Dock J. Readhead & Sons (State name of Dock.)

Last Report No. Port

Particulars of Examination and Repairs (if any) Docking & T.S.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Do. " Donkey " " " No.

If this was not done, state for what reasons? Boilers not due for Survey.

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?

Has screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? no

Has shaft now been changed? no If so, state reasons

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft? 8"

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done? Complete

Now done:- Vessel placed in dry dock. Examination made of Propeller, aft end of Stern bush and outside fastenings. Tail shaft drawn, examined & refitted. A New Bronze propeller was fitted. All now in good condition

General Observations, Opinion, and Recommendation:- The Machinery of this Vessel, as far as (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,11, B.&M.S. 9,11, or L.M.C. 9,11, 140 lb., F.D., &c.)

now seen, is in good condition and eligible in my opinion to remain as now classed, with fresh notation of Tail Shaft cl. seen 2.29

Survey Fee (per Section 29) £ : : Fees applied for 19

Special Damage or Repair Fee (if any) (per Section 28.) £ : : Received by me, 19

Travelling Expenses (if chargeable) £ : :

Committee's Minute FRI. 8 MAR 1929

Assigned as now

5 2.29

Joeking. New propeller fitted

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Scum shaft end

*It is submitted that
this vessel is eligible to
remain as CLASSED.*

S. 2.29

Hm

4.3.29

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation