

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 20 NOV 1933)

Date of writing Report 13<sup>th</sup> Nov. 1933 When handed in at Local Office 13<sup>th</sup> Nov. 1933 Port of Piraeus.

No. in Register Book 0401 Survey held at Piraeus. Date, First Survey 31<sup>st</sup> Oct Last Survey 3<sup>rd</sup> Nov. 1933  
(No. of Visits 3)

on the Machinery of the ~~Wood~~ Steel Se. AGAMEMNON

Gross 2190 Vessel built at Bridgeburg. By whom Canadian Allis Chalmers When 1919-9  
Net 1245 Engines made at -Do- By whom -Do- When 1919

Boilers, when made (Main) 1919 (Donkey)   
Owners Nuchalinos Maritime & Commercial Co. Ltd. Address Port Piraeus Voyage

Key Boilers 180 lbs Managers   
Boilers 180 lbs Surveyed Afloat  in Dry Dock N<sup>o</sup> 1 Dry Dock & Harbour, Pir.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Report No. \_\_\_\_\_ Port \_\_\_\_\_  
Particulars of Examination and Repairs (if any) T.S & B.S.

CHARACTER for Special Survey, Date of last Survey and of Periodical Surveys.	Year assigned and expired.	Machinery and Boiler Surveys (including date of N.B., if any)
<u>+100 R</u> <u>7.32</u> <u>P.S.P.R. N<sup>o</sup> 3 - 7.32</u>		<u>+LMC 7.32</u> <u>CL 7.32</u>

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and any details in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he has made his services for this purpose, and why they were declined

Has a special damage report made by anyone else? If so, by whom?

Has the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Donkey " " " "

When done, state for what reasons?

When parts of the Boilers could not be thus thoroughly examined?

Special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State the date of internal examination of each boiler Starb. 31-10-33, Port 1-11-33.

Did you examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 180 lbs sq"

Did you examine the Safety Valves of Donkey Boiler?  To what pressure were they afterwards adjusted under steam? \_\_\_\_\_

Did you examine all the manholes, doors and their fastenings of the Main Boilers? Yes and of the Donkey Boilers? \_\_\_\_\_

Did you examine the drain plugs of the Main Boilers? none fitted and of the Donkey Boiler? \_\_\_\_\_

Did you examine all the mountings of the Main Boilers? Yes and of the Donkey Boiler? \_\_\_\_\_

Has the Main Shaft been drawn and examined? Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? No

Has the Donkey Shaft been changed? No If so, state reasons \_\_\_\_\_

Has the Donkey Shaft been fitted been previously used?  Has it a continuous liner?  Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? Good fit lower half rewooded.

State the date of examination of Screw Shaft 1-11-33 State the distance between ligament vixæ or bearing metal of stern bush and top of after bearing of screw shaft \_\_\_\_\_

If the examination is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

Work Done:- Propeller, stern bush, and screw shaft, and fastenings connections examined and found in order.

Propeller key and two coupling bolts renewed.

BS (due 7.33) - P. & S. main boiler examined throughout, with their safety valves, mountings etc, and found in order. Safety valves adjusted under steam.

all plain tubes renewed.

Condenser tubes removed, cleaned and tested. Approx 35 tubes and Condenser satisfactorily tested on completion (Wear & Leak).

Observations, Opinion, and Recommendation:- This vessels machinery, so far as seen, is in good order and eligible in my opinion to be classed with fresh record of B.S. 11.33.

Propeller Shaft (C.L) seen 11.33.

per Section 29) BS & T.S. £10:19 0 Fees applied for 13/10 1933 WR

Age or Repair Fee (if any) £: 6:0

Expenses (if chargeable) £: 6:0 Received by me, 6.12.1933 WR

Signature of Engineer Surveyor Wm Rennie Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI. 1 DEC 1933

BS 11.33 FRI. 19 JAN 1934

CERTIFICATE WRITTEN.



© 2021

Lloyd's Register Foundation

Insert Character of Ship and Machinery precisely as in the Register Book.

Of due 733 held. Some boiler  
& condenser tubes renewed

It is submitted that  
this vessel is eligible for  
THE RECORD.

11-11-33  
S 11-33

29/11/33

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

*[Faint handwritten text, likely bleed-through from the reverse side of the page]*

1-11-33

1-11-33

120 B.2  
S.A. 02T  
S.S.V. 333  
S.S.V. 333

ADAMENADA 22



© 2021

Lloyd's Register  
Foundation

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.