

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Date of writing Report 10-6-31 When handed in at Local Office

Port of Rotterdam

No. in Reg. Book. Survey held at Rotterdam

Date, First Survey and Last Survey 15-6-1931

(No. of Visits 1)

on the Machinery of the ~~Wood Iron or Steel~~ S/S. "JOHANNA"

Gross 2076

Net 1143

Nominal Horse Power 106

No. of Main Boilers 2

No. of Donkey Boilers 1

Steam Pressure in Main Boilers 100 lb

in Donkey Boilers

Vessel built at ~~Alendrik~~ By whom ~~Johanna~~

When 1917 8.

Engines made at Rotterdam

By whom ~~Willems~~ When 1917

Boilers, when made (Main) 1917

(Donkey)

Owners N.V. My S/S. "JOHANNA"

Owners' Address Rotterdam

Managers N.V. Handels My Rotterdam

Port Rotterdam

Voyage Rotterdam

If Surveyed Afloat or in Dock

(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. No. for Special Survey. Date of last Survey and of Periodical Surveys.	Years and months expired.	Machinery and Boiler Surveys (including date of N.B., if any)
+100R1-5.30		+L17C 5.30
S.S. ROT. NO. 1-5.30		T.S. 5.30
		CL
CARGO BATTENS NOT FITTED.		

Last Report No. 20750 Port Rot

Particulars of Examination and Repairs (if any) Dam:

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

as a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " " "

this was not done, state for what reasons?

Did what parts of the Boilers could not be thus thoroughly examined?

So what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?

Is screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Is shaft now been changed? No If so, state reasons

Is the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 1/8

The Survey of the Boilers will be done after vessel's return of her present voyage. It is reported that the vessel's propeller touched the quay wall at La Rochelle on the 31st January 1931.

Screw shaft drawn afloat, same examined and found in order. Stern bush and fastenings examined and found in order.

One propeller blade found damaged on tip. Same of no consequence for the present, but will be renewed at the first convenient opportunity.

General Observations, Opinion, and Recommendation:— The Machinery being (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 11, B.&M.S. 11, & L.M.C. 11, 140 lb., &c.) as far as seen in a good condition. I am of opinion that this vessel is eligible to remain as classed and notation of T.S. seen 6-31

Survey Fee (per Section 29) £25.00 Fees applied for 226 1931
Special Damage or Repair Fee (if any) £ : :
(per Section 29.)
Travelling expenses (if chargeable) £3.00 Received by me, 19 FRI. 30 OCT 1931

Committee's Minute
Assigned Deferred for 10.31
Willems 10.31

Mr. Willems
Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation
W582-0027