

Rpt. 8.

(Received at London Office)

21 NOV 1928

WRECK BOY
No. 60 Top

No. 48629

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report,

When handed in at Local Office

12. 11. 1928 Port of Glasgow.

No. in Reg. Book.

Survey held at Glasgow.
80099 on the Wood, Iron or Steel S/s OlivaDate, First Survey 24th Oct (No. of Visits) 12Last Survey 6th Nov

1928

TONNAGE—
GROSS 5694
UNDER D.K. 5273
NET 3325

Built at Newcastle

By whom Swan, Hunter, Wigham Richardson Ltd. When 1916

YEAR.
7.Owners Anglo-Saxon Petroleum Co. Ltd. Owners' Address
(if not already recorded in Appendix to Register Book).

Managers

Port belonging to London

Surveyed Afloat or in Dry Dock? dry Name of Dock Glasgow

WB=Cell DB or DBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 93139 Port L.W.

Destined Voyage

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER, for Special Survey, Date of last Survey and of Periodical Surveys.	YEAR Assigned exclusively	Machinery and Boiler Surveys (including date of N.B., if any).
H100 H1 1928 5.5.24 N.2.24		G1 MC MS 3.24
Carrying Pet. in bulk, Filled for oil fuel		A.S. 1.28 C.C.
7-16 F.P. above 150°F		T.S. 8.25.

Society's Freeboard (if assigned) as painted on Ship and now verified | ft. ins.

Was a damage report made by anyone else? If so, by whom? Owner, M. Murray.

EXAMINATION AS PER RULE, FOR

Damage and condition.age, stated to have been caused through vessel stranding on an Head. Isle of Horan, on the 17th Sept 1928

Vessel placed in dry dock & examined, Bottom found hole & extensively damaged.

at 85 shell plates (including Keel plates), framing, Girders Bulkheads were affected.

Damage Report covering the above as far as can at present be attainable, has been prepared and can be obtained if required

DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—	P.T.O.
nd Fairied or Repaired									
repaired in place									
ATION OF THE									

State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
State if Tanks now tested	Engine Room Skylights	(State if on Felt). When put on, Month Year
Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	
Ceiling	Scuppers	
Cement or Asphalt (State which.)	Cargo Hatchways	
Rudder	Hatches	
Steering gear and its connections	Planking of Wood Vessels	
Windlasses	Caulking ditto	
Have Pumps now been examined and found sufficient?	Treenails ditto	
Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	
Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	
Have Ventilators and their Coamings been examined and found efficient?	Ditto ditto at other places ditto	
	Stringers, Clamps & Shelves ditto	
	Salting ditto	

Observations, Opinion as to Class, Recommendation, &c.:—

state clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon reclassification, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24 and pntD24, &c."

it has been decided that this vessel be broken up. This report is forwarded for the formation of the Committee

Fees applied for,
20 Nov 1928
1920 Nov 1928
19Received by me,
21/12/1928
John Macadam

Henry Gibbons

Surveyor to Lloyd's Register of Shipping

Committee's Minute GLASGOW 20 NOV 1928

TUE. 8 JAN 1929

Character Assigned Deferred

Lloyd's Register
Foundation

Glasgow

Continuation of Report No. 48629 dated 4. 11. 28 on the

Condition

ested by Owners Agent to examine cargo tanks for Special Survey, found same rust bound & recommended same to be scaled examination, but in view of apparent wastage, No. 8 cargo (oil) was locally examined (see below).

Superintendent in making out the Specification for Tear Repair has based same on this tank, a copy which is herewith attached.

one: No. 8 Main Oil Cargo Tank:- This tank (first examined) was -rust bound- and after chipping local parts of the internal were found same generally wasted. - Scuttings measured embodied on sketches forwarded.

- Drilled scuttings taken of shell @ No. 1.4-8 cargo tanks, the upper & main deck plating, transverse & centre line bulkheads etc. showing in way of all cargo tanks & trunk side plating in way inner tanks, and the material appears seriously riveted in places.

2.3.4.5.6.7 & 9 { all badly rust bound and appear cargo tanks same as No. 8.

Final recommendations made for these tanks.

Owing form:-

summers Tanks are also badly rust bound and wastage apparent (see drillings)

The following parts now examined:

Peak Tank:- Clear of damage - in good order, except tank 15th which is thin - 6 plates to renew.

Engine Room Locker:- In good order - 2 beams to repair.

Forward Deck Tank:- Clear of damage - in good order.

Fore Hold - In good order.

Forward Cofferdam:- Clear of damage - in good order.

Engine Room:- " " " in good order

Cofferdam:- In good order - cement on bottom broken

Engine Room Tank:- Clear of damage - in good order.

Engine Room Space:- In good order.

Port Side Bunkers:- In good order.

Engine Room D.B. Tank:- Clear of damage - several floors require reinforcing

Engine Room Space:- In good order.

Aft Peak Tank:- Top portion of Bulkhead Wash Bulkhead to be repaired with part new. Riveting in aft former to over haul. Soundings pipe to renew. Spaces above tank in good order.

The Pool Deck & Casings in way. - in good order

" Bridge " " " " " " "

The Cross Bunker Space:- not examined - filled with oil.

Nothing done to stem damage - see Lpl Rpt. which remains apparent.

Generally:- The internal structure of this vessel is very seriously deteriorated and the thicknesses as shown on sketches are as accurate as possible in view of the vessel not having been scaled.

The whole of the internal structure in way of the cargo tanks requires to be scaled & cleaned down before final recommendations can be made for repairs.

The internal scannings taken in W.8. Tank appear to represent the condition of the remaining cargo tanks and the owners have issued a specification asking for prices for the renewal of practically all the internal structure in these tanks.

At the request of the owners representative we have partially surveyed the vessel in an advisory capacity.

M.

We have been informed by Mr Gordon Owners representative that it has been decided to sell this vessel to be broken up.

Owners specification for repairs and two plans of scannings as taken from vessel forwarded herewith

HG
19-11-28.



W624-0028 (3/3)