

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

WED AUG 4 1920
NEWCASTLE-ON-TYNE

Date of writing Report 22nd May 1920 When handed in at Local Office 25 MAY 1920 Port of NEWCASTLE-ON-TYNE

No. in Survey held at Bent's Shields Date, First Survey 10th May Last Survey 20th May 1920

Boat on the Machinery of the Wood, Iron or Steel SS "WAR QUEBEC" Master Quebec SB Repairs Ltd

Age { Gross 2391 Net 1458 Vessel built at Quebec By whom Quebec SB Repairs Ltd When 1918 MONTH 6

Registered { Horse Power 322 Engines made at Lachine By whom Rominion Bridge Co Ltd When 1918

No. of Main Boilers 2 Boilers, when made (Main) 1918 (Donkey)

No. of Donkey Boilers 1 Owners Shipping Controller Port London Voyage

Steam Pressure 185 If Surveyed Afloat or in Dry Dock in Dry Dock Middle Dock Eng Co.

No. of Donkey Boilers 1 Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Years Assigned	Machinery and Boiler
For Special Survey.	Assigned	Surveyed
Date of last Survey and of Periodical Surveys.	expired	(including date of N.B., if any).
<u>+12A1</u>	<u>3-20</u>	<u>+Lmc 5'19</u>
<u>Sailed</u>		<u>WT Bldg</u>

Last Report No.

Port

Particulars of Examination and Repairs (if any) BS and T.S.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

Was this not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers?

and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers?

and of the Donkey Boiler?

Has screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes

Soldered joints

or is it without liners?

Has shaft now been changed? No If so, state reasons

Has the shaft now fitted new? No Has it a continuous liner?

or two liners?

or is it without liners?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Now done:- The main boilers and their mountings examined.

The propeller, sternbush, tail shafts + seaconnections + their fastenings examined.

The safety valves of the main boilers were adjusted to the above pressure.

Water tube boilers to be examined annually.

General Observations, Opinion, and Recommendation:- The machinery of this vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 2.11, B.S.M.S. 2.11, or L.M.C. 2.11, 14th Ed., &c.)

as far as seen is now in good order & safe working condition and eligible in my opinion to remain as classed and to have the notation BS 5-20 + TS 5-20, subject to the boilers being examined in 12 months, & the joints of tail shaft liner examined in 2 years.

Survey Fee (per Section 28) £ 1 10 0

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Fee applied for
7.8.19
Received by me,
13

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute

TUE. AUG. 17. 1920

CERTIFICATE WRITTEN 13. 10. 20

Assigned

as work subject

BS 5-20

Subject

FRI. JUL. 11 1921

W734 - 0006

Lloyd's Register
Foundation

BS due 5.20 Screw Shaft liner examination
due 6.20 now held

It is submitted that
this vessel is eligible for
THE RECORD. BS 5.20

S. 5.20

It is submitted that
this vessel is eligible to
remain as **CLASSED**,
Subject to the Water Tube Boilers
being surveyed annually, & the
joints of the Screw Shaft
liner being examined
before the end of
May 1922.

Rel
13/8/20

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation