

No. 69752

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office THU 29 MAR 1917)

Writing Report	March 20 th 1917	When handed in at Local Office	28 MAR 1917	Port of	NEWCASTLE ON TYNE
Survey held at Hebburn on Tyne on the Machinery of the Wood, Iron or Steel			Date, First Survey 22 nd Jan	Last Survey 8 th Mar	1917
Gross	9717	S/S "SAN ONOFRE"	(No. of Visits)		
Net	5964	Vessel built at Newcastle	CHARACTER		
red wer	790	By whom Armstrong Whitworth & Co Ltd When 1914 9	for Special Survey		
ain Boilers	483	Engines made at Newcastle	Date of last Survey and of Periodical Surveys		
key Boilers	-	Boilers, when made (Main) 1914 (Donkey)	Year Assumed now scraped		
ssure-	Boilers 220 ft	Owners Eagle Oil Transport Co Ltd Port London Voyage	Machinery and Boiler Surveys (including date of N.B., if any)		
key Boilers	-	If Surveyed at afloat in Dry Dock Palmers Dry Dock Hebburn			

Report No. Port

Particulars of Examination and Repairs (if any Damage)

All Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of damage (the cause of which must be stated) should be separated from Repairs due to other causes; and being detailed in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were not required? Was a damage report made by anyone else? If so, by whom? Mr. Dodds, underwriters Surveyor

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No.

- Donkey " " "
- Boilers " not due for survey.
- parts of the Boilers could not be thus thoroughly examined?
- special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?
- Surveyor examine the Safety Valves of the Main Boiler?
- To what pressure were they afterwards adjusted under steam?
- Surveyor examine the Safety Valves of Donkey Boiler?
- To what pressure were they afterwards adjusted under steam?
- Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?
- , and of the Donkey Boiler?
- Surveyor examine the drain plugs of the Main Boilers?
- , and of the Donkey Boiler?
- Surveyor examine all the mountings of the Main Boilers?
- , and of the Donkey Boiler?
- shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes or two liners? or is it without liners?
- now been changed? No If so, state reasons
- Is it now fitted new? Has it a continuous liner? or two liners? or is it without liners?

distance between lignum vitae of stern bush and top of after bearing of screw shaft? Stern bush rewooded. "working fit"

Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Damage stated to have been sustained through collision with "S.S. Manie" in the Bristol Channel on the 24th December, afterwards taking the ground.

Turned up Main Engines for examination "rig" cylinders, pistons, slide valves, m.r. shaft, thrust shaft & screw shaft examined. Main condenser main pumps, air, feed & bilge, Weir pumps, circulating pumps. Cargo pumps examined. All sea cocks & valves examined.

Steam steering engine. Starboard after capstan. Dynamo & Engine, Ballast pump, running engine

Screw shaft drawn in & examined (continuous liner) stern bush rewooded.


Main condenser tested a few tubes renewed P.T.O.

General Observations, Opinion, and Recommendation:— The machinery of this vessel so clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9/11, B&M.S. 9/11, or *E.M.C. 9/11, 140 lb., F.D., &c.)

as seen is in good order & safe working condition and in my opinion eligible to remain as classed in the Register Book. & have fresh record of S. 3.14

£ (per Section 28)	£	Fees applied for	28 MAR 1917
Damage or Repair Fee (if any) (per Section 28.)	£ 5.5.0	Received by me,	<i>John Thomas Brooks</i>
Expenses (if chargeable)	£ 5.5.0	573717	© 2020
Committee's Minute	TUE - 3 APR. 1917	815717	In a Certificate required? If so, to be sent to

ed
ed
ed now
(without st. cont'd)



Lloyd's Register
Foundation
W773-01322

Damage due to collision
Machinery examined & parts fitted

It is submitted that
this vessel is eligible to
remain as CLASSED without
Special restrictions.

J.W.
27/4/17
53.17

N.B.-If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to smudge the ink, or to cause it to show through to the other side.

Rpt. 9a.

Port of Newcastle on Tyne

Continuation of Report No. 6975 dated 20th March 1917 on the

s/s "SAN ONOFRE"

"Found" Air pump chamber patched. pump rod broken
new pump & rod fitted.

Feed pump rams broken & bent. new rams fitted -

Bilge pump rams bent & broken new rams fitted gland unmad

Pump levers strained & twisted & back gudgeon bent
levers fairied & new gudgeon fitted.

Pump links (front & back) renewed were broken & new brasses
fitted

Pump cross ^{had} bent & twisted. new one fitted.

Bracket for pump gudgeon bearing on engine column broken
patch cast & fitted on bearing unmad & brasses alto.

Feed & Bilge pump castings found free from defects

"Wearo" Pumps No 1 pump new piston rings fitted. group valves faced
up, two steam stop valves renewed & other minor repairs effected

No 2 pump. New piston rings fitted. New bucket & rod fitted
group valves faced up, also delivery valves. two stop valves & glands
renewed. minor repairs effected.

"Dynamo" cylinder bored out new piston & rings fitted

Alternator & Installation overhauled

Turning engine frame broken new ^{one} fitted. circulating pump engine
2 new piston rings fitted.

"Cargo Pumps" Forward pump room Port side cylinder broken new one
fitted. Starboard side pistons broken. 2 new ones fitted.

Starboard Captain engine. main bearing housing broken. Keys & half moon pins
ship new ones fitted

Metal in top half of the LT counter strap cracked. new metal
fitted. One main feed pipe & one auxiliary feed pipe broken
new ones fitted.

Cargo pipe line in tanks. found broken. branch bends. Valves
& stems. Renewed 5 Branches, 3 bends, 5 Valves &
6 stems.

numerous minor repairs effected in engine room.

The superintendent. Engineer had all boiler mountings opened
for examination. but did not request me to examine them.

J.W.

© 2020

Lloyd's Register
FW77301392