

No. 39591

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

FRI. 13 APR. 1917

(Received at London Office)

Report 12<sup>th</sup> Apr 1917 When handed in at Local Office 12<sup>th</sup> Apr 1917 Port of CARDIFF  
 Survey held at Cardiff Date, First Survey 27<sup>th</sup> Mar Last Survey 7<sup>th</sup> Apr 1917  
 in the Machinery of the Wood, Iron or Steel Twin S.A.M.V. Sebastian Master  
 SS 3110  
 1846 Vessel built at Dundee By whom Caledon S.B.C.L.P. When 1914 2  
 ✓ Engines made at Amsterdam By whom Werkspoor When +NE 6,16  
 ✓ Oilers Boilers, when made (Main) (Donkey) 1914  
 ✓ Boilers 2 Owners S.D. Motor Boat Co. Ltd (Lane & Macandrew) Port London Voyage  
 ✓ Reboilers If Surveyed Afloat or in Dry Dock Mount Stuart  
 ✓ Boilers 150 lbs (State name of Dock.)

Port No. Port

## Details of Examination and Repairs (if any) L.M.C.

Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on damage (the cause of which must be stated) should be separated from Repairs due to other causes; and being detailed in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were not accepted.

Was a damage report made by anyone else? If so, by whom?

You personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey "

Dry Blrs not due

No

not done, state for what reasons?

Parts of the Boilers could not be thus thoroughly examined?

Special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Not as yet at this time

Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

Shaft now been drawn and examined? No Is it fitted with continuous liner?

, or two liners? or is it without liners?

Shaft now been changed? If so, state reasons

Shaft now fitted new? Has it a continuous liner?

, or two liners?

, or is it without liners?

Distance between lignum vitæ of stern bush and top of after bearing of screw shaft?

No

Survey is not complete state what arrangements have been made for its completion and what remains to be done? Survey complete

here and when to Superintendence  
 done. Port Eng. The Nos 3 and 4 pistons, withdrawn from cylinders, the cylinders examined, gauged, and found good, the covers and valves examined, pistons replaced, with two new rings, the old rings having been broken, while taking them off pistons of 6 cylinder cover and valves, the Nos 1, 2 and 5 connecting rods their top ends, and brasses. The Nos 3 and 4 connecting rods, and their bottom end brasses. The Nos 3 and 4 crank pins, Nos 4 and 8 crank shaft journals, and main bearings. The two after collars of thrust shaft, their shoes, and both journals, and valve gears, these all examined and found good. Aboard Eng. The Nos 3 and 4 pistons, withdrawn from P.T.O.

General Observations, Opinion, and Recommendation:—The machinery of this vessel

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, R.S. 6,11, R.M.S. 6,11, or +L.M.C. 6,11, 140 lb., E.D., &c.

far as seen is in good condition, and eligible in my opinion to remain as classed and to have record of survey. +L.M.C. 4,17 and subject to the two air injection, and two floating fuel bottles being replaced at Owners convenience, as per Ams. Rpt. No. 6903.

Fee (per Section 28) £ 5 : 10 :

Total Damage or Repair Fee (if any) £ :

Fees applied for  
25 Apr 1917Fees applied for  
25 Apr 1917

Committee's Minute FRI. 20 APR. 1917

Signed + L.M.C. 4:17 Subject

Fees applied for

Received by me,

25 Apr 1917

W.4.17

FRI. 18 MAY. 1917

W.4.17

James Barclay  
Engineer Surveyor to Lloyd's Register of Shipping.

Is a Certificate required? If so, to be sent to

from cylinders, the cylinders examined, gauged and found good.  
the covers and valves examined, pistons replaced.

The No 1 cylinder cover and valves, the Nos 2 and 5 connecting rods, their top ends and brasses, the Nos 3 and 4 connecting rods and their bottom end brasses. The Nos 3 and 4 crank pins, the Nos 3 and 5 journals of crank shaft, and main bearings. The two after-collars of thrust shaft, their shoes and both journals, and valve gears, these all examined and found good.

Two large and four small air receivers cleaned internally  
examined and found good.

Air pipes from compressors cleaned internally

Two injection air bottles, tested by hydraulic pressure to 1100 lbs  
per square inch and found satisfactory

Pumps, compressors, and their coolers examined, and tried under working conditions

Two fuel pumps taken to works overhauled, and their rods  
which were slightly scored, ground true, refitted with new packing.  
The parts now opened, closed again, all corrections made as before  
and the engines manœuvred under working conditions.  
and found satisfactory

James Barclay