

intermdt. Bks. 9/2" and as approved.  
G. depth of girder .....  
depth and thickness of Floor Plate)

" Angles or Bulb Angles .....  
SIDE KEELSONS, Number .....  
Angles or Bulb Angles

Surveyors 17.10.17

Received from Chief Surveyors

NAME *Shells Landonia*

Report *Erk*

No. 17/84

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**


uses which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

When due

❖ 100 A-1 (Steel)  
1 DK (Steel) Well DK  
Cell D.B. 253 616E. F.P.T. 68E A.P.T. 129E.  
FK. Intermediate Bulkhead in fore hold dispensed  
with 4 B.H. only. Can. Lloyd cover.  
P 24 Q 80 B 55 F 29

*M*  
17.10.17

© 2020



Letter re. B.H. attached to report on sister vessel *Deister vessel*

Lloyd's Register  
Foundation

Angles on upper edge				Forecastle Deck Stringer Plate, b'dth & th'kns	29
Spacing	30	30		" Angle on ditto	3, 3
BEAMS, Forecastle Deck, Angles, Bulb Angles				" Tie Plates	

Vertical text on right margin: 29, 3, 5, 27, 45, 2, 4, 29, 3, 3