

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report 8th Dec. 1939When handed in at Local Office 8th Dec. 1939

(Received at London Office)

JAN 5 1940

No. in Reg. Book. Survey held at

Quebec, P.Q.

Date, First Survey 17th Nov. 1939Last Survey 17th Nov. 193925348 on the Machinery of the Wood, Iron or Steel *See "Geo."*Tonnage { Gross 4211
Net 2610

Vessel built at Sunderland

By whom J. L. Thompson & Sons Ltd.

Year. Month. When 1917-10

Nominal Horse Power { 365

Engines made at "

By whom J. Dickenson & Sons Ltd.

When 1917-

No. of Main Boilers 2

Boilers, when made (Main) 1917

(Donkey) ✓

No. of Donkey Boilers ✓

Owners C. Grolle Olsen & J. Hyung Olsen

Owners' Address

Steam Pressure in Main Boilers 180

Managers Frederic A. J.

Port St. John

Voyage

in Donkey Boilers ✓

If Surveyed Afloat or in Dry Dock Quebec Wharf

(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey Date of last Survey and of Periodical Surveys.	Year and Month last examined.	Machinery and Boiler Surveys (including date of N.B., if any).
+ 100 A. 1. 4. 39		+ A. 7. C.
1st Reg. N. 3-8-39		7. 4. 39
1st Reg. N. 1-37		2d 8-38
		2d N. 4-37 C.

Last Report No. 981 Port St. John

Particulars of Examination and Repairs (if any) St. John

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ✓

" " Donkey " " " " ✓

If this was not done, state for what reasons? ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler Port Boiler 17th Nov. 1939

Present condition of funnel(s) Good

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓

To what pressure were they afterwards adjusted under steam? Not adjusted

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓

To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓

, and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓

, and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? ✓

, and of the Donkey Boilers? ✓

Has screw shaft now been drawn and examined? ✓

Is it fitted with continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed? ✓ If so, state reasons ✓

Has the shaft now fitted been previously used? ✓

Has it a continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

State date of examination of Screw Shaft ✓

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft ✓

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted? ✓

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Port main boiler safety valves

to be adjusted under steam.

Now done i- Port main boiler with all mountings examined throughout and found in good condition.

General Observations, Opinion, and Recommendation:— This vessel's machinery is in good

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 0.11, B.&M.S. 0.11, & L.M.C. 0.11, or L.M.C. 140 lb., F.D., &c.)

Condition. Eligible in my opinion to remain as classed with the record of St. John with date on completion of the survey.

Survey Fee (per Section 29) £

\$1500

Fees applied for

Dec. 8. 1939

Special Damage or Repair Fee (if any) £

(per Section 29.)

Received by me,

19

Travelling expenses (if chargeable) £

Geo. Allan for Robt. W. Morton.
Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute

FRI 19 JAN 1940

WED 27 MAR 1940

Assigned

Deferred for

Comp. 185

Deferred

write R.W.

W483-0210

Lloyd's Register
Foundation