

This vessel was classed & appears by London report in 1834
and surveyed by me in 1847. 234 234
No. 234 Survey held at Whitby Date September 1843
on the brig Matchless Master John Smith
^{formerly} ₁₅₇₃ Tonnage ²³³ _{old} 217 new Built at Bridport When built 1810 London No. 62,
By whom built W G Barricks Whitby 60,
Port belonging to Whitby Destined Voyage Seaham & London
If Surveyed Afloat or in Dry Dock in dry dock of Messrs H & G B Classed. A. \
cut in two & lengthened 18 feet — flush deck Ship omitted

	Feet.	Inches.		Feet.	Inches.		Feet.	Inches.
Length aloft	82.3 + 6	Brake	88	3		Extreme Breadth	24	5
Breadth of Sternpost	91	-					22	2
Scantlings of Timber.						Thickness of Plank.		
Timber and Space	each	12@13				Outside.	inches.	
Floors	(avg 11 x 11)	sided	10@13	Moulded	11@11½	Keel to Bilge	2½	Foot Waling
1 st Foothooks	avg 9	"	10	"	9	Bilge Planks	5 of	Bilge Planks
2 nd Ditto	8@10	"	"	"	7½	Bilge to Wales	2½	Ceiling in Flat
3 rd Ditto	"	8	"	"	7	Wales	5 of	Ditto Bilge to Clamp
Top Timbers	"	7	"	"	4½	Topsides	1@3	Hold Beam Clamps
Deck Beams ... N°. of 22	9@8½	"	9@8½	6@5½		Sheer Strakes	1@3	52 stakes 233 inches of 3½
Hold Beams ... N°. of 13	9½@11	"	11	7½		Plank Sheers	3	Deck Beam Ditto
Keel	"	10	"	"	7	Water-Ways	10	Ceiling 'twixt Decks
Kelsons	"	12½	"	13½	16	Upper Deck	3	21 of 16 by 4
								Hold Beam Shelfs
								Deck Beam Ditto
								4
SIZE OF BOLTS IN FASTENINGS.								
all iron bolts under this repair except the Scarph of Keel								
Copper.								
Heel-Knee, and Dead Wood abaft								
Scarphs of Keel	N°. 8 C	3½		Bolts thro' the Bilge and Foot Waling	iron	3½	Hold Beam	7/8.
Floor Timber Bolts				Butt End Bolts	iron	11	Deck Beam	3½
Kelson ditto	iron 12, 1½	1½		Lower Pintle of the Rudder		2½		
Transoms and throats of Hooks	iron	1					same in Iron above the Copper	{
Arms of Hooks	do.	7/8						

Timbering.—The Space between the Floor Timbers and Lower Foothooks in this Vessel is 1@2 Inches. The Space between the Top-timbers is 4@5 Inches. The Stem, Stern Post, are composed of Eng^h oak ~~as~~ of the Transoms, Aprons, Knight Heads, Hawse Timbers, of Eng^h & African oak and are apply free from all defects.

The Floors and first Foothooks are composed of two floors new al=oak Timber.
The other Foothooks and Top Timbers of English oak
The Shifts of the first and second Foothooks are not less than 3"9 N. B. When less than prescribed by the Rule, state how many.
The rest of the Shifts of the Frame are sufficient
The Frame is fairly well squared from the first Foothook Heads upwards, and fairly free from sap, and from thence downwards, the frame is the same — the original frame is square

The alternate ~~Frames~~ are _____ bolted together. *N.B. If not, state how bolted. original frames*
The Butts of the Timbers are all ^{fairly} close together; their thickness not less than 1/4 to full of the entire moulding at that place.
The Frame is _____ chocked with no Butt at each end of the chock Some square on - some slope
Others more fitting ^{slope} Cross Shooles
The Main Kelson is composed of English and oak and the False Kelson of Am= oak
The Scarphs of the Kelsons are not less than 5 6 feet 7 inches.
The Deck and Hold Beams are composed of English & stettin and Am= oak

Planking Outside.—From the Keel to the first Foothook Heads the Plank is composed of *Amber-elm with some Engⁿ-oak ends*
From the first Foothook Heads to the Light Water Mark of *the elm now new*
From the Light Water Mark to the Wales of *the clus now new*
The Wales and Black-strokes are *of Wales all new Amⁿ-elm* The Topsides of *new Dantzic oak*
Black-strokes new Dantzic oak
The Sheer-strokes and Plank-sheers of *new Dantzic oak* The Water-ways of *pitch pine*
The Decks of *new yellow pine* State of *new*
The Shifts of the Planking are not less than 5 Feet — Inches. *general very good* N. B. If less than prescribed by the Rule, state whether general

Planking Inside.—The Limber-strokes are composed of Am-oak new the Bilge Planks of mixed oak new

The Ceiling, Lower Hold, of mixed oak Between Decks of oak & fir & pitch pine
Ships D. Oak Dantzic Clamps of hold and oak deck pitch pine

Fastenings.—To Hold Beams (double or two iron ledge knees upon a string between beams with a stinger over top) — the knees appear strong & good
Deck Beams 2-5 $\frac{1}{2}$ oak knees (lodging) at shelf also 1 $\frac{1}{4}$ iron hang knees fastened

Number of Breasthooks 5 Dug - sake Pointers apt Eng oak Crutches one iron
~~iron tension iron hooked - timber one across wood three also transom above trunk iron tension'd~~
Butts End Bolts are of iron in the Bottom, and one Bolt in each Butt End through and clenched.

Bilge and Footwaling iron bolted through and clenched.

General Quality of Workmanship *good*

General Quality of Workmanship

We certify that the preceding is a correct description of the above-named Vessel.

Builder's Name Henry & George Lawrence
Surveyor's Name Tho Jackson

Her Masts, Yards, &c. are in good condition, and sufficient in size and length. ^{2nd hand} other parts ^{2nd hand} new to this vessel and appear good

She has SAILS.

CABLES, &c.

ANCHORS, and their weights.

Dec.

N°.	Fathoms.	Inches.	N°.
2 Fore Sails,	180	Chain new.....	3 Bower, $\frac{1}{16}^{\circ}$ 3.20 wood stock
2 Fore Top Sails,	80	Hempen Stream Cable 30 cwt.	1 Stream, $\frac{1}{16}^{\circ}$ 2.2 iron stock
2 Fore Topmast Stay Sails,	60	Hawser 3/8	1 Kedge, 1.3.
2 Main Sails,	90	Towlines 5	
2 Main Top Sails,	90	Warp 15/2	

and one entire suit
of new sails others
enlarged & repaired
Her Standing and Running Rigging all

sufficient in size and new in quality. Except for shrouds
nearly new and some small ropes all appear very good

She has one Long Boat and one skiff good

The present state of the Windlass is good Capstan good and Rudder good
with Tyzacks purchased

2 new wood pumps

General Remarks—Statement and Date of Repairs. At this time after

having been ashore and sustained damage — Cut in two and lengthened 18 feet when the upper deck and waterways and the deck beams & fastenings with all the hold beams & their fastenings were taken out — the whole of the ceiling from end to end and from and including the deck beam clamps down to it, including the footwaling taken out so that every timber in the vessel was exposed to view and every visibly defective timber taken out & removed with either new or good sound second hand Eng^t oak as was also the space filled up with new & some good sound 2^d hand Eng^t oak timber — The planksheer sheer strakes topsides blackstrakes & wales all & entire stripped off and the ship heightened another course of timbers for this purpose all the upper top timbers were taken out & removed with Eng^t oak also new knight heads & oak & hawse timbers new Eng^t oak — All the planks off below the wales except some shorthoods — the keelson taken out — the breaststrakes all upset & transom knees all off — Then the defective timbers having been replaced the space filled up with new or good sound 2^d hand Eng^t oak with 2 new square floors (the 2^d hand oak timber & beams used in this repair is from 5^t to 15^t of 1^t book 1842 Thomas 288) — new forekeel of 4m — the former false keelson of Eng^t oak now made the mainkeel & made out in length at fore end with a piece of Bantue oak — the false keelson new Ant^t oak — two viz one new Eng^t oak & one 2^d hand Eng^t oak breaststrakes & the other hooks all new bolted also a ft of new Eng^t oak pointers shifting with the bole immediately below the bow port for loading the lower hole — The decked hold beams & clamps & stringers all new — the thick or spiriteking planks in twix deck & ceiling new Ant^t oak — the thinn twix ceiling is good fix from old decks with pitch pine & 3 or 4 good old Eng^t oak planks — the ceiling in the lower hold is all new except not more than 5 or 6 plank at each end of ship of good sound Eng^t oak taken off the outside — turner hold beams viz 2 new Ant^t oak & 8 from the above named big Thomas which are Baltic oak and appear sound & good — fastenings to hold beams good — 8 new Eng^t oak deck beams — others all appear sound and fastenings very good — Decks all new yellow pine — the waterways new pitch pine — the windlasses refit all all belonging to them appear very good — the coming & other appendages to deck all new the planksheer sheer strakes topsides blackstrakes & wales all new the planks from wales to keel all new except some shorthoods not removed viz on the larboard side ten strakes next — below the wales run out new to the stem & 3 strakes run out aft to the counter new — others gently run out to shift with shorthoods On the starboard side 5 strakes new also run out to the stem & 8 strakes next below the wales run out to counter new & others others shift with short hoods — the transom knees new bolted firmly in bottom sole first Ant^t oak & those above of Eng^t oak She has very hollow quarters and very much dead wood the planks on which with bolts have not been now disturbed —

If Sheathed, Doubled, Felted, or Coppered Single

When last done

I am of opinion this Vessel should be Clasped AEI I am also of opinion that if the owner had given timely notice that she should be surveyed for restoration she might have been restored to the first class now as long a period as the materials she is repaireed with will admit and that she do now deserve being in my opinion fit for the safe conveyance of any perishable goods anywhere The Amount of the Fee.....^{in my opinion} is received by me so far as it is prudent to do being unfastened

Special No fee yet

Tho Jackson

Committee's Minute 9th January 1841

Character assigned AII, 1st class & record by the

1843 1st class & record by the

London 4 Dec 1842 The above appears to be a correct description of the vessel as far as can now be seen by us and she is in good and efficient condition and may be clasped as recommended by Mr Jackson ^{© 2018} unless the materials used in the repair precludes

