

6 SEP 1898

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Date of writing Report	1 Sept	IS 98 When handed in at Local Office	2/9/1898	Port of Boston
No. in Reg. Book	Survey held at Boston		Date, First Survey Aug 17 th	Last Survey 31 Aug 1898
466	on the Machinery of the Wood, Iron or Steel蒸氣機器及機械 Master		(No. of Visits 5)	
Tonnage { Gross 99	Vessel built at St. Shields By whom 100t by 5t		YEAR. 1877.	MONTH. 6
Net 63	Engines made at Newcastle When 1877 Boilers, when made (Main) 1877 (Donkey) 96		When 1877.	
Registered Horse Power 25	Owners Boston London & Co	Port Boston Voyage London		
No. of Main Boilers 2	If Surveyed Afloat or in Dry Dock both Boston			
No. of Donkey Boilers 1	(State name of Dock.)			
Steam Pressure in Main Boilers 65				
in Donkey Boilers 50				

Last Survey No. Port

Particulars of Examination and Repairs (if any) 0.0 R. 2

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey "

CHARACTER for Special Survey. Date of last Survey and of Periodical Surveys.	Year Assigned or entered into Register Book.	Machinery and Boiler Surveys (including date of N.B., if any).
+ 90 A 1 6.96	L.M.C. 9.94	
SS 2. 3. 6. 90	B.S. 8. 97	
SS 2. 1. 94		

If this was not done, state for what reasons? Donkey Boiler too small

And what parts of the Boilers could not be thus thoroughly examined? Could see from door all over

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? Satisfied myself

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes At what pressure were they afterwards adjusted under steam? 55 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes To what pressure were they afterwards adjusted? 50 lbs

Has the propeller shaft been drawn and examined at this time? Yes If spare propeller shaft fitted, state whether new? Retired

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? Retired

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? —

The Main Boiler opened out and examined internally and externally, the Boiler shell at centre line at bottom much reduced in thickness from normal size to $\frac{1}{4}$ in at smallest near mudhole door. Owing to the Boiler being within one inch of keelson as a temporary repair to enable the vessel to run until the end of the year fitted plates $\frac{9}{16}$ thick about 3 inches wide and sufficiently long to get through the mudhole these are bolted to the shell the joint being double row of bolts with locking bolts here and there. A number of the stays are reduced as also the flange sides are corroded at line of the lugs. The Boiler tested by hydraulic pressure to 80 lb and found tight, and is now in my opinion safe. It is submitted that the Boiler be either removed or lifted astern and efficiently repaired in four months time from this date.

The Safety Valves and Boiler mountings unhandled. Examined under steam and the Safety Valves set to blow at 55 lbs per square inch.

The Donkey Boiler opened out and examined condition throughout good. The Safety Valves and Boiler mountings unhandled

General Observations, Opinion, and Recommendation:— The Boiler and Machinery of

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressure, &c.; thus, for example, B.S. 9.97, B.H.S. 9.97 or S.L.M.C. 9.97, 140 lb., F.D., &c.)

This vessel are now in my opinion in safe working condition eligible to remain as classed and be rated L.M.C. 8.98 in the Register Book. It is submitted that the Main Boiler be either removed astern and efficiently repaired or removed in four months time from this date.

Office or Registration Fee (per Sec. 27) £ 1 . . . Fees applied for

Survey Fee (per Section 28) Dis. 2. 10. 0 5/9/1898 B.R. 18. 9. 98

Special Damage Fee (per Section 28) Det. & 2. 5. - 11. R. 10. 9. 98

Travelling Expenses (if chargeable) Cyl. £ 18. 9 Received by me, 12. 9. 98

State if Certificate is required *None*

Committee's Minute *None* FRI. 9 SEP 1898

Assigned £ 18. 9. 98 subject

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Long shaft examined stern both round
Temporary repair effected to stern
Portion

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD L.H.C. & P.
to the main Bilge being
presently unbarred around
the end of Dec 9th
1898

© THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



Port of

Seattle

Continuation of Report No. 12050 dated 1 Sept 91 on the

Mamma Lizzie & Annie

Examined under steam and the Safety valve set to blow at 50 lbs per square inch.

The engine opened out and examined. Cylinders, Pistons & their valves good. Piston rods and Valve spindles turned up and reconditioned. Crank shaft good. New bottom end bearing fitted. Thrust relieved up. Propeller shaft main turned up in lathe and new stem bush fitted. Valve and pump gear adjusted. all pumps overhauled, Air rod and sea flanger turned up and relashed. Bilge plunger renewed. Valve renewed or readjusted as required. The condenser tube main cleaned replaced and reassembled. The sea connection ship side valve, suction cock and Bilge injection overhauled briefly by me overhauled and made good. The main steam pipe where seen good.

James Brown