

No. 2462

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

27 MAR 1893

Date of writing Report	March 23 <sup>rd</sup> 1893	When handed in at Local Office	Port of Hamburg
No. in Reg. Book.	Survey held at Hamburg		Date, First Survey March 20 <sup>th</sup> 1886 Last Survey March 21 <sup>st</sup> 1892
23	on the Machinery of the Wood, Iron or Steel		(No. of Trials)
Tonnage	Gross 1669	Net 1093	Vessel built at W. Hartlepool By whom W. Guy & Co.
Registered Horse Power	200	Engines made at W. Hartlepool When 1886	Boilers, when made (Main) 1886 (Donkey) 1886
No. of Main Boilers	2	Owners Albaum Transport, Garage to Lin/Port London	Voyage Albaum
Steam Pressure in Main Boilers	15 lbs	If Surveyed Afloat or in Dry Dock in dry dock	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
in Donkey Boiler	10 lbs	(State name of Dock.) Albaum's dry dock	CHARACTER For Special Survey, Date of last Survey and of Periodical Surveys.

Last Survey No. 1-90 Port Hdl.

Particulars of Examination and Repairs (if any) ~~See of damage up to~~

*(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)*

CHARACTER	Machinery and Boiler SURVEY
For Special Survey, Date of last Survey and of Periodical Surveys.	Years since last survey applied

M-1-90  
£ 100A17,92  
B, S, 7,92

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

The Vessel having broken her propeller in the ice, was fitted with a new propeller. Copy of damage Report will be found attached. I examined the propeller shaft and after a new coppering had been fitted and secured between the two liners, I found it in satisfactory condition.

The sea connections and their fastenings are examined in dry dock and found in good condition.

## General Observations, Opinion, and Recommendation:

*(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey; thus, for example, B.S. 0,02, B.M.S. 0,02 or L.M.C. 0,02, as the case may be.)*

I beg to recommend that the class of this Vessel be continued in the Register Book, without new entry with regard to machinery.

Office or Registration Fee (per Sec. 27) £ 1

Fees applied for

1893

Survey Fee (per Section 28) £ 1

1893

In 1893

Special Damage Fee (per Section 28) £ 2.00

5.00

Travelling Expenses (if chargeable) £ 1.00

Received by me,

\*State if Certificate is required

1893

Committee's Minute TUES. 28 MAR 1893

Assigned As now

Mr. Bowes

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Dr. Rieck

© 2018

Lloyd's Register  
Foundation

It is submitted that  
this vessel is eligible  
to remain AS CLASSED.

In account of damage sustained  
on countaining rice, a new  
hopper has been fitted  
+ the hatch slightly removed.  
M/S 27/3/193 -

5.3.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2018  
AF-SA16-86

Lloyd's Register  
Foundation